

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-75

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5c. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator AMOCO PRODUCTION COMPANY	8. Farm or Lease Name Selby
3. Address of Operator P. O. Box 68, Hobbs, NM 88240	9. Well No. 1
4. Location of Well UNIT LETTER <u>N</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>1</u> TOWNSHIP <u>20-S</u> RANGE <u>35-E</u> N.M.P.M.	10. Field and Pool, or Wildcat Wildcat Bone Springs
15. Elevation (Show whether DF, RT, GR, etc.) 3654.9' GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING CONS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>test additional Upper Bone Springs Pay</u> <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1105.

Propose to test additional Bone Springs pay as follows:

POH with tubing and packer. RIH with cast iron bridge plug and set at 9760'. Cap with 35' of class C neat cement and POH. RIH with 3-1/8" hollow carrier casing gun and perforate the interval 9644'-9662' w/4 JSPF. RIH w/1 joint of tailpipe, packer, by-pass valve, and 2-3/8" tubing to surface. Land tailpipe at 9550' and set packer. Swab test and evaluate productivity. Run Base GR/Temp survey from PBSD to 9300'. Acidize with 2000 gal of 15% NEFE HCL acid tagged with RA material. Open by-pass valve and displace tubing with acid. Close by-pass valve and pump acid. Flush acid to perfs with 1700 gal clean brine water. Run Base Gr/Temp survey from PBSD to 9300'. Swab to recover load and evaluate. Supplemental brief will follow.

O+5-NMOCD, H 1-J. R. Barnett, HOU Rm. 21.156 1-F. J. Nash, HOU Rm. 4.206 1-GCC 1-Superio, Mid 1-Superior, HOU

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Mary C. Clark TITLE Assist. Admin. Analyst DATE 4-27-84

APPROVED BY ORIGINAL SIGNED BY JERRY SEXTON TITLE DISTRICT SUPERVISOR DATE APR 27 1984

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

APR 27 1984

O.C.D.

HOBS OFFICE