

CONFIDENTIAL WELL

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-77

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.B.	
LAND OFFICE	
OPERATOR	

3a. Indicate Type of Lease
State ☐ Fee ☒
3. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT - 1 (FORM C-101) FOR SUCH PROPOSALS.

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER		7. Unit Agreement Name
2. Name of Operator AMOCO PRODUCTION COMPANY		8. Firm or Lease Name Selby
3. Address of Operator P. O. Box 68, Hobbs, NM 88240		9. Well No. 1
4. Location of Well UNIT LETTER N 660 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 1 TOWNSHIP 20-S RANGE 35-E N.M.P.M.		10. Field and Pool, or Wildcat Wildcat Bone Springs
15. Elevation (Show whether DF, RT, GR, etc.) 3654.9' GL		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☒	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to abandon the Lower Bone Springs and test the Upper Bone Springs as follows:

* Reference verbal approval from Eddie Seay, NMOC D 4-19-84 to G. C. Clark.
Release packer, POH with tubing and packer. RIH with cast iron bridge plug on wireline and set at 10,450'. Cap with 35' of class C neat cement. RIH with 3-1/8" hollow carrier casing gun and perforate the interval 9786'-9804' w/4 SPF. RIH with 1 joint 2-3/8" tailpipe, packer, by-pass valve, and 2-3/8" tubing to surface. Land tailpipe at 9700' and set packer. Swab test to evaluate. Run Base Gamma Ray/Temperature survey. Acidize with 1800 gals of 15% NEFE HCL acid tagged with RA material. Flush to perfs with 1700 gals of clean brine water. Run after job Gamma Ray Temperature survey. Swab and evaluate.

O+5-NMOC D, H 1-J. R. Barnett, HOU Rm. 21.156 1-F. J. Nash, HOU Rm. 4.206 1-GCC 1-Superior
Mid 1-Superior, HOU

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Mary C. Clark* TITLE Assist. Admin. Analyst DATE 4-23-84
APPROVED BY ORIGINAL SIGNED BY JERRY SEXTON DISTRICT 1 SUPERVISOR
CONDITIONS OF APPROVAL, IF ANY

APR 26 1984