State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

FILE IN TRIPLICATE	OIL CO	NSERVA	TION I	IVISION				
DISTRICT I P.O. Box 1980, Hobbs, NM 88240		2040 Pacheco St. Santa Fe, NM 87505			WELL API NO. 30-025-28973			
DISTRICT II					5. Indicate Type of Lease			
811 S. 1st Street, Artesia, NM 88210					FED STATE X FEE			
DISTRICT III					6. State Oil & G	as Lease No.		ł
1000 Rio Brazos Rd, Aztec, NM 87410					, , , , , , , , , , , , , , , , , , ,	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		7777
SUNDRY NOTICES AND REPORTS ON WELLS								
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101 FOR SUCH PROPOSALS.)					7. Lease Name or Unit Agreement Name SOUTH HOBBS (G/SA) UNIT			
1. Type of Well:								Ì
Oil Well X	Gas Well	Other			0.11.11.11	175		
2. Name of Operator					8. Well No.	175		
OCCIDENTAL PERMIAN LTD.					9. Pool name or Wildcat HOBBS (G/SA)			
3. Address of Operator 1017 W. Stanolind Rd., HOBBS, NM 88240 505/397-8200								
4. Well Location	DJ, 14141 602-40	200,23						
Unit Letter A : 101	0 Feet From The N	NORTH	Line and	820 Fee	t From The	EAST L	ine	
Section 6	Township	19S		Range 38E	NMPN	М	LEA County	
	10. Elevation (Show w		B, RT GR, etc	c.)				
<u>(////////////////////////////////////</u>	//////	Indicate Nat	ure of Not	ice, Report, or (Other Data	<i>,,,,,,,,,,,,,,,</i>		
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:								
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK						ALTERING CA	ASING	
TEMPORARILY ABANDON X CHANGE PLANS COMMENCE DRILLING OF					NS.	PLUG & ABA	NDONMENT	
PULL OR ALTER CASING	$\overline{}$		CASING T	EST AND CEMEN	NT JOB []			
OTHER:	_		OTHER:					
12. Describe Proposed or Completed Op	perations (Clearly state all pertir	nent details, and	l give pertine	ent dates, including	estimated date of s	tarting any propos	ed work)	
SEE RULE 1103.	,							
1 DIIDII DOH w/2-7/8" the	*** Only 16 its the in wel	11.						
 RUPU. POH w/2-7/8" tbg. *** Only 16 jts tbg in well. Move in and rack 2-7/8" workstring. 								
3. RIH w5.5" csg scraper to 3925'.								
4. Set 5.5" CIBP @3900'. TOP PERF @3958'.								
5. Circ csg w/pkr fluid.								
6. Test csg to 500 psi for 30 min and chart for the NMOCD.					1	ر 2		
						=	C.	
						-		
						14. 3. 3. 3. 3.	<u> </u>	
I hereby certify that the information abo	ove is true and complete to the b	est of my know	ledge and bel	ief.				
SIGNATURE To have	I Gilbert		TITLE	SR. ENGR. TE	СН	DATE	01/17/2002	
TYPE OR PRINT NAME ROBE	RT GILBERT				TEI	EPHONE NO.	505/397-8206)
(This space for State Use)						↑0aa		
APPROVED BY	COGN N.S	CARO DY	_ TITLE			JANE 2	4_2002_	
CONDITIONS OF APPROVAL IF AN	1 Y :	dikili Northera	STIVE B/9	TAFF HUNNAG	JE%			