

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER- 2. Name of Operator AMOCO PRODUCTION COMPANY 3. Address of Operator P. O. Box 68, Hobbs, NM 88240 4. Location of Well SL/BHL UNIT LETTER <u>F</u> <u>2540/2609</u> FEET FROM THE <u>North</u> LINE AND <u>1423/1342</u> FEET FROM THE <u>West</u> LINE, SECTION <u>5</u> TOWNSHIP <u>19-S</u> RANGE <u>38-E</u> NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) <u>3622.2' GR</u>	6. Indicate Type of Lease State ☐ Fee ☒ 7. Unit Agreement Name 8. Farm or Lease Name <u>South Hobbs (GSA) Unit</u> 9. Well No. <u>183</u> 10. Field and Pool, or Wildcat <u>Hobbs GSA</u> 12. County <u>Lea</u>
--	--

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER <u>Cement Squeeze</u> ☒	CASING TEST AND CEMENT JOB ☐	OTHER ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
Propose to cmt. squeeze zone I channel as follows:
POH with production equipment. Plugback from 4315' - 4155' with sand (~21.4' cap top of sand with 10' (~1.3 ft³ calseal). New PBTD should be 4145'. Perf 4100-4110' w/2 TJSPF. RIH and set pkr at 4000'. Establish injection rate into perfs and POH. RIH and set cmt. retainers at 4000'. Pump 50 sxs self stress I followed by 50 sxs class C w/4 lbs per sxs Truff-plug. Max squeeze pressure 1000 psi. Reverse out excess cmt, POH, and WOC. Drill out to 4120' and test to 1000 psi. Drill out to 4315' and circ. clean. RIH with production equipment and return well to production.
175 NMOC, H 1-JRB 1-FJN 1-GCC

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Gary C. Clark TITLE Asst. Admin. Analyst DATE 2-22-85

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____

TITLE _____

DATE FEB 22 1985

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

FEB 22 1985

**O.C.A.
HOSER OFFICE**