

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

**OIL CONSERVATION DIVISION**

**DISTRICT I**  
P.O. Box 1980, Hobbs NM 88241-1980

**DISTRICT II**  
P.O. Drawer DD, Artesia, NM 88210

**DISTRICT III**  
1000 Rio Brazos Rd., Aztec, NM 87410

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO.

30-025-29793

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL  
WELL ☒

GAS  
WELL ☐

OTHER

2. Name of Operator

Cross Timbers Operating Company

3. Address of Operator

3000 N. Garfield, Suite 175 Midland, Texas 79705

7. Lease Name or Unit Agreement Name

Cardinal

8. Well No.

1

9. Pool name or Wildcat

Wildcat (Glorieta)

4. Well Location

Unit Letter G : 2110 Feet From The N Line and 1650 Feet From The E Line

Section 27 Township 19S Range 38E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3587' GR

11.

**Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data**

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 7400', CIBP @ 6030' w/35' cement on top. Perfs 5540-5564' and 5903-5914'.  
Cross Timbers proposes to plug and abandon the well as follows:

Set CIBP @  $\pm$  5850' w/35' bailed cement cap or 25 sx/100' minimum spotted cement cap.  
Set CIBP @  $\pm$  5490' w/35' bailed cement cap or 25 sx/100' minimum spotted cement cap.  
Cut and pull any free 5-1/2" casing. Will spot cement plug across casing cut point.  
Circulate well w/salt gel mud. Spot 25 sx cement plug from 2910-1810'.  
Spot 25 sx cement plug from 1605-1505'.  
Spot 25 sx cement plug from 245-145'.  
Spot 10 sx surface plug.  
Install well marker upon completion of P&A.

**TAG PLUG**

**THE COMMISSION MUST BE NOTIFIED 24  
HOURS PRIOR TO THE BEGINNING OF  
PLUGGING OPERATIONS FOR THIS C-103  
TO BE APPROVED.**

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Janice Courtney*

TITLE Regulatory Tech

DATE 4/8/99

TYPE OR PRINT NAME

Janice Courtney

TELEPHONE NO. 915/682-8873

(This space for State Use)

ORIGINAL SIGNED BY

GARY WALK

FIELD OFFICIAL

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

JE

✓