to Appropriate District Office	Energy, Minerals and Natural Resources Department		Form C-103 ' Revised 1-1-89	
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088		WELL API NO.	
DISTRICT			30-025-31503	
P.O. Drawer DD, Arceila, NM 88210		5. Indicate Type of Lease	FEE X	
DISTRICT III 1000 Rio Brazos Rd., Azec, NM 87410			6. State Oil & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name	
I. Type of Well: OL WEL X WEL	OTH <b>ER</b>		NORTH MONUMENT G/SA UNIT BLK. 16	
2. Name of Operator			8. Well Na	
AMERADA HESS CORPORATION 3. Address of Operator			9. Pool same or Wildcat	
POST OFFICE DRAWER D, MONUMENT, NEW MEXICO 88265			EUNICE MONUMENT G/SA	
Unit Letter :7.	35_Feet From TheNORTH	Lipe and18	40 Feet From The WEST	Line
Section 32 Township 19S Range 37E NMPM LEA County				
10. Elevation (Show whether DF, RKB, RT, GR, etc.)				
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
		REMEDIAL WORK		a 🗌
	ABANDON CHANGE PLANS COMMENCE DRILLING			
		EMENT JOB		
OTHER: Amended report fr. original of 10/24 X. OTHER:				[
12. Describe Proposed or Completed Operations (Clearly state all persinent details, and give persinent dates, including estimated date of starting any proposed work). SEE RULE 1103.				
NMGSAU #1603				
Move in and rig up pulling unit. TOH with rods and pump. Nipple down wellhead. Nipple up BOP. TOH with tubing. TIH with a Sonic Hammer on tubing to TD. Rig up acid company. Acidize well with 5,000 gals. 15% NEFE DI HCL w/3% DP-77MX Micellar Solvent. TOH with Sonic Hammer. TIH with tubing and packer. Set packer at $\pm 3,700'$ . Swab/flow back load. TOH with tubing and packer, laying down production tubing. Pick up and TIH w/2 3/8" coated injection tubing with injection packer. Nipple down BOP. Nipple up injection wellhead assembly. Rig down and move out pulling unit. Clean and clear location.				
SIONATURE	y L. Harvey NAL SIGNED BY		Assistant DATE TELETIONE NO.	)3-94 393-2144
) A	SARY WINK IELD REP. II	u	NOV 1	4 1994
APPROVED BY	m		-	