i		
Submit 3 Copies Sta to Appropriate Energy Mineral	ate of New Mexico	
District Office	s and Natural Resources Department	Form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs NM 88241-1980 OIL CONS	ERVATION DIVISION	
DISTRICT #	2040 Pacheco St.	WELL API NO.
P.O. Drawer DD, Artesia, NM 88210	inta Fe, NM 87505	<u>30-025-33607</u>
DISTRICT III	1	5. Indicate Type of Lease STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410		6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPOR	RTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL O DIFFERENT RESERVOIR. USE "APPLIC, (FORM C=100) FOR SOULD SOL		7. Lease Name or Unit Agreement Name
(FORM C-101) FOR SUCH PRO	OPOSALS.)	McGrail State
	OTHER	-
2. Name of Operator		8. Well No.
Address of Operator		9. Weil No.
0. Box 2409, Hobbs NM 88240		9. Pool name or Wildcat
4. Well Location		Monument Abo
Unit Letter K: 1980 Feet From The	South Line and 165	0 Feet From The West Line
Section 26 Township	19-5 Range 36-E	Line West Line
Township	19-5 Range 36-E P. on (Show whether DF, RKB, RT, GR, etc.)	IMPM Lea County
	G 3691 VD. 2007	V/////////////////////////////////////
Check Appropriate Box t	o Indicate Nature of Notice	Report. or Other Data
NOTICE OF INTENTION TO	D: SUB	SEQUENT REPORT OF
	SUB:	SEQUENT REPORT OF:
		SEQUENT REPORT OF:
RFORM REMEDIAL WORK PLUG AND ABAI		
RFORM REMEDIAL WORK PLUG AND ABAI MPORARILY ABANDON CHANGE PLANS		PNS. PLUG AND ABANDONMENT
RFORM REMEDIAL WORK PLUG AND ABAI		PNS. PLUG AND ABANDONMENT
RFORM REMEDIAL WORK PLUG AND ABAN MPORARILY ABANDON CHANGE PLANS LL OR ALTER CASING HER: Install Rod Pumping Equipment	NDON REMEDIAL WORK COMMENCE DRILLING C CASING TEST AND CEM	SEQUENT REPORT OF:
RFORM REMEDIAL WORK PLUG AND ABAN MPORARILY ABANDON CHANGE PLANS LL OR ALTER CASING HER: Install Rod Pumping Equipment	NDON REMEDIAL WORK COMMENCE DRILLING C CASING TEST AND CEM	SEQUENT REPORT OF:
RFORM REMEDIAL WORK PLUG AND ABAN MPORARILY ABANDON CHANGE PLANS LL OR ALTER CASING HER: Install Rod Pumping Equipment . Describe Proposed or Completed Operations (Clearly state al work) SEE RULE 1103.	SUB: NDON REMEDIAL WORK S COMMENCE DRILLING C CASING TEST AND CEM OTHER: Il pertinent details, and give pertinent dates	SEQUENT REPORT OF:
RFORM REMEDIAL WORK PLUG AND ABAY MPORARILY ABANDON CHANGE PLANS LL OR ALTER CASING HER: Install Rod Pumping Equipment - Describe Proposed or Completed Operations (Clearly state alwork) SEE RULE 1103. MIRU pulling unit. K111 well. ND wellhead RIH, release pkr.	J: SUB: NDON REMEDIAL WORK S COMMENCE DRILLING C CASING TEST AND CEM CASING TEST AND CEM OTHER: Il pertinent details, and give pertinent dates d. NU BOP.	SEQUENT REPORT OF:
RFORM REMEDIAL WORK PLUG AND ABAN MPORARILY ABANDON CHANGE PLANS LL OR ALTER CASING Install Rod Pumping Equipment HER: Install Rod Pumping Equipment . Describe Proposed or Completed Operations (Clearly state alwork) SEE RULE 1103. MIRU pulling unit. K111 well. ND wellhead RIH, release pkr. POOH w/2 3/8" tubing. RIH with 2 7/8" production string.	J: SUB: NDON REMEDIAL WORK S COMMENCE DRILLING C CASING TEST AND CEM CASING TEST AND CEM OTHER: Il pertinent details, and give pertinent dates d. NU BOP.	SEQUENT REPORT OF:
RFORM REMEDIAL WORK PLUG AND ABAN MPORARILY ABANDON CHANGE PLANS LL OR ALTER CASING HER: Install Rod Pumping Equipment . Describe Proposed or Completed Operations (Clearly state al work) SEE RULE 1103. MIRU pulling unit. K111 well. ND wellhead RIH, release pkr. POOH w/2 3/8" tubing. RIH with 2 7/8" production string. SN at ND BOP. Set TAC. NU wellhead.	J: SUB: NDON REMEDIAL WORK S COMMENCE DRILLING C CASING TEST AND CEM CASING TEST AND CEM OTHER: Il pertinent details, and give pertinent dates d. NU BOP.	SEQUENT REPORT OF:
RFORM REMEDIAL WORK PLUG AND ABAN MPORARILY ABANDON CHANGE PLANS LL OR ALTER CASING CHANGE PLANS HER: Install Rod Pumping Equipment Describe Proposed or Completed Operations (Clearly state al work) SEE RULE 1103. MIRU pulling unit. K111 well. ND wellhead RIH, release pkr. POOH w/2 3/8" tubing. RIH with 2 7/8" production string. SN at ND BOP. Set TAC. NU wellhead. RIH with 7/8" rods. RIH with 7/8" rods.	J: SUB: NDON REMEDIAL WORK S COMMENCE DRILLING C CASING TEST AND CEM CASING TEST AND CEM OTHER: Il pertinent details, and give pertinent dates d. NU BOP.	SEQUENT REPORT OF:
RFORM REMEDIAL WORK PLUG AND ABAN MPORARILY ABANDON CHANGE PLANS LL OR ALTER CASING CHANGE PLANS HER: Install Rod Pumping Equipment Describe Proposed or Completed Operations (Clearly state al work) SEE RULE 1103. MIRU pulling unit. Kill well. ND wellhead RIH, release pkr. POOH w/2 3/8" tubing. RIH with 2 7/8" production string. SN at ND BOP. Set TAC. NU wellhead. RIH with 7/8" rods. RD pulling unit.	Y: SUB: NDON REMEDIAL WORK S COMMENCE DRILLING C CASING TEST AND CEM CASING TEST AND CEM OTHER: II pertinent details, and give pertinent dates d. NU BOP. t. 7465'.	ALTERING CASING
RFORM REMEDIAL WORK PLUG AND ABAN MPORARILY ABANDON CHANGE PLANS LL OR ALTER CASING CHANGE PLANS HER: Install Rod Pumping Equipment Describe Proposed or Completed Operations (Clearly state al work) SEE RULE 1103. MIRU pulling unit. K111 well. ND wellhead RIH, release pkr. POOH w/2 3/8" tubing. RIH with 2 7/8" production string. SN at ND BOP. Set TAC. NU wellhead. RIH with 7/8" rods. RIH with 7/8" rods.	Y: SUB: NDON REMEDIAL WORK S COMMENCE DRILLING C CASING TEST AND CEM CASING TEST AND CEM OTHER: II pertinent details, and give pertinent dates d. NU BOP. t. 7465'.	ALTERING CASING
RFORM REMEDIAL WORK PLUG AND ABAN MPORARILY ABANDON CHANGE PLANS LL OR ALTER CASING CHANGE PLANS HER: Install Rod Pumping Equipment Describe Proposed or Completed Operations (Clearly state al work) SEE RULE 1103. MIRU pulling unit. K111 well. ND wellhead RIH, release pkr. POOH w/2 3/8" tubing. RIH with 2 7/8" production string. SN at ND BOP. Set TAC. NU wellhead. RIH with 7/8" rods. RD pulling unit.	Y: SUB: NDON REMEDIAL WORK S COMMENCE DRILLING C CASING TEST AND CEM CASING TEST AND CEM OTHER: II pertinent details, and give pertinent dates d. NU BOP. t. 7465'.	ALTERING CASING
RFORM REMEDIAL WORK PLUG AND ABAN MPORARILY ABANDON CHANGE PLANS LL OR ALTER CASING CHANGE PLANS HER: Install Rod Pumping Equipment Describe Proposed or Completed Operations (Clearly state al work) SEE RULE 1103. MIRU pulling unit. K111 well. ND wellhead RIH, release pkr. POOH w/2 3/8" tubing. RIH with 2 7/8" production string. SN at ND BOP. Set TAC. NU wellhead. RIH with 7/8" rods. RD pulling unit.	Y: SUB: NDON REMEDIAL WORK S COMMENCE DRILLING C CASING TEST AND CEM CASING TEST AND CEM OTHER: II pertinent details, and give pertinent dates d. NU BOP. t. 7465'.	ALTERING CASING
RFORM REMEDIAL WORK PLUG AND ABAN MPORARILY ABANDON CHANGE PLANS LL OR ALTER CASING CHANGE PLANS HER: Install Rod Pumping Equipment Describe Proposed or Completed Operations (Clearly state al work) SEE RULE 1103. MIRU pulling unit. K111 well. ND wellhead RIH, release pkr. POOH w/2 3/8" tubing. RIH with 2 7/8" production string. SN at ND BOP. Set TAC. NU wellhead. RIH with 7/8" rods. RD pulling unit.	Y: SUB: NDON REMEDIAL WORK S COMMENCE DRILLING C CASING TEST AND CEM CASING TEST AND CEM OTHER: II pertinent details, and give pertinent dates d. NU BOP. t. 7465'.	ALTERING CASING
RFORM REMEDIAL WORK PLUG AND ABAN MPORARILY ABANDON CHANGE PLANS LL OR ALTER CASING HER: Install Rod Pumping Equipment. . Describe Proposed or Completed Operations (Clearly state al work) SEE RULE 1103. MIRU pulling unit. K111 well. ND wellhead RIH, release pkr. POOH w/2 3/8" tubing. RIH with 2 7/8" production string. SN at ND BOP. Set TAC. NU wellhead. RIH with 7/8" rods. RD pulling unit. Connect surface equipment and start well	Y: SUB: NDON REMEDIAL WORK COMMENCE DRILLING C CASING TEST AND CEM CASING TEST AND CEM OTHER: II pertinent details, and give pertinent dates d. NU BOP. t 7465'. TAC at 7375'.	ALTERING CASING
RFORM REMEDIAL WORK PLUG AND ABAN MPORARILY ABANDON CHANGE PLANS LL OR ALTER CASING CHANGE PLANS HER: Install Rod Pumping Equipment . Describe Proposed or Completed Operations (Clearly state alwork) SEE RULE 1103. MIRU pulling unit. K111 well. ND wellhead RIH, release pkr. POOH w/2 3/8" tubing. RIH with 2 7/8" production string. SN at ND BOP. Set TAC. NU wellhead. RIH with 7/8" rods. RD pulling unit. Connect surface equipment and start well Connect surface equipment and start well	Y: SUB: NDON REMEDIAL WORK COMMENCE DRILLING C CASING TEST AND CEM CASING TEST AND CEM OTHER: II pertinent details, and give pertinent dates d. NU BOP. t. 7465'. TAC at 7375'. pumping to production facilit: of my knowledge and belief.	ALTERING CASING
RFORM REMEDIAL WORK PLUG AND ABAN MPORARILY ABANDON CHANGE PLANS LL OR ALTER CASING CHANGE PLANS HER: Install Rod Pumping Equipment . Describe Proposed or Completed Operations (Clearly state al work) SEE RULE 1103. MIRU pulling unit. K111 well. ND wellhead RIH, release pkr. POOH w/2 3/8" tubing. RIH with 2 7/8" production string. SN at ND BOP. Set TAC. NU wellhead. RIH with 7/8" rods. RD pulling unit. Connect surface equipment and start well reby certify that the information above is true and complete to the best o VATURE MATURE	Y: SUB: NDON REMEDIAL WORK COMMENCE DRILLING C CASING TEST AND CEM CASING TEST AND CEM OTHER: II pertinent details, and give pertinent dates d. NU BOP. t 7465'. TAC at 7375'.	SEQUENT REPORT OF:
RFORM REMEDIAL WORK PLUG AND ABAN MPORARILY ABANDON CHANGE PLANS LL OR ALTER CASING CHANGE PLANS HER: Install Rod Pumping Equipment . Describe Proposed or Completed Operations (Clearly state alwork) SEE RULE 1103. MIRU pulling unit. K111 well. ND wellhead RIH, release pkr. POOH w/2 3/8" tubing. RIH with 2 7/8" production string. SN at ND BOP. Set TAC. NU wellhead. RIH with 7/8" rods. RD pulling unit. Connect surface equipment and start well Connect surface equipment and start well	Y: SUB: NDON REMEDIAL WORK COMMENCE DRILLING C CASING TEST AND CEM CASING TEST AND CEM OTHER: II pertinent details, and give pertinent dates d. NU BOP. t. 7465'. TAC at 7375'. pumping to production facilit: of my knowledge and belief.	SEQUENT REPORT OF:
RFORM REMEDIAL WORK PLUG AND ABAN MPORARILY ABANDON CHANGE PLANS LL OR ALTER CASING CHANGE PLANS HER: Install Rod Pumping Equipment Describe Proposed or Completed Operations (Clearly state alwork) SEE RULE 1103. MIRU pulling unit. K111 well. ND wellhead RIH, release pkr. POOH w/2 3/8" tubing. RIH with 2 7/8" production string. SN at ND BOP. Set TAC. NU wellhead. RIH with 7/8" rods. RD pulling unit. Connect surface equipment and start well Connect surface equipment and start well reby certify that the information above is true and complete to the best o VATURE Generation NAME Kelly Cook S space for State Use) Space for State Use)	J: SUB: NDON REMEDIAL WORK COMMENCE DRILLING C CASING TEST AND CEM CASING TEST AND CEM OTHER: II pertinent details, and give pertinent dates d. NU BOP. t 7465'. TAC at 7375'. pumping to production facilit: of my knowledge and belief.	SEQUENT REPORT OF:
RFORM REMEDIAL WORK PLUG AND ABAN MPORARILY ABANDON CHANGE PLANS LL OR ALTER CASING CHANGE PLANS HER: Install Rod Pumping Equipment • Describe Proposed or Completed Operations (Clearly state al work) SEE RULE 1103. MIRU pulling unit. K111 well. ND wellhead RIH, release pkr. POOH w/2 3/8" tubing. RIH with 2 7/8" production string. SN at ND BOP. Set TAC. NU wellhead. RIH with 7/8" rods. RD pulling unit. Connect surface equipment and start well Image: Start well the start well reby certify that the information above is true and complete to the best or Image: Start well the start well reby certify that the information above is true and complete to the best or Image: Start well ORIGINAL SIGNED BY CHBIS WIL ORIGINAL SIGNED BY CHBIS WIL	7: SUB: NDON REMEDIAL WORK COMMENCE DRILLING C CASING TEST AND CEM CASING TEST AND CEM OTHER: II pertinent details, and give pertinent dates d. NU BOP. t. 7465'. TAC at 7375'. pumping to production facilit: If my knowledge and belief.	SEQUENT REPORT OF:
RFORM REMEDIAL WORK PLUG AND ABAN MPORARILY ABANDON CHANGE PLANS LL OR ALTER CASING CHANGE PLANS HER: Install Rod Pumping Equipment Describe Proposed or Completed Operations (Clearly state al work) SEE RULE 1103. MIRU pulling unit. K111 well. ND wellhead RIH, release pkr. POOH w/2 3/8" tubing. RIH with 2 7/8" production string. SN at ND BOP. Set TAC. NU wellhead. RIH with 7/8" rods. RD pulling unit. Connect surface equipment and start well reby certify that the information above is true and complete to the best o VATURE ACTURE MERU PRINT NAME Kelly Cook	7: SUB: NDON REMEDIAL WORK COMMENCE DRILLING C CASING TEST AND CEM CASING TEST AND CEM OTHER: II pertinent details, and give pertinent dates d. NU BOP. t. 7465'. TAC at 7375'. pumping to production facilit: If my knowledge and belief.	SEQUENT REPORT OF:
RFORM REMEDIAL WORK PLUG AND ABAN MPORARILY ABANDON CHANGE PLANS LL OR ALTER CASING CHANGE PLANS HER: Install Rod Pumping Equipment . Describe Proposed or Completed Operations (Clearly state al work) SEE RULE 1103. MIRU pulling unit. K111 well. ND wellhead RIH, release pkr. POOH w/2 3/8" tubing. RIH with 2 7/8" production string. SN at ND BOP. Set TAC. NU wellhead. RIH with 7/8" rods. RD pulling unit. Connect surface equipment and start well worky certify that the information above is true and complete to the best o NATURE MIRU DUMAL GOR PRENT NAME Kelly Cook Space for State Use) ORIGINAL SIGNED BY CHRIS WILL	7: SUB: NDON REMEDIAL WORK COMMENCE DRILLING C CASING TEST AND CEM CASING TEST AND CEM OTHER: II pertinent details, and give pertinent dates d. NU BOP. t. 7465'. TAC at 7375'. pumping to production facilit: If my knowledge and belief.	SEQUENT REPORT OF:
RFORM REMEDIAL WORK PLUG AND ABAN MPORARILY ABANDON CHANGE PLANS LL OR ALTER CASING CHANGE PLANS HER: Install Rod Pumping Equipment. . Describe Proposed or Completed Operations (Clearly state alwork) SEE RULE 1103. MIRU pulling unit. K111 well. ND wellhead. RIH, release pkr. POOH w/2 3/8" tubing. RIH with 2 7/8" production string. SN at ND BOP. Set TAC. NU wellhead. RIH with 7/8" rods. RD pulling unit. Connect surface equipment and start well Connect surface equipment and start well reby certify that the information above is true and complete to the best o VATURE MIRU Cook s space for State Use) ORIGINAL SIGNED BY CHRIS WILL DISTRUCT I SUPERVISOR	Y: SUB: NDON REMEDIAL WORK COMMENCE DRILLING C CASING TEST AND CEM CASING TEST AND CEM OTHER: II pertinent details, and give pertinent dates d. NU BOP. t 7465'. TAC at 7375'. pumping to production facilit: of my knowledge and belief.	SEQUENT REPORT OF: ALTERING CASING



÷