

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

**OIL CONSERVATION DIVISION**

**DISTRICT I**  
P.O. Box 1980, Hobbs NM 88241-1980

**DISTRICT II**  
P.O. Drawer DD, Artesia, NM 88210

**DISTRICT III**  
1000 Rio Brazos Rd., Aztec, NM 87410

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO.  
**30-025-33780**

5. Indicate Type of Lease  
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name  
**MCNEILL "30"**

8. Well No.  
**1**

9. Pool name or Wildcat  
**DEVONIAN (WILDCAT)**

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator  
**ARCO Permian**

3. Address of Operator  
**P.O. Box 1610 Midland, TX 79702**

4. Well Location  
Unit Letter **P** : **467** Feet From The **SOUTH** Line and **990** Feet From The **EAST** Line

Section **30** Township **19S** Range **39E 35** NMPM **LEA** County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
**3607' GR**

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU PULLING UNIT. POOH W/RODS AND PUMP.  
ND WELLHEAD. NUBOP. POOH W/TBG.  
RU ELECTRIC LINE. SET CIBP @ 8600'. DUMP 35' CMT ON PLUG. TO BE ABANDONED  
ND BOP & TBG HEAD. STRETCH CASING AND CUT AT CALCULATED FREE POINT (+/- 6000')  
POOH LD 5-1/2" CASING.  
GIH W/TBG OE 50' INTO REMAINING 5-1/2" CASING. SPOT 30 SX PLUG. WOC & TAG.  
POOH AND SPOT 30 SX PLUG AT 4200-4100' (SAN ANDRES). WOC & TAG.  
POOH AND SPOT 30 SX PLUG AT 1672-1572' (TOP SALT).  
POOH AND SPOT 30 SX PLUG AT 471-371' (SURFACE SHOE).  
POOH. SPOT 10 SX PLUG 30'-SURFACE. CUT OFF WELLHEAD. RELEASE RIG.

THE COMMISSION MUST BE NOTIFIED 24  
HOURS PRIOR TO THE EFFECTIVE DATE OF  
PLUGGING OFF CASINGS AND THE CLOSURE  
TO BE ABANDONED

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Elizabeth A. Casbeer TITLE REG./COMPLIANCE DATE 3/31/98

TYPE OR PRINT NAME ELIZABETH A. CASBEER TELEPHONE NO. 915-688-5570

(This space for State Use)

COPIES SIGNED BY

COPY WINK

FIELD REP.

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

MAY 12 1998