State of New Mexico Energy, ...inerals and Natural Resources Department

Form C-103 Revised 1-1-89

Submit 3 Copies to Appropriate District Office <u>DI</u> P.0

District Office	OH CONCEDIATIO	NI DIVICIONI	
DISTRICT I	Box 1980, Hobbs NM 88241-1980 2040 Pacheco St.		WELL API NO.
·			30-025-34946
DISTRICT II Santa Fe, NM 87505		5. Indicate Type of Lease	
P.O. Drawer DD, Artesia, NM 88210			STATE FEE X
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			Ĭ
1. Type of Well:	-101) FOR SOON FROM OSALS.)		South Hobbs (GSA) Unit
OIL GAS G			
WELL WELL WELL WELL WELL WELL WELL WELL	OTHER Water	Injection	8. Well No.
2. Name of Operator	To achieve and the		
Occidental Permian Limited Partnership 3. Address of Operator			9. Pool name or Wildcat
P.O. Box 4294, Houston, TX 77210-4294			Hobbs; Grayburg - San Andres
4. Well Location	. / 220 222		Table 1 Carry Start 9 Dail 1 Start Co
Unit Letter I :198	Feet From The South	Line and 37	70 Feet From The East Line
Section 5		ange 38-E	NMPM Lea County
	10. Elevation (Show whether	er DF, RKB, RT, GR, etc. 3609' GL)
Check Ar	ista Day to Indicate		Danast as Other Data
_	opropriate Box to Indicate	1	- 1
NOTICE OF INTENTION TO:			SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		G OPNS.	
PULL OR ALTER CASING CASING TEST AND C		EMENT JOB 🔲	
OTHER:		OTHER: Run 5	-1/2" Production Casing
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed			
work) SEE RULE 1103.			
6/28/00 -			
6/29/00: Run 107 jts. 5-1/2", 15.5#, J-55, LT&C casing with 10 centralizers and set at 4395'.			
Cement with 800 sx. Premium Plus (lead) w/58,000 SCF Nitrogen and 100 sx. Premium Plus			
tail. Plug down and circulate 20 sx. to pit. Blow down backside and cap with 100 sx. Fremium Plus. WCC. ND BOP, set slips, cut off 5-1/2" casing, and rig down.			
riducing rise. Not. 10 Dary set bilps, the til 5 1/2 table, and rig domi.			
Release drilling rig @ 12:00 hours, 6/29/00.			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE Mark Step	phens m	E Business Anal	Lyst (SG) DATE 06/30/2000
TYPE OR PRINT NAME Mark Steph	ens		TELEPHONE NO. 281/552-1158
(This space for State Use)			
		the second second	146
APPROVED BY	ŢIII	LE	DATE
CONDITIONS OF APPROVAL, IF ANY:			

