						į.	Form C-
Submit 3 Copies	To Ap propriate District	State	of New 1	Mexico			March 25,
Office		Energy, Mine	rais and N	anırai Resources	WELL API		
<u>District (</u> 1625 N. French D	r., Hobbs, NM 87240				30-	-025 <u>-35815</u>	
District II	ND / #7710	OIL CONSI	ERVATIO	N DIVISION		Type of Lease	
District III	rtesia, NM 87210	2040	South Pa	checo		EFEE_	\square
1000 Rio Brazos i	Rd., Aziec, NM 87410	Santa	a Fe, NM	87505	6. State Oil	& Gas Lease No).
District IV 2040 South Pache	o, Santa Fe, NM 87505					27462 <u>. </u>	
	CI DIDDY NOTICE	S AND REPORTS	ON WELL	S	7. Lease Nar	ne or Unit Agree	ment Nan
PROPOSALS.) 1. Type of We	IIS FORM FOR PROPOSAI ERVOIR USE "APPLICA" II:	i s to drill or to l	DEEPEN UK P	TOG BACK TO A		Herradura	
	X Gas Well	·Ould			8. Well No.		
2. Name of O	perator c Oil & Gas Corp					#2	
3. Address of	Operator				9. Pool name		`
P. 0	. Box 352, Midla	and, TX 7970	2		Nadine l	Drinkard ABC	
4. Weil Locat		-					
Unit Le	nter 0 - 8	50 feet from th	e South	line and 16	50 feet	from the East	liı
Section	15	Township		MIEC 24-	MPM Lea	County	
36641011	10). Elevation (Show	whether D	R. RKB. RT. GR. etc.)			
		3	597' CR		TOTAL OF Other	er Data	
•	11. Check Appr	opriate Box to I	ndicate N	ature of Notice, Re		REPORT OF:	
. N	OTICE OF INTE	NTION TO:		SUBSE	מחביא ו ע	ALTERING	CASING
PERFORM REM	EDIAL WORK 🔲 PL	UG AND ABANDO	N	REMEDIAL WORK	<u></u>	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
TEMPORARILY A	ABANDON CH	IANGE PLANS		COMMENCE DRILLI	ng opns. [PLUG AND ABANDONM	ENT [
	CASING ML	IANGE PLANS ILTIPLE IMPLETION		COMMENCE DRILLI CASING TEST AND CEMENT JOB	ng opns. [PLUG AND ABANDONM	
PULL OR ALTER	CASING	ILTIPLE IMPLETION	0 (CASING TEST AND CEMENT JOB	ion Attemy	ABANDONM	
PULL OR ALTER	posed or completed op	ILTIPLE IMPLETION		CASING TEST AND CEMENT JOB OTHER: Complet	ion Attemp	ABANDONM	nated dat
OTHER: 2. Describe pro of starting arr	posed or completed op proposed work). SEE ion. MIRU Pulling Unit; 7340', 7348', 735	ILTIPLE IMPLETION ERULE 1103. For Install BOP; Perf A 50', 7386', 7392	Abo W/1 Sl	CASING TEST AND CEMENT JOB OTHER: Completionent details, and give completions: Attach we or Attach we see that the see th	ion Attemp pertinent date ellbore diagram follows: 72:	ABANDONM pt ss. including esum m of proposed co 54', 7302, 730 20', 7422', 74	nated dat mpletion 04, 34',
OTHER: 2. Describe proof starting arror recompilat	posed or completed op proposed work). SET ion. MIRU Pulling Unit; 7340', 7348', 7357440', 7442', 7447528', 7552', 757	ILTIPLE IMPLETION ERULE 1103. For Install BOP; Perf A 50', 7386', 7392: 4', 7446', 7452: 5', 7660', Total	Abo W/1 Sl 7, 7394', 7 7, 7460', 7	CASING TEST AND CEMENT JOB OTHER: Completionent details, and give completions: Attach we or Attach we see that the see th	pertinent date eilbore diagram	ABANDONM bt	mated date mpletion 04, 34',
PULL OR ALTER OTHER: 2. Describe pro of starting am or recompilat 3/8/02	posed or completed op proposed work). SEE ion. MIRU Pulling Unit; 7340', 7348', 735 7440', 7442', 744 7528', 7552', 757	ILTIPLE IMPLETION ERULE 1103. For Install BOP; Perf A 50', 7386', 7392: 4', 7446', 7452: 5', 7660', Total	Abo W/1 Sl 7, 7394', 7 7, 7460', 7	CASING TEST AND CEMENT JOB OTHER: Completionent details, and give completions: Attach we or Att	pertinent date eilbore diagram	ABANDONM bt	mated date mpletion 04, 34',
PULL OR ALTER OTHER: 12. Describe pro of starting and or recompilate 3/8/02	posed or completed op proposed work). SET ion. MIRU Pulling Unit; 7340', 7348', 7357440', 7442', 7447528', 7552', 757	ILTIPLE IMPLETION ERULE 1103. For Install BOP; Perf A 50', 7386', 7392: 4', 7446', 7452: 5', 7660', Total	Abo W/1 Sl 7, 7394', 7 7, 7460', 7	CASING TEST AND CEMENT JOB OTHER: Completionent details, and give completions: Attach we or Att	pertinent date eilbore diagram	ABANDONM bt	nated date mpletion 04, 34',
OTHER: 2. Describe proof starting amor recompilate 3/8/02	posed or completed op proposed work). SEE ion. MIRU Pulling Unit; 7340', 7348', 735 7440', 7442', 744 7528', 7552', 757	ILTIPLE IMPLETION ERULE 1103. For Install BOP; Perf A 50', 7386', 7392: 4', 7446', 7452: 5', 7660', Total	Abo W/1 Sl 7, 7394', 7 7, 7460', 7	CASING TEST AND CEMENT JOB OTHER: Completionent details, and give completions: Attach we or Att	pertinent date eilbore diagram	ABANDONM bt	nated date mpletion 04, 34',
PULL OR ALTER OTHER: 2. Describe pro of starting and or recompilate 3/8/02 3/9/02 3/10/02	posed or completed op proposed work). SEI ion. MIRU Pulling Unit; 7340', 7348', 735 7440', 7442', 744 7528', 7552', 757 RIH W/230 Jts 2 7. Flow test Abo.	ILTIPLE (MPLETION) ETATIONS. (Clearly SERULE 1103. For A 100', 7386', 7392', 7446', 7452', 7660', Total (100'), William (100'	Abo W/1 Sl ', 7394', 7 ', 7460', 7 33 0.42 Di	CASING TEST AND CEMENT JOB OTHER: Completionent details, and give completions: Attach we complete completions: Attach we complete com	ion Attemportment date eilbore diagram	ABANDONM bt	mated date mpletion 04, 34',
PULL OR ALTER OTHER: 2. Describe pro of starting and or recompilate 3/8/02 3/9/02 3/10/02	posed or completed op proposed work). SEI ion. MIRU Pulling Unit; 7340', 7348', 735 7440', 7442', 744 7528', 7552', 757 RIH W/230 Jts 2 7. Flow test Abo.	ILTIPLE (MPLETION) ETATIONS. (Clearly SERULE 1103. For A 100', 7386', 7392', 7446', 7452', 7660', Total (100'), William (100'	Abo W/1 Sl ', 7394', 7 ', 7460', 7 33 0.42 Di	CASING TEST AND CEMENT JOB OTHER: Completionent details, and give completions: Attach we complete completions: Attach we complete com	ion Attemportment date eilbore diagram	ABANDONM bt	nated dat mpletion 04, 34',
DTHER: 2. Describe proof starting amor recompilate 3/8/02 3/9/02 3/10/02	posed or completed op proposed work). SEE ion. MIRU Pulling Unit; 7340', 7348', 735 7440', 7442', 744 7528', 7552', 757	ILTIPLE (MPLETION) ETATIONS. (Clearly SERULE 1103. For A 100', 7386', 7392', 7446', 7452', 7660', Total (100'), William (100'	Abo W/1 SI 7, 7394', 7 7, 7460', 7 33 0.42 Di Pkr @ 71!	CASING TEST AND CEMENT JOB OTHER: Completionent details, and give completions: Attach we complete completions: Attach we complete com	follows: 72.7, 7414', 742', 7485', 74	ABANDONM bt	mated date mpletion 34, 34', 26',
PULL OR ALTER OTHER: 2. Describe pro of starting and or recompilate 3/8/02 3/9/02 3/10/02 ereby certify that	posed or completed op proposed work). SEI ion. MIRU Pulling Unit; 7340', 7348', 735 7440', 7442', 744 7528', 7552', 757 RIH W/230 Jts 2 7. Flow test Abo.	ILTIPLE IMPLETION ETATIONS. (Clearly SERULE 1103. For A 100, 7386, 7392) 14', 7446', 7452' 15', 7660', Total Serule and completions and completions and completions are and completions.	Abo W/1 SI 7, 7394', 7 7, 7460', 7 33 0.42 Di Pkr @ 71!	CASING TEST AND CEMENT JOB OTHER: Completionent details, and give completions: Attach we complete comple	follows: 72, 7414', 74., 7485'	ABANDONM The state of the stat	nated date mpletion 04, 34', 26',
of starting are or recompilated 3/8/02 3/9/02 3/10/02 GNATURE	posed or completed op proposed work). SEI ion. MIRU Pulling Unit; 7340', 7348', 735 7440', 7442', 744 7528', 7552', 757 RIH W/230 Jts 2 7. Flow test Abo.	ILTIPLE IMPLETION ETATIONS. (Clearly SERULE 1103. For A 100, 7386, 7392) 14', 7446', 7452' 15', 7660', Total Serule and completions and completions and completions are and completions.	Abo W/1 SI 7, 7394', 7 7, 7460', 7 33 0.42 Di Pkr @ 71!	CASING TEST AND CEMENT JOB OTHER: Completionent details, and give completions: Attach we complete comple	ion Attemportment date eilbore diagram follows: 72: 7,7414',74: 7,7485',	DATE 3/21 phone No. 915-	702 683-31
PULL OR ALTER OTHER: 12. Describe pro of starting and or recompilate 3/8/02 3/9/02 3/10/02 GNATURE	posed or completed op proposed work). SEI ion. MIRU Pulling Unit; 7340', 7348', 735 7440', 7442', 744 7528', 7552', 757 RIH W/230 Jts 2 7. Flow test Abo.	ILTIPLE IMPLETION ETATIONS. (Clearly SERULE 1103. For A 100, 7386, 7392) 14', 7446', 7452' 15', 7660', Total Serule and completions and completions and completions are and completions.	Abo W/1 Si 7, 7394', 7 7, 7460', 7 33 0.42 Di	CASING TEST AND CEMENT JOB OTHER: Completionent details, and give completions: Attach we complete comple	ion Attempertment date eilbore diagram follows: 72: 7,7414',74: 7,7485',	DATE 3/21 phone No. 915- ABANDONM DATE 3/21 APR 1 5 2002	702 683-31
PULL OR ALTER OTHER: 12. Describe pro of starting and or recompilate 3/8/02 3/9/02 3/10/02 GNATURE	posed or completed op proposed work). SEI ion. MIRU Pulling Unit; 7340', 7348', 735 7440', 7442', 744 7528', 7552', 757 RIH W/230 Jts 2 7. Flow test Abo.	ILTIPLE IMPLETION ERULE 1103. For Install BOP; Perf A 50', 7386', 7392 4', 7446', 7452 75', 7660', Total Is true and complete The complete of the complete	Abo W/1 Si 7, 7394', 7 7, 7460', 7 33 0.42 Di	CASING TEST AND CEMENT JOB OTHER: Completionent details, and give completions: Attach we complete comple	ion Attempertment date eilbore diagram follows: 72: 7,7414',74: 7,7485',	DATE 3/21 phone No. 915-	702 683-31