

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-06054
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	

7. Lease Name or Unit Agreement Name	E.H.B. Phillips
8. Well No.	1
9. Pool name or Wildcat	Eumont Yates 7 Rv Qn

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	2. Name of Operator Texaco Inc.
3. Address of Operator P.O. Box 730 Hobbs, NM 88240	4. Well Location Unit Letter <u>D</u> : <u>660</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>West</u> Line

Section <u>10</u>	Township <u>20S</u>	Range <u>37E</u>	NMPM <u>Lea</u>	County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3545 KB</u>				

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Kill well. Tag PBTD @ 3695. POH w/ tbg. Cleanout to PBTD if necessary.
2. Perf 3578-80, 85-87, 3642, 47-52, 59-65, 80-87. (28 int/56 holes)
3. TIH w/ pkr and set @ 3450.
4. Acidize Eumont w/ 3000 gal. 15% NEFE.
5. Frac Eumont w/ 32200 gal. 40# linear gel, 32200 gal. CO2 and 315000# 12/20 sand.
6. Flow back. Cleanout sand. Run rods & tbg. Place on test.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. D. Ridenour TITLE Engineer's Assistant DATE 8-24-90
TYPE OR PRINT NAME L. D. Ridenour TELEPHONE NO. 393-7191

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: