STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

-0. 07 (07)15 0(16)46	J. OIL CONSERVA	A LION DIVISION	
DISTRIBUTION	Р. О. во	X 2088	Form C-103 ·
SANTA FE	SANTA FE, NEW	V MEXICO 87501	Revised 10-1-78
FILE			to leder T
U.S.G.S.			5a. Indicate Type of Lease
LAND OFFICE	}		State Fee X
OPERATOR]		5, State Oil & Gas Lease No.
			•
SUNDR	Y NOTICES AND REPORTS ON PROBALS TO DRILL OR TO DEEPEN OF PLUG RE 100 POR PERMIT -" FORM C-101) FOR SUC	WELLS BACK TO A DIFFERENT RESERVOIR. EN PROPOSALS.)	
OIL X GAB WELL	OTHER-		7. Unit Agreement Name
2. Name of Operator			8. Farm or Legse Name
TEXACO Inc.		C. H. Weir B	
3. Address of Operator			9. Well No.
P. O. Box 728	, Hobbs, New Mexico 8824	40	2
4. Location of Well	<u></u>		10, Field and Pool, or Wildcat
A	660 FEET FROM THE North	660	10. Field and Pool, or Wildest Weir Blinebry East Skaggs Drinkard
UNIT LETTER A	FEET FROM THE	LINE AND FEET FROM	mmmmmm
Fast	11 TOWNSHIP 20-	-S 37-E	
THE LINE, SECTION	ON TOWNSHIP	HANGE HIMPM.	
mmmm	15. Elevation (Show whether	DE PT CP	
		(DF)	12. County Lea
Check	Appropriate Box To Indicate N	lature of Notice, Report or Oth	per Data
	TENTION TO:		REPORT OF:
·			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORABILY ABANDON		COMMENCE DRILLING OPNS.	, ;
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT
,		OTHER	. С
Repair Water F	low X	OTHER	
OTHER	======================================		
17. Describe Proposed or Completed Opwork) SEE RULE 1103.	erations (Clearly state all pertinent deta	ails, and give pertinent dates, including	estimated date of starting any proposed
		•	
•		1	
1. RIG UP.	PULL RODS AND PUMP.	INSTALL BOP. PULL	TUBING.
2. SET RBP	@ 4000' AND SPOT 2 S	X. SAND ON PLUG.	
_	TE 5 1/2" CASING W/2-		

ORIG	DISTRICT I SUPERVISOR		ALIC 2/ 1002	=
1CHED	1 Francisco		DATE	_
	the the	Asst Dist Mgr	8-22-83	
8. I hereby certify ti	hat the information above is true and com	aplete to the best of my knowledge and belief.		_
5.	INSTALL PRODUCTION	EQUIPMENT. TEST AND RETUR	N TO PRODUCTION.	
4.	5 I/2 CASING PE	NER @ 1410'. CEMENT TO S RFS @ 1509' W/ 600 SX. SQUEEZE W/ ADDL. 200 SX. WOC. DOC. TEST.	CIACC II CEMENT	
3.	PERFORATE 5 1/2" CA	ASING W/2-JS @ 1509'.		
3.				

SECEIVED

MG 2 3 1983

O.C.D.
HOBBS OFFICE