NO. OF COPIES RECEIVED	1		Form C-103
DISTRIBUTION			Supersedes Old C-102 and C-103
	NEW MEXICO OIL CONSE	RS AFIGNCEONMESSION	Effective 1-1-65
SANTA FE			
FILE	HAR (2 3 32 PN 156	5a. Indicate Type of Lease
U.S.G.S.			State Fee.
LAND OFFICE	-		5. State Oil & Gas Lease No.
OPERATOR	J		
(DO NOT USE THIS FORM FOR PRI USE "APPLICAT	RY NOTICES AND REPORTS ON W	VELLS CK TO A DIFFERENT RESERVOIR. PROPOSALS.)	7. Unit Agreement Name
1. GAS	OTHER-		7. Onit Agreement Ivane
WELL XX WELL	OTHER-		8. Farm or Lease Name
			Theodore Anderson
Gulf Oil Corporation 3. Address of Operator			9. Well No.
	A		5
Box 670, Hobbs, New Me	28100	······································	10. Field and Pool, or Wildcat
4. Location of Well	No Month	1980	Momment
UNIT LETTER	1980 FEET FROM THE North	LINE AND FEET FROM	
THE LINE, SECT	10N 17 TOWNSHIP 20-5	RANGE 37-E NMPN	
mmmmmmm	15. Elevation (Show whether D	DF, RT, GR, etc.)	12. County
		3541 GL	Lea Allilli
¹⁶ . Check	Appropriate Box To Indicate Na	ature of Notice, Report or O	ther Data
	INTENTION TO:	SUBSEQUEN	T REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPNS.	
		OTHER	
OTHER Flug and Abando			
		it i i i i i i i i i i i i i i i i i i	a estimated date of starting any proposed

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any prop work) SEE RULE 1903.

3865' TD, 3762' PB.

Pull rods and tubing. Run CI BF on bubing and set at approximately 3680'. Test 5-1/2" casing with 500#. Circulate hole with 85 barrels of mid. Spot 10 sack cement plug on top of BP. Pull tubing to 50'. Spot 10 sack cement plug to surface. Install dry hole marker and clean location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED	TITLE Area Production Manager	DATE February 25, 1966
APPROVED BY	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:		