MO. OF COPICS BCCCIVCO	•
DISTRIBUTION	Form C-103
SANTA FE	Supersedes Old C-102 and C-103
FILE NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
U.S.G.S.	
LAND OFFICE	Sa. maicate Type of Lease
OPERATOR	State X Fee
	2. Style (1. 6 Los Lease No.
	B-1481
SUNDRY NOTICES AND REPORTS ON WELLS	
USE "APPLICATION FOR PLANIT -" IFOR A CHICLE SUCH PROPORTIES I	\sim $((((((((((((((((((((((((((((((((((($
	7. Unit Agreenent Liame
WELL X OTHER.	
Cities Service Oil & Gas Corp.	8. rum or Lease Hame
J. Adaress of Operator	State F
	9. Well No.
P.O. Box 1919 - Midland, Texas 79702	2
	10. Field and Pool, or Mildeat
WHIT LETTER I 1980 FEET FROM THE South LINE AND 660	
	Eumont Yates 7 Rvs Que
THE East LINE, SECTION 30 TOWNSHIP 20S AANGE 37E	
	<u> </u>
15. Elevation (Show whether DF, RT, GR, etc.)	
3536'GR	12. County
	Lea())))))))
Check Appropriate Box To Indicate Nature of Notice, Repor NOTICE OF INTENTION TO:	t or Other Data
SUBSI	EQUENT REPORT OF:
TEMPORARILY ABANDON	ALTERING CASING
PULL OR ALTER CASING	
CHANGE PLANS CASING TEST AND CEMENT JOB	PLUE AND ABANDONMENT
0THCR	
 7. Describe Proposed or Completed Operations (Clearly state cli pertinent details, and give pertinent dates, work) SEE RULE 1103. 0. T. D. 2025 L. L. 2025 F. 	·
work) SEE RULE 1103.	
	including estimated date of starting any proposed
$V_{-}I_{-}II_{-}$ $\Delta \Delta \Delta \Delta \Delta L_{1}$ $MODTO \Delta C Z C I = 1$	
V_{1} V_{2} V_{3} V_{1} V_{2} V_{3} V_{2} V_{3} V_{3} V_{2} V_{3} V_{3	
V_{1} V_{2} V_{2} V_{3} V_{1} V_{2} V_{3} V_{2} V_{3} V_{3	
3363 - 3535' Lime, OPBTD 3675'. It is proposed to squeeze off the 3363 - 3535', DO the CIBP which is set @ 3675' and CO to the O.T.Manner:	e producing Queen Perfs @ D. of 3835' in the following
3363 - 3535' Lime, OPBTD 3675'. It is proposed to squeeze off the 3363 - 3535', DO the CIBP which is set @ 3675' and CO to the O.T.Manner:	e producing Queen Perfs @ D. of 3835' in the following
3363 - 3535' Lime, OPBTD 3675'. It is proposed to squeeze off the 3363 - 3535', DO the CIBP which is set @ 3675' and CO to the O.T.Manner:	e producing Queen Perfs @ D. of 3835' in the following
 0.1.D. 3835' Lime, OPBTD 3675'. It is proposed to squeeze off the 3363 - 3535', DO the CIBP which is set @ 3675' and CO to the O.T.I manner: 1. MIRU a pulling unit, kill well w/produced water, ND WH, and packer. 	e producing Queen Perfs @ D. of 3835' in the following , NU BOP, and POOH w/tubing
 1. MIRU a pulling unit, kill well w/produced water, ND WH, and packer. 2. Set a 7" cement retainon @ + 22751 DIM (0.11) 	e producing Queen Perfs @ D. of 3835' in the following , NU BOP, and POOH w/tubing
 1. Jackson Lime, OPBTD 3675'. It is proposed to squeeze off the 3363 - 3535', D0 the CIBP which is set @ 3675' and C0 to the O.T.I manner: 1. MIRU a pulling unit, kill well w/produced water, ND WH, and packer. 2. Set a 7" cement retainer @ + 3275', RIH w/tubing and set Oueen Perfs @ 3363 - 3525' w/125 area 	e producing Queen Perfs @ D. of 3835' in the following , NU BOP, and POOH w/tubing eal assembly and squeeze the
 1. J. 3835 Lime, OPBTD 3675'. It is proposed to squeeze off the 3363 - 3535', DO the CIBP which is set @ 3675' and CO to the O.T.I manner: 1. MIRU a pulling unit, kill well w/produced water, ND WH, and packer. 2. Set a 7" cement retainer @ + 3275', RIH w/tubing and set Oueen Perfs @ 3363 - 3525' w/125 area 	e producing Queen Perfs @ D. of 3835' in the following , NU BOP, and POOH w/tubing eal assembly and squeeze the
 0.1.D. 3835' Lime, OPBTD 3675'. It is proposed to squeeze off the 3363 - 3535', D0 the CIBP which is set @ 3675' and C0 to the O.T.I manner: 1. MIRU a pulling unit, kill well w/produced water, ND WH, and packer. 2. Set a 7" cement retainer @ + 3275', RIH w/tubing and sequeen Perfs @ 3363 - 3535' w/125 sacks of Class C + 0.3 of Class C neat. PU out of retainer and reverse out ex w/tubing and seal assembly. 	e producing Queen Perfs @ D. of 3835' in the following , NU BOP, and POOH w/tubing eal assembly and squeeze the 3% Halad-4 cement and 75 sacks access cement to the pit. POOH
 3835' Lime, OPBTD 3675'. It is proposed to squeeze off the 3363 - 3535', D0 the CIBP which is set @ 3675' and C0 to the O.T.I manner: MIRU a pulling unit, kill well w/produced water, ND WH, and packer. Set a 7" cement retainer @ + 3275', RIH w/tubing and se Queen Perfs @ 3363 - 3535' w/125 sacks of Class C + 0.3 of Class C neat. PU out of retainer and reverse out ex w/tubing and seal assembly. RIH w/RB, and DC's on 2-3/8" tubing and d it. 	e producing Queen Perfs @ D. of 3835' in the following , NU BOP, and POOH w/tubing eal assembly and squeeze the 3% Halad-4 cement and 75 sacks access cement to the pit. POOH
 3835' Lime, OPBTD 3675'. It is proposed to squeeze off the 3363 - 3535', D0 the CIBP which is set @ 3675' and C0 to the O.T.I manner: MIRU a pulling unit, kill well w/produced water, ND WH, and packer. Set a 7" cement retainer @ + 3275', RIH w/tubing and sequeen Perfs @ 3363 - 3535' w/125 sacks of Class C + 0.3 of Class C neat. PU out of retainer and reverse out ex w/tubing and seal assembly. RIH w/RB and DC's on 2-3/8" tubing and drill out squeezed and sequent and squeeze is to form and squeeze in the form of the squeeze is to form and squeeze is to form and be be form of the squeeze is to form and squeeze is to form and be be form of the squeeze is to form and squeeze is t	e producing Queen Perfs @ D. of 3835' in the following , NU BOP, and POOH w/tubing eal assembly and squeeze the 3% Halad-4 cement and 75 sacks access cement to the pit. POOH are cement. Pressure test the
 3835' Lime, OPBTD 3675'. It is proposed to squeeze off the 3363 - 3535', D0 the CIBP which is set @ 3675' and C0 to the O.T.I manner: MIRU a pulling unit, kill well w/produced water, ND WH, and packer. Set a 7" cement retainer @ + 3275', RIH w/tubing and sequeen Perfs @ 3363 - 3535' w/125 sacks of Class C + 0.3 of Class C neat. PU out of retainer and reverse out ex w/tubing and seal assembly. RIH w/RB and DC's on 2-3/8" tubing and drill out squeezed and sequent and squeeze is to form and squeeze in the form of the squeeze is to form and squeeze is to form and be be form of the squeeze is to form and squeeze is to form and be be form of the squeeze is to form and squeeze is t	e producing Queen Perfs @ D. of 3835' in the following , NU BOP, and POOH w/tubing eal assembly and squeeze the 3% Halad-4 cement and 75 sacks access cement to the pit. POOH are cement. Pressure test the
 3835' Lime, OPBTD 3675'. It is proposed to squeeze off the 3363 - 3535', D0 the CIBP which is set @ 3675' and CO to the O.T.I manner: MIRU a pulling unit, kill well w/produced water, ND WH, and packer. Set a 7" cement retainer @ + 3275', RIH w/tubing and set Queen Perfs @ 3363 - 3535' w/125 sacks of Class C + 0.3 of Class C neat. PU out of retainer and reverse out ex w/tubing and seal assembly. RIH w/RB and DC's on 2-3/8" tubing and drill out squeez casing and squeeze job to 500#. FIH w/RB and DC's to 3 the CIBP which is set @ 3675' and CO the OH to the O.T. 	e producing Queen Perfs @ D. of 3835' in the following NU BOP, and POOH w/tubing eal assembly and squeeze the 3% Halad-4 cement and 75 sacks access cement to the pit. POOH re cement. Pressure test the 6675' and drill out cement and D. of 3835' POOH w/RB DC'r
 3835' Lime, OPBTD 3675'. It is proposed to squeeze off the 3363 - 3535', D0 the CIBP which is set @ 3675' and CO to the O.T.I manner: MIRU a pulling unit, kill well w/produced water, ND WH, and packer. Set a 7" cement retainer @ + 3275', RIH w/tubing and set Queen Perfs @ 3363 - 3535' w/125 sacks of Class C + 0.3 of Class C neat. PU out of retainer and reverse out ex w/tubing and seal assembly. RIH w/RB and DC's on 2-3/8" tubing and drill out squeez casing and squeeze job to 500#. FIH w/RB and DC's to 3 the CIBP which is set @ 3675' and CO the OH to the O.T. 	e producing Queen Perfs @ D. of 3835' in the following NU BOP, and POOH w/tubing eal assembly and squeeze the 3% Halad-4 cement and 75 sacks access cement to the pit. POOH re cement. Pressure test the 6675' and drill out cement and D. of 3835' POOH w/RB DC'r
 Jass' Lime, OPBTD 3675'. It is proposed to squeeze off the 3363 - 3535', D0 the CIBP which is set @ 3675' and C0 to the O.T.I manner: MIRU a pulling unit, kill well w/produced water, ND WH, and packer. Set a 7" cement retainer @ + 3275', RIH w/tubing and sequeen Perfs @ 3363 - 3535' w/l25 sacks of Class C + 0.3 of Class C neat. PU out of retainer and reverse out ex w/tubing and seal assembly. RIH w/RB.and DC's on 2-3/8" tubing and drill out squeez casing and squeeze job to 500#. FIH w/RB and DC's to 3 the CIBP which is set @ 3675' and C0 the OH to the 0.T. and tubing. RIH w/2-3/8" OE'd tubing to 3566', ND BOP, NU WH and sh 	e producing Queen Perfs @ D. of 3835' in the following , NU BOP, and POOH w/tubing eal assembly and squeeze the 3% Halad-4 cement and 75 sacks access cement to the pit. POOH ce cement. Pressure test the 6675' and drill out cement and D. of 3835'. POOH w/RB, DC's
 Jame, OPBTD 3675'. It is proposed to squeeze off the 3363 - 3535', D0 the CIBP which is set @ 3675' and C0 to the O.T.I manner: MIRU a pulling unit, kill well w/produced water, ND WH, and packer. Set a 7" cement retainer @ + 3275', RIH w/tubing and sequeen Perfs @ 3363 - 3535' w/l25 sacks of Class C + 0.3 of Class C neat. PU out of retainer and reverse out ex w/tubing and seal assembly. RIH w/RB.and DC's on 2-3/8" tubing and drill out squeez casing and squeeze job to 500#. FIH w/RB and DC's to 3 the CIBP which is set @ 3675' and C0 the OH to the 0.T. and tubing. 	e producing Queen Perfs @ D. of 3835' in the following , NU BOP, and POOH w/tubing eal assembly and squeeze the 3% Halad-4 cement and 75 sacks access cement to the pit. POOH ce cement. Pressure test the 6675' and drill out cement and D. of 3835'. POOH w/RB, DC's
 U.T.D. 3835' Lime, OPBTD 3675'. It is proposed to squeeze off the 3363 - 3535', D0 the CIBP which is set @ 3675' and C0 to the O.T.I manner: MIRU a pulling unit, kill well w/produced water, ND WH, and packer. Set a 7" cement retainer @ + 3275', RIH w/tubing and sequeen Perfs @ 3363 - 3535' w/l25 sacks of Class C + 0.3 of Class C neat. PU out of retainer and reverse out ex w/tubing and seal assembly. RIH w/RB, and DC's on 2-3/8" tubing and drill out squeez casing and squeeze job to 500#. FIH w/RB and DC's to 3 the CIBP which is set @ 3675' and C0 the OH to the 0.T. and tubing. RIH w/2-3/8" OE'd tubing to 3566', ND BQP, NU WH and sh 	e producing Queen Perfs @ D. of 3835' in the following NU BOP, and POOH w/tubing eal assembly and squeeze the 3% Halad-4 cement and 75 sacks access cement to the pit. POOH ce cement. Pressure test the 6675' and drill out cement and D. of 3835'. POOH w/RB, DC's wut-in the well.
 0.1.D. 3835 Lime, OPBTD 3675'. It is proposed to squeeze off the 3363 - 3535', D0 the CIBP which is set @ 3675' and CO to the O.T.M manner: MIRU a pulling unit, kill well w/produced water, ND WH, and packer. Set a 7" cement retainer @ + 3275', RIH w/tubing and see Queen Perfs @ 3363 - 3535' w/125 sacks of Class C + 0.3 of Class C neat. PU out of retainer and reverse out ex w/tubing and seal assembly. RIH w/RB.and DC's on 2-3/8" tubing and drill out squeez casing and squeeze job to 500#. FIH w/RB and DC's to 3 the CIBP which is set @ 3675' and CO the OH to the 0.T. and tubing. RIH w/2-3/8" OE'd tubing to 3566', ND BOP, NU WH and sh this well will be turned over to Chevron and will te unitized into a well #114. 	e producing Queen Perfs @ D. of 3835' in the following , NU BOP, and POOH w/tubing eal assembly and squeeze the 3% Halad-4 cement and 75 sacks access cement to the pit. POOH ce cement. Pressure test the 6675' and drill out cement and D. of 3835'. POOH w/RB, DC's
 0.1.D. 3835' Lime, OPBTD 3675'. It is proposed to squeeze off the 3363 - 3535', D0 the CIBP which is set @ 3675' and CO to the O.T.M manner: MIRU a pulling unit, kill well w/produced water, ND WH, and packer. Set a 7" cement retainer @ + 3275', RIH w/tubing and see Queen Perfs @ 3363 - 3535' w/125 sacks of Class C + 0.3 of Class C neat. PU out of retainer and reverse out ex w/tubing and seal assembly. RIH w/RB. and DC's on 2-3/8" tubing and drill out squeez casing and squeeze job to 500#. FIH w/RB and DC's to 3 the CIBP which is set @ 3675' and CO the OH to the 0.T. and tubing. RIH w/2-3/8" OE'd tubing to 3566', ND BOP, NU WH and sh This well will be turned over to Chevron and will te unitized into Init as well #114. 	e producing Queen Perfs @ D. of 3835' in the following , NU BOP, and POOH w/tubing eal assembly and squeeze the 3% Halad-4 cement and 75 sacks access cement to the pit. POOH ce cement. Pressure test the 6675' and drill out cement and D. of 3835'. POOH w/RB, DC's
 3335' Lime, OPBTD 3675'. It is proposed to squeeze off the 3363 - 3535', D0 the CIBP which is set @ 3675' and C0 to the O.T.I manner: MIRU a pulling unit, kill well w/produced water, ND WH, and packer. Set a 7" cement retainer @ + 3275', RIH w/tubing and see Queen Perfs @ 3363 - 3535' w/125 sacks of Class C + 0.3 of Class C neat. PU out of retainer and reverse out ex w/tubing and seal assembly. RIH w/RB and DC's on 2-3/8" tubing and drill out squeez casing and squeeze job to 500#. FIH w/RB and DC's to 3 the CIBP which is set @ 3675' and C0 the OH to the 0.T. 	e producing Queen Perfs @ D. of 3835' in the following , NU BOP, and POOH w/tubing eal assembly and squeeze the 3% Halad-4 cement and 75 sacks access cement to the pit. POOH ce cement. Pressure test the 6675' and drill out cement and D. of 3835'. POOH w/RB, DC's
 0.1.D. 3835' Lime, OPBTD 3675'. It is proposed to squeeze off the 3363 - 3535', D0 the CIBP which is set @ 3675' and C0 to the 0.T.M manner: MIRU a pulling unit, kill well w/produced water, ND WH and packer. Set a 7" cement retainer @ + 3275', RIH w/tubing and see Queen Perfs @ 3363 - 3535' w/125 sacks of Class C + 0.3 of Class C neat. PU out of retainer and reverse out ex w/tubing and seal assembly. RIH w/RB and DC's on 2-3/8" tubing and drill out squeez casing and squeeze job to 500#. FIH w/RB and DC's to 3 the CIBP which is set @ 3675' and C0 the OH to the 0.T. and tubing. RIH w/2-3/8" OE'd tubing to 3566', ND BOP, NU WH and sh This well will be turned over to Chevron and will be unitized into Jnit as well #114. 	e producing Queen Perfs @ D. of 3835' in the following , NU BOP, and POOH w/tubing eal assembly and squeeze the 3% Halad-4 cement and 75 sacks access cement to the pit. POOH access cement to the pit. POOH and drill out cement and D. of 3835'. POOH w/RB, DC's nut-in the well. their Eunice Monument South
 0.1.D. 3835' Lime, OPBTD 3675'. It is proposed to squeeze off the 3363 - 3535', D0 the CIBP which is set @ 3675' and CO to the O.T.I manner: MIRU a pulling unit, kill well w/produced water, ND WH, and packer. Set a 7" cement retainer @ + 3275', RIH w/tubing and set Queen Perfs @ 3363 - 3535' w/125 sacks of Class C + 0.3 of Class C neat. PU out of retainer and reverse out ex w/tubing and seal assembly. RIH w/RB and DC's on 2-3/8" tubing and drill out squeez casing and squeeze job to 500#. FIH w/RB and DC's to 3 the CIBP which is set @ 3675' and CO the OH to the 0.T. and tubing. RIH w/2-3/8" OE'd tubing to 3566', ND BOP, NU WH and sh This well will be turned over to Chevron and will te unitized into Jnit as well #114. 	e producing Queen Perfs @ D. of 3835' in the following , NU BOP, and POOH w/tubing eal assembly and squeeze the 3% Halad-4 cement and 75 sacks access cement to the pit. POOH se cement. Pressure test the 2675' and drill out cement and D. of 3835'. POOH w/RB, DC's out-in the well. their Eunice Monument South
 3835' Lime, OPBTD 3675'. It is proposed to squeeze off the 3363 - 3535', D0 the CIBP which is set @ 3675' and C0 to the O.T.M manner: MIRU a pulling unit, kill well w/produced water, ND WH, and packer. Set a 7" cement retainer @ + 3275', RIH w/tubing and see Queen Perfs @ 3363 - 3535' w/125 sacks of Class C + 0.3 of Class C neat. PU out of retainer and reverse out ex w/tubing and seal assembly. RIH w/RB and DC's on 2-3/8" tubing and drill out squeeze casing and squeeze job to 500#. FIH w/RB and DC's to 3 the CIBP which is set @ 3675' and C0 the OH to the 0.T. and tubing. RIH w/2-3/8" OE'd tubing to 3566', ND BOP, NU WH and sh This well will be turned over to Chevron and will be unitized into Jnit as well #114. 	e producing Queen Perfs @ D. of 3835' in the following , NU BOP, and POOH w/tubing eal assembly and squeeze the 3% Halad-4 cement and 75 sacks access cement to the pit. POOH access cement to the pit. POOH and drill out cement and D. of 3835'. POOH w/RB, DC's nut-in the well. their Eunice Monument South
 3835' Lime, OPBTD 3675'. It is proposed to squeeze off the 3363 - 3535', D0 the CIBP which is set @ 3675' and C0 to the O.T.M manner: MIRU a pulling unit, kill well w/produced water, ND WH, and packer. Set a 7" cement retainer @ + 3275', RIH w/tubing and see Queen Perfs @ 3363 - 3535' w/125 sacks of Class C + 0.3 of Class C neat. PU out of retainer and reverse out ex w/tubing and seal assembly. RIH w/RB and DC's on 2-3/8" tubing and drill out squeeze casing and squeeze job to 500#. FIH w/RB and DC's to 3 the CIBP which is set @ 3675' and C0 the OH to the 0.T. and tubing. RIH w/2-3/8" OE'd tubing to 3566', ND BOP, NU WH and sh This well will be turned over to Chevron and will be unitized into Jnit as well #114. 	e producing Queen Perfs @ D. of 3835' in the following , NU BOP, and POOH w/tubing eal assembly and squeeze the 3% Halad-4 cement and 75 sacks access cement to the pit. POOH access cement to the pit. POOH ce cement. Pressure test the 6675' and drill out cement and D. of 3835'. POOH w/RB, DC's nut-in the well. their Eunice Monument South
 3835' Lime, OPBTD 3675'. It is proposed to squeeze off the 3363 - 3535', D0 the CIBP which is set @ 3675' and C0 to the O.T.M manner: MIRU a pulling unit, kill well w/produced water, ND WH, and packer. Set a 7" cement retainer @ + 3275', RIH w/tubing and see Queen Perfs @ 3363 - 3535' w/125 sacks of Class C + 0.3 of Class C neat. PU out of retainer and reverse out ex w/tubing and seal assembly. RIH w/RB and DC's on 2-3/8" tubing and drill out squeez casing and squeeze job to 500#. FIH w/RB and DC's to 3 the CIBP which is set @ 3675' and C0 the OH to the 0.T. and tubing. RIH w/2-3/8" OE'd tubing to 3566', ND BOP, NU WH and sh Chis well will be turned over to Chevron and will be unitized into Jnit as well #114. 	e producing Queen Perfs @ D. of 3835' in the following , NU BOP, and POOH w/tubing eal assembly and squeeze the 3% Halad-4 cement and 75 sacks access cement to the pit. POOH access cement to the pit. POOH te cement. Pressure test the 6675' and drill out cement and D. of 3835'. POOH w/RB, DC's out-in the well. their Eunice Monument South

÷