

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REOPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT - "C" FORM C-101 FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> T.A. GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator Atlantic Richfield Company		5. State Oil & Gas Lease No. 193
3. Address of Operator P. O. Box 1710, Hobbs, New Mexico 88240		7. Unit Agreement Name
4. Location of Well UNIT LETTER <u>L</u> <u>1650</u> FEET FROM THE <u>South</u> LINE AND <u>990</u> FEET FROM THE <u>West</u> LINE, SECTION <u>30</u> TOWNSHIP <u>20S</u> RANGE <u>37E</u> N.M.P.M.		8. Farm or Lease Name State 193
15. Elevation (Show whether DF, RT, GR, etc.) 3541' GR		9. Well No. 1
16.		10. Field and Pool, or Wildcat Eunice Monument Grbg SA
		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 3837'
7" OD 24# csg set @ 3751'. Cmted w/300 sx.
9-5/8" OD 40# csg set @ 1277'. Cmted w/500 sx.
12-1/2" OD 50# csg set @ 254'. Cmted w/300 sx.
Present perfs 3751-3837'.

Propose to P&A in the following manner:


1. Kill well, install BOP. POH w/completion assy.
2. Set 7" cmt retr on tbg @ 3650' & squeeze w/100 sx cmt.
3. Load hole w/heavy gelled mud.
4. Cut 7" csg from free point.
5. Spot 40 sk cmt plug half in and half out 7" OD csg stub.
6. Spot 40 sk cmt plug across 9-5/8" csg shoe & top of salt.
7. Spot 10 sx cmt @ surface.
8. Install regulation dry hole marker, clean & level location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED H. J. Bernard TITLE Dist. Drlg. Supv.

DATE 1/21/75

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:



ATLANTIC RICHFIELD COMPANY
Blow Out Preventer Program

Lease Name State 193

Well No. 1

Location 1650' FSL & 990' FWL,
Sec 30, T20S, R37E, Lea Co.

BOP to be tested before installed on well and will be maintained in good working condition during workover. All wellhead fittings to be of sufficient pressure to operate in a safe manner.