

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-06794

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS

WELL ☒

OTHER

2. Name of Operator

TEXACO PRODUCING INC

3. Address of Operator

P.O. BOX 728, HOBBS, NEW MEXICO 88240

4. Well Location

Unit Letter F : 1980 Feet From The NORTH Line and 1980 Feet From The WEST Line

Section

26

Township

21S

Range

37E

NMPM

LEA

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3395 D.F.

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☒

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: TUBB ZONE-TA; BUNEBRY-ACIDIZE ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

THE S.J. SARKEYS WELL NO. 4 IS A DUAL COMPLETION. THE TUBB ZONE FLOWS UP THE BACKSIDE. THE BUNEBRY OIL & GAS ZONE IS ON PUMP. IT IS PROPOSED TO TEMPORARILY ABANDON THE TUBB ZONE. IT IS ALSO PROPOSED TO ACIDIZE THE BUNEBRY ZONE.

1. MIRV. POH WITH BUNEBRY PRODUCTION RODS AND PUMP.
2. RIG UP WIRELINE. SET PLUG IN E.R. RECEPTACLE @ 6058'. RIG DOWN WIRELINE. (TUBB PERFS 6135'-6235')
3. PICKUP AND GET 6000 LBS OVER BUNEBRY STRING WEIGHT AND SNAP OUT OF E.R. RECEPTACLE. TO H.
4. TIH WITH BUNEBRY PRODUCTION EQUIPMENT.
5. PLACE WELL ON TEST. AFTER WELL STABILIZES, PUMP 55 GAL. PARAFFIN DISPERANT. CIRC. WELL FOR 24 HRS.
6. TEST WELL. ACIDIZE BUNEBRY PERFS (5733'-5855') WITH 1000 GALS 15% NEFE HCL ACID DOWN BACKSIDE. TEST WELL.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

K.L. Johnson

TITLE

AREA SUPERINTENDENT

DATE

MAR 1 1989

TYPE OR PRINT NAME

K.L. Johnson

TELEPHONE NO. 394-2585

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

MAR 3 1989

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

4-22-1989

RECEIVED

MAR 2 1989

OCD
HOBBS OFFICE