

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN _____ DATE _____
(Other Instructions on Reverse Side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 032096 (2)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Continental Oil Company

3. ADDRESS OF OPERATOR

P. O. Box 460, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1980' FNL 4'330' FNL of Sec. 27, T-21S,

R-22E, in De Baca County, N. Mex.

14. PERMIT NO.

15. ELEVATIONS (Show whether DT, RT, CA, etc.)

3952' DT

7. UNIT AGREEMENT NAME

M.M.F. 21

8. FARM OR LEASE NAME

Zachary A-27

9. WELL NO.

7

10. FIELD AND POOL, OR WILDCAT

Monte Ole Pool

11. SECT., T., R., OR BLK. AND SURVEY OR AREA

Sec. 27, T-21S, R-22E

12. COUNTY OR PARISH 13. STATE

Dea N. Mex.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETION

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

Recompletion

☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

☐
☐
☐
☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

It is proposed to squeeze the Blinney zone and open the Abo zone by the following procedure:

Drill out cement and cast iron bridge plug at 5895'. Squeeze Blinney perf at 5790-5965'. Drill out cement and cast iron bridge plug at 6010. Clean out to 7350' and set cast iron bridge plug. Selectively perforate Abo from 6770' to 7296' with 1-3/8" JSPF. Treat perf from 6770' to 7296' with 4,000 gals 15% LSTNE acid and ball sealers. Test zone.

18. I hereby certify that the foregoing is true and correct

SIGNED

M.E. Yeakley

TITLE Administrative Section Chief

DATE 1-22-69

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

DATE

JAN 25 1969

U.S.G.S.-5 Atk Ross, for Am Hobbs 2,
Chas mid 2, 2 ilc.

*See Instructions on Reverse Side

J. L. GORDON
ACTING DISTRICT ENGINEER