

COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NE MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

Corrected Report

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <u>EXXON CORPORATION</u>	8. Farm or Lease Name <u>F.F. HARDISON "B"</u>
3. Address of Operator <u>P.O. BOX 1600, MIDLAND, TEXAS 79701</u>	9. Well No. <u>6</u>
4. Location of Well UNIT LETTER <u>J</u> , <u>1980</u> FEET FROM THE <u>SOUTH</u> LINE AND <u>1980</u> FEET FROM THE <u>EAST</u> LINE, SECTION <u>27</u> TOWNSHIP <u>21-S</u> RANGE <u>37-E</u> NMPM.	10. Field and Pool, or Wildcat <u>DRINKARD</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>DF-3410</u>	12. County <u>LEA</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUS AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>PERF. & FRAC ADDITIONAL DRINKARD</u> <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

KILL WELL AND PULL TBG OUT OF HOLE. RUN A GR/N LOG AND COLLAR LOCATOR FROM 6575 TO 3800'. PERFORATE THE INTERVALS PICKED BY GEOLOGIST WITH A JET CASING GUN. USE LUBRICATOR WHEN PERFORATING. RUN A RETRIEVABLE BRIDGE PLUG AND TREATING PACKER ON 2 7/8" WORKSTRING. A SUPPLEMENTAL PROCEDURE WILL BE PREPARED TO ACID FRAC THE NEWLY PERFORATED INTERVAL. SHEAFER 39, MANUAL, DOUBLE RAM BOP W/3000# WORKING PRESSURE.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>A. L. Clemmer</u>	TITLE <u>UNIT HEAD</u>	DATE <u>1-12-76</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>[Signature]</u>	DATE <u>1-12-76</u>

CONDITIONS OF APPROVAL, IF ANY: