

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells)	
30-025-06834	
5. Indicate Type of Lease	
STATE	<input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	
N/A	
7. Lease Name or Unit Agreement Name	
J.N. CARSON (NCT-C)	
8. Well No.	
7	
9. Pool name or Wildcat	
PADDOCK	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG B DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well:	
OIL WELL <input checked="" type="checkbox"/>	GAS WELL <input type="checkbox"/> OTHER
2. Name of Operator	
CHEVRON U.S.A. INC.	
3. Address of Operator	
P.O. BOX 1150 MIDLAND, TX 79702 ATTN: P.R. MATTHEWS	
4. Well Location	
Unit Letter	P : 554 Feet From Th SOUTH Line and 554 Feet From The EAST Line
Section	28 Township 21S Range 37E NMPM LEA County
10. Elevation(Show whether DF, RKB, RT, GR, etc.)	
3439' GE	

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CMT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including
estimated date of starting any proposed work) SEE RULE 1103.

IT IS PROPOSED TO:

SET CIBP AT 5100', SPOT 150' CMT F/5100-4950, PLUG COVERS GLORIETA.
SPOT 200' CMT F/3950-3750, PLUG COVERS SAN ANDRES.
PERF AT 2850', SET CIGR AT 2460', PUMP INTO W/115 SX. CMT PULL OUT AND LEAVE 35' CMT ON TOP.
ABOVE PLUG WILL COVER YATES AND 8 5/8" CASING SHOE.
PERF AT 1240', SET CIGR AT 1100', PUMP 85 SX. CMT INTO AND LEAVE 35' CMT ON TOP.
ABOVE PLUG WILL COVER TOP OF SALT AND RUSTLER.
PERF AT 360', SPOT 90 SXS. CMT & BRING 210' UP 9 5/8" 7 13 3/8" CSG. SPOT 60' CMT TO SURFACE.
10# P & A MUD WILL BE PLACED BETWEEN ALL CMT. PLUGS.
CUT OFF WELLHEAD AND INSTALL P & A MARKER.
CHANGE WELL STATUS TO P & A.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE	<u>P.R. Matthews</u>	TITLE	TECH. ASSISTANT	DATE:	5-8-92
TYPE OR PRINT NAME	P.R. MATTHEWS	TELEPHONE NO	(915)687-7812		

APPROVED BY _____ TITLE _____ DATE **MAY 11 '92**
CONDITIONS OF APPROVAL, IF ANY: _____