D15	TRIBUTION	
SANTA FE		
FILE		
U. S. G. S.		
LAND OFFICE		
TRANSPORTER	OIL	
	GAS	
PRORATION OFFI	E	
OBERATOR		

## NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

MISCELLANEOUS NOTICES

\*\*Trict Office Oil Conservation Commission before the work specified is to begin. A copy will be

	ulations of the Commission.  Indicate Nature of Notice by Checking	g Below	
Notice of Intention to Change Plans	Notice of Intention to Temporarily Abandon Well	Notice of Intention to Drill Deeper	
Notice of Intention to Plug Well	Notice of Intention to Plug Back	Notice of Intention to Set Liner	
Notice of Intention to Squeeze	Notice of Intention to Acidize	Notice of Intention to Shoot (Nitro)	
Notice of Intention to Gun Perforate	Notice of Intention (Other)	Notice of Intention (Other) Abandon Drinkard	& rec
OIL CONSERVATION COMMISSION Santa fe, New Mexico	N Hobbs, New Mexico	in Blinebry October 3, 1962	••••
Gentlemen:			
ulf Oil Corporation	Eunice King	Well No. 4 in B	
(Company or Ope	rator) Lease	MPM., <b>Drinkard</b>	mit) Рос
(FOLI	FULL DETAILS OF PROPOSED PLA LOW INSTRUCTIONS IN THE RULES A	ND REGULATIONS)	
It is proposed to abando  1. Kill well and po  2. Set CI EP at app  3. Test plug and ed  4. Run GR-N log. If  5. Run 3-1/2" frac  NEA and frac with  per gal and 1 to  6. Swab and test.	on Drinkard and recomplete in all tubing. proximately 6475' on wire line sing with 1000%. Perforate Blinebry in the intertubing with FB packer and act the 10,000 gallons gelled lease	Elinebry oil as follows:  and dump 2 sacks cement on to  erval 5770 - 5900.  Idize perfs with 500 gals 15%  o oil containing 1/40% Adomite	
It is proposed to abando  1. Kill well and po  2. Set CI EP at app  3. Test plug and ed  4. Run GR-N log. It  5. Run 3-1/2" frac  NEA and frac with  per gal and 1 to  6. Swab and test.  7. Pull frac tubing	on Drinkard and recomplete in all tubing. proximately 6475' on wire line asing with 1000%. Perforate Blinebry in the intertubing with FB packer and act th 20,000 gallons gelled lease 3% SPG.  g and FB packer and run 2-3/8'	Elinebry oil as follows:  and dump 2 sacks cement on to  erval 5770 - 5900.  Idize perfs with 500 gals 15%  oil containing 1/40 Adomite  tubing and place well on  Gulf Oil Corporation  Company or Operator	
It is proposed to abando  1. Kill well and po  2. Set CI EP at app  3. Test plug and ed  4. Run OR-N log. If  5. Run 3-1/2" frac  NEA and frac with  per gal and 1 to  6. Swab and test.  7. Pull frac tubing  production.	on Drinkard and recomplete in all tubing.  proximately 6475' on wire line asing with 1000%.  Perforate Blinebry in the intention of tubing with FB packer and act th 20,000 gallons gelled lease of 3% SPG.  g and FB packer and run 2-3/8'  Position	Elinebry oil as follows:  and dump 2 sacks cement on to  erval 5770 - 5900.  Idize perfs with 500 gals 15%  oil containing 1/40% Adomite  tubing and place well on	