

## U.S. CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease

State ☐Fee ☒

5. State Oil &amp; Gas Lease No.

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
 USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Gulf Oil Corporation	8. Farm or Lease Name Eunice King
3. Address of Operator P. O. Box 670, Hobbs, NM 88240	9. Well No. 19
4. Location of Well UNIT LETTER <u>C</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>28</u> TOWNSHIP <u>21S</u> RANGE <u>37E</u> NMPM.	10. Field and Pool, or Wildcat Blinebry-Paddock
15. Elevation (Show whether DF, RT, GR, etc.) 3466' GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
 NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
 TEMPORARILY ABANDON ☐  
 PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐  
 CHANGE PLANS ☐

OTHER P&A Paddock, equip Blinebry to pump ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
 COMMENCE DRILLING OPNS. ☐  
 CASING TEST AND CEMENT JOBS ☐  
 OTHER ☐

ALTERING CASING ☐  
 PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

POH with production equipment., Push packer at 5235' to bottom. Set RBP at 5750', cap with 10' frac sand. Set cement retainer at 5050', test tubing 3000#. Pump fresh water, caustic water and 100 sacks Class "C" with Halad 9 & CFR-2. Squeeze off 5114'-5182'. Drill up cement and cement retainer. Test squeezed perfs 500#. Reverse sand off RBP and POH. Acidize with 750 gals 15% NEA. Swab. Run production equipment. Set pumping unit; hang off. Test well.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED RDP PithTITLE Area EngineerDATE 5-10-82APPROVED BY ORIGINAL SIGNED BY

TITLE

DATE MAY 12 1982

CONDITIONS OF APPROVAL, IF ANY: