NO. OF COPIES RECEIVED	NEW	MEXICO OIL CONSER	VATION COMMISSION		orm C-101 levised 1-1-	65	
FILE						e Type of Lease	
U.S.G.S.					STATE	FEE X	
OPERATOR					5. State Oil	à Gas Lease No.	
	<u>.</u>			k	<u>IIIII</u>		
	N FOR PERMIT TO	DRILL, DEEPEN, C	OR PLUG BACK				
la. Type of Work				[7. Unit Agre	eement Name	
b. Type of Well DRILL		DEEPEN	PLUG B	аск [Х] -	8. Farm or 1	.ease Name	
OIL XX GAS WELL	ZONE	Cordelia Hardy					
2. Name of Operator	T 0 N M T		ZONE WUL		9. Well No.		
Mobil Producing	IX. & N.M., Inc	•					
<u>P.O.Box 633, Mic</u>	11and Ty 79702			1	10. Field and Pool, or Wildcat Penrose Skelly Grayburg		
4. Location of Well UNIT LETTE	$E_{\rm R}$ E Loc	ATED 2310 FE	ET FROM THE North	LINE		Skerry Grayburg	
				k k	IIIII		
AND 330 FEET FROM	THE West	E OF SEC. 29 TH	(P. 275 RGE. 3	7E NMPM	12. County	mhhhhhh	
					Lea		
ΔΠΠΠΠΠΠΠ	///////////////////////////////////////	hittittittitti	tittittittitti	ttttttt	חווח	ttittittittittittittitti	
		//////////////////////////////////////		9A. Formation		20. Rotary or C.T.	
21. Elevations (Show whether DF,	RT, etc.) 21A. Kind	& Status Plug. Bond 21	5100'	Grayburg		Workover	
3483-Ground	1	n File	Unknown		22. nppios	ASAP	
23.	<u></u>	ROPOSED CASING AND					
·			· · · · · · · · · · · · · · · · · · ·				
SIZE OF HOLE Existing 11"	SIZE OF CASING	WEIGHT PER FOOT			CEMENT	EST. TOP	
<u>8 1/4"</u>	7"	36# 24#	<u>1344'</u> 3625'	<u>310</u> 175		Surface 2070'	
6 1/8"	4 1/2"	11.6#	5400'		200	1. 5400 to 3377	
				2nd Stg.		2. DV tool at 3377' to Surface	
The subject well is We are requesting pe complete in the Penr	ermission to ab	bandon on the Pa	ddock, plug bad	ck to 510 is attac	0' and hed.		
IN ABOVE SPACE DESCRIBE PR	ER PROGRAM, 1F ANY.		·	PRESENT PROD	UCTIVE 2.0NE	AND PROPOSED NEW PRODUC-	
I hereby certify that the informatic	1						
Signed C.a. Mo	ore for	_{Title} Environment	al & Regulatory	/ Manage _Ø	ue 05/1	3/87	
	State Use)						
Orlg. Sig Paul B	med by				a		
APPROVED BY Geolo	gist	TITLE			ате <u></u>	1061 C T THI	
CONDITIONS OF APPROVAL, IF	ANY:						





STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

THE CONSERVATION DIVISIO

P.O. BOX 2088 SANTA FE, NEW MEXICO 87501

Form C-102 Revised 10-1-78

	۸	Il distances must be fro	m the outer bound	dartes of the	Section.	
Operator		1	_ease			Well No.
	ucing TX & N.M., I		ordelia Ha			1
Unit Letter		militip C	Range	1	iunty (
E	29 21	2	375		Lea	
Actual Feature Loc 330		<u>.</u>	2310		Nonth	
Ground Level Elev.	feet from the WEST Froducing Formation	Hne and	 Pool	feet fro	m the North	Ine
3483	Grayburg	4	Penrose Sk	ellv		Dedicated Acreoge: 40
	e acreage dedicated t	l		······		Acres
2. If more th						thereof (both as to working
	ommunitization, unitiz		.etc?		e the interests o	f all owners been consoli-
this form il No allowab forced-pool	necessary.) le will be assigned to	the well until all in til a non-standard u	iterests have init, eliminati	been cons ng such in	olidated (by con terests, has beer	ated. (Use reverse side of imunitization, unitization. approved by the Division.
						CERTIFICATION
23.0	1 1 1		1		tained he best of m	certify that the information con- rein is true and complete to the y knowledge and belief. 2720AUC RAD
					Name	Sweeney
<u>330'</u> _1					Env. Company Mobil Pr Date	& Reg. Manager oducing Tx. & N.M., In 13, 1987
	T-21-S	29 R-37-Ė	· 		shown on notes of under ny Is true a	certily that the well location this plat was platted from field actual surveys made by me or supervision, and that the same and correct to the best of my and belief.
		· · · · · · · · · · · · · · · · · · ·			Date Survey	ed
	1 1 1		T T T		Registered F and/or Land	rolessional Engineer Survéyar
330 (40 60	1.320 1080 1010 2310	•	12/10 10/00	-00		o.

RECOMMENDED WORK PROCEDURE

LEASE: CORDELIA HARDYWELL NO: 1ANNULAR FLUID PRIOR TO WORKOVER:
FORMATION FLUIDSW/O FLUID TO BE USED:
2% KCL WTR

PLEASE CONTACT OPERATIONS ENGR. IN HOBBS (393-9186) 24 HOURS PRIOR TO MIRU

- 1. MIRU.
- 2. POH w/ RODS & PUMP.
- 3. NU BOPS. RELEASE TAC & POH w/ 2-3/8" TBG.
- 4. MIRU WIRELINE CO. RIH w/ GAUGE RING & JUNK BASKET TO 5140. POH.
- 5. RIH w/ 4-1/2" 11.6# CIBP & SET @ 5100'. CAP w/ 35' CMT. POH.
- 6. RIH w/ 2-3/8" TBG TO 5000' & CIRC HOLE w/ 2% KCL WTR.
- 7. TEST CASING TO 1000 PSIG. POH.
- 8. RIH w/ GAMMA RAY, COMPENSATED NEUTRON, & CCL TOOLS & LOG FROM 3700 TO 2000'. POH.
- 9. RIH w/ 3-1/8" CSG GUN & PERFORATE THE PENROSE SKELLY GRAYBURG FROM 3473 TO 3597 (EXACT PERFS TO BE DETERMINED FROM LOG BEING RUN), 2 JSPF, ZERO DEGREE PHASING - DECENTRALIZED. POH.
- 10. RIH w/ 4-1/2" TREATING PKR ON 2-3/8" TBG TO 3600 & SPOT 100 GAL NEFE 15% HCL ACROSS PERFS.
- 11. PU & SET PKR @ 3350'.
- 12. TEST/HOLD BACKSIDE TO 500 PSIG. ACIDIZE PENROSE FORMATION w/ 2000 gal NEFE 15% HCL @ 4-5 BPM & RCNBS (80% EXCESS), MAX 4000 PSIG TP. FLUSH w/ 15 BBLS 2% KCL WTR.
- 13. OBTAIN ISIP @ 5, 10, & 15 MIN.
- 14. SWAB WELL UNTIL LOAD IS RECOVERED. POH.
- 15. RIH w/ MA, SN (SET @ 3640'), 9 JTS 2-3/8" TBG, TAC, & FIH w/ 2-3/8" TBG.

RECOMMENDED WORK PROCEDURE CONT. P. 2

- 16. RIH w/ 1.5" * 20' PUMP, 66% 3/4" STEEL RODS, 34% 7/8" STEEL.
- 17. LOAD TBG & TEST PUMP ACTION.
- 18. RDMO PULLING UNIT.
- 19. TEST & EVALUATE FOR FRACTURE STIMULATION. IF FRACTURE STIMULATION IS NEEDED, CONTACT OPERATIONS ENGINEERING FOR PROCEDURE.

KA CARWILE

.



•

٠