

Oil Conservation Division
Attn. Jerry Sexton
July 20, 1993

Dear Sir

As per our conversation the morning of July 20, Chevron submits this Packer Leakage Test on our Central Drinkard Unit # 159 and Mobil's C. Hardy # 6. We feel we have corrected our downhole problem that prevented this test from being filed at the proper time, but we have experienced difficulties containing this much pressure through our surface pumping connections. I have included a copy of our well service report and a copy of the work ticket detailing the repair procedure used. Please advise if this test does not meet your requirements. If you have any helpful suggestions I would really appreciate them.

Thank You



J. R. (Ray) Smith
Production Specialist
P. O. Box 688
Eunice, New Mexico 88231
Ph. 397-8770 Ext. 231