NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

NOTICE OF INTENTION TO CHANGE PLANS	NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTE TO DRILL DEEPE		
Notice of Intention to Plug Well	Notice of Intention to Plug Back	x	Notice of Inte to Set Liner	NTION	
Notice of Intention to Squeeze	Notice of Intention to Acidize		Notice of Inte to Shoot (Nite		
Notice of Intention to Gun Perforate	NOTIOE OF INTENTION (Other)		Notice of Inte (Other)	NTION	
OIL CON SERVATION COMMIS S Santa Fe, New Mexico	Hobbs, New Mexico	0	Nar	ch 22, 196 (Date)	51
Gentlemen:		_			
	on to do certain work as described below a	it the			17
Oil Company	D. Hardy		Well No	in	II (Unit)
SE 1/4 NE 1/4 of Sec.	Operator) 29 T. 218 R. 37E	- 	PB Hare Pool	to Wants	Abo Pool
(40-acre Subdivision)		-		t i se ta	Her Just
Pull rods and tubing a Run gauge ring to 7800 Set CI BP @ 7550' w/1 Perforate 4 holes/ft f	sx cmt on top. rom 7446-681 and intervals	LES AND	REGULATIONS)		tst tbg and
Pull rods and tubing a Run gauge ring to 7800 Set CI BP @ 7550' w/l Perforate 4 holes/ft f Run 2 3/8" tbg with re CI BP to 3500#. Reset Treat lower perforatio Swab to clean up and t Run plug into BP4, Un- Treat upper perfs down Swab to clean up and t	OLLOW INSTRUCTIONS IN THE RU nd install BOP. '. sx cmt on top. rom 7446-68' and intervals I trievable Brown BP4 pkr and BP4 @ approx 7400'. ns w/5000 gals 15% NE acid. est. J from BP4. tbg w/6000 gals 15% NE acid est. tions are non-commercial, se	LES AND between set @ a d in sta	REGULATIONS) 7140'-7280'. approx 7475'.	Pressure N balls.	-
Pull rods and tubing a Run gauge ring to 7800 Set CI BP @ 7550' w/l Perforate 4 holes/ft f Run 2 3/8" tbg with re CI BP to 3500#. Reset Treat lower perforatio Swab to clean up and t Run plug into BP4, Un- Treat upper perfs down Swab to clean up and t In event lower perfora	DLLOW INSTRUCTIONS IN THE RU nd install BOP. ". sx cmt on top. rom 71416-68" and intervals I trievable Brown BP4 pkr and BP4 @ approx 7400". ns w/5000 gals 15% NE acid. est. J from BP4. tbg w/6000 gals 15% NE acid est. tions are non-commercial, so By	LES AND between set @ s d in sta et CI EF	REGULATIONS) 7140'-7280'. approx 7475'. ages using RC at approx 7 continent 0 company or Op	Pressure N balls. 400' w/l :	sx cement of
Pull rods and tubing a Run gauge ring to 7800 Set CI BP @ 7550' w/l Perforate 4 holes/ft f: Run 2 3/8" tbg with re CI BP to 3500#. Reset Treat lower perforatio Swab to clean up and t Run plug into BP4, Un- Treat upper perfs down Swab to clean up and t In event lower perfora Put well on production Approved OIL CONSERVATION COMMIS	OLLOW INSTRUCTIONS IN THE RU nd install BOP. ". sx cmt on top. rom 7446-68' and intervals I trievable Brown BP4 pkr and BP4 @ approx 7400'. ns w/5000 gals 15% NE acid. est. J from BP4. tbg w/6000 gals 15% ME acid est. tions are non-commercial, so By	LES AND between set @ s d in sta et CI EF nref Mic R. E Dist Send	REGULATIONS) 7140'-7280'. approx 7475'. ages using RC e at approx 7 d Continent O	Pressure N balls. 400' w/l : hil Company	sx cement or

12