10

NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

مر ورم مرغد الأرب MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		Notice of Intention to Drill Deeper	
NOTICE OF INTENTION TO PLUG WELL		Notice of Intention to Plug Back		Notice of Intention to Set Liner	
Notice of Intention to Squeeze		Notice of Intention to Acidize	X	Notice of Intention to Shoot (Nitro)	
Notice of Intention to Gun Perforate	I	Notice of Intention (Other)		Notice of Intention (Other)	

OIL CONSERVATION COMMISSION SANTA FE, NEW MEXICO

Bunice, New Mexico

May 27, 1959

Address Box 988, Eunice, New Mexico

Gentlemen:

By

Title

WATTTA' A	. Penrose,	Inc.	State A		in
W 1/4 NW	(Company or Operato	^{ar)} , T. 218	, R. 375	Penrose-Sk	elly P
Tee	-	ounty.			
			PROPOSED PLAN		
	•		IN THE RULES AN	D REGULATIONS)	
e propose . Run gamme	to treat a	s ioiiows: ron collar l	og from TD	792' to 2600'.	
. Set dril	lable brid	ge plug at 3	605' with Ca	al-seal on top	of plug
to give	10 [†] fill a	bove plug.	L shate new	foot from 3525	t to 35651.
\neq Load not Run 3 [#] t	ubing with	packer and	holddown.		
. Circulat	e 500 gals	acid to av	ot and break	c down formatio	n.
		A MAR AN AL			
.Treat per	forations	with 10,000	gals. Petro-	-gel and 10,000	# to 20,000#
Treat per of 2 9/4 0	forations sand.	with 10,000	gals. Petro-	-gel and 10,000	# to 20,000#
•.Treat per of 2 9 /40 •. Allow we producti	forations) sand. 11 to go c ion packer	with 10,000 n vacuum and in well.	gals. Petro-	-gel and 10,000 ping; run 2 [#] tu	# to 20,000#
of 2 9/4 0 of 2 9/4 0 Allow we producti	forations) sand. 11 to go c ion packer	with 10,000 n vacuum and in well.	gals. Petro-	-gel and 10,000	# to 20,000#
o.Treat per of 2 Q/4 0 . Allow we	forations) sand. 11 to go c ion packer	with 10,000 n vacuum and in well.	gals. Petro-	-gel and 10,000	# to 20,000#
of 2 9/4 0 of 2 9/4 0 Allow we producti	forations) sand. 11 to go c ion packer	with 10,000 n vacuum and in well.	gals. Petro- I pull 3 ^m tu	-gel and 10,000 bing; run 2" tu	# to 20,000# bing and
o.Treat per of 20/40 . Allow we producti . Swab wel	forations sand. It to go o on packer I into pro	with 10,000 n vacuum and in well.	gals. Petro- I pull 3 ^m tu	-gel and 10,000	# to 20,000# bing and
o.Treat per of 2 9 /40 7. Allow we producti 3. Swab wel	forations sand. It to go o on packer I into pro	with 10,000 n vacuum and in well. duction.	gals. Petro- I pull 3 ^m tu	-gel and 10,000 bing; run 2" tu	# to 20,000# bing and
of 29/40 • Allow we producti • Swab wel	forations sand. It to go o on packer I into pro	with 10,000 n vacuum and in well. duction.	gals. Petro- i pull 3" tu Nevil By	-gel and 10,000 ping; run 2" tu G. Penrose, Company or Operato	# to 20,000# bing and Inc.
of 29/40 of 29/40 . Allow we producti . Swab wel	forations sand. It to go o on packer i into pro	with 10,000 n vacuum and in well. duction.	gals. Petro- i pull 3" tu Nevil By	-gel and 10,000 bing; run 2" tu G. Penrose, Company or Operato	# to 20,000# bing and Inc.