

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. Unknown
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Paddock (San Angelo) Unit
8. Well No. 2
9. Pool name or Wildcat Paddock
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
2. Name of Operator Exxon Corporation
3. Address of Operator P.O. Box 1600, Midland, TX 79702
4. Well Location Unit Letter P : 764 Feet From The South Line and 554 Feet From The East Line Section 34 Township 21S Range 37E NMMP Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
12-30-88 MIRU
12-31&1-1-89 SI
1-2 thru 4 Fish
1-5 Clean out to 5180
1-6 Pump 119 bbls of 15% HCL and POOH w/ PKR., well began to flow. Shut BOP and nipple below BOP failed. Attempt to blow down well to replace nipple.
1-7 Kill well w/ brine and replace nipple.
1-8 SI
1-9 Fill OH w/ sand
1-10 Perf 5030 - 5057, Acidize w/ 8000 gal of 15% HCL
1-11 Clean out sand in OH
1-12 & 13 Set PKR @ 4955 and swab
1-14 thru 2-3 Well testing and SI
2-4 4 pt test run

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Stephen Johnson TITLE Administrative Specialist DATE 2-28-89
TYPE OR PRINT NAME Stephen Johnson (915) 688-7548 TELEPHONE NO.

(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

MAR 7 1989

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

RECEIVED

MAR 6 1966

OLD
MORRIS OFFICE