

COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		5. State Oil & Gas Lease No.
2. Name of Operator EXXON CORPORATION		7. Unit Agreement Name
3. Address of Operator P.O. BOX 1600, MIDLAND, TEXAS 79701		8. Farm or Lease Name F.F. HARDISON "B"
4. Location of Well UNIT LETTER G 1980 FEET FROM THE EAST LINE AND 2015 FEET FROM THE NORTH LINE, SECTION 34 TOWNSHIP 21-S RANGE 37-E NMPM.		9. Well No. 3
15. Elevation (Show whether DF, RT, GR, etc.) 3429 D.F.		10. Field and Pool, or Wildcat DRINKARD
12. County LEA		

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER PERFORATE AND FRAC <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER _____ <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

THE PROCEDURE WILL BE TO KILL WELL AND PULL PRODUCTION EQUIPMENT. GUIBERSON PACKER SET AT 6407'. PACKER TYPE OR MODEL NO. UNKNOWN. PACKER WAS SET IN 1200# TENSION. RUN A GRIN LOG AND COLLAR LOCATOR FROM 6602' PBD TO 3800'. PERFORATE THE INTERVALS PICKED BY GEOLOGIST WITH A JET CASING GUN. USE LUBRICATOR WHEN PERFORATING. RUN A RETRIEVABLE BRIDGE PLUG AND TREATING PACKER ON 2 7/8" WORKSTRING. A SUPPLEMENTAL PROCEDURE WILL BE PREPARED TO ACID FRAC THE NEWLY PERFORATED INTERVAL AND OLD INTERVAL.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED **A. L. Clemmer** TITLE **UNIT HEAD** DATE **12-18-75**

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: