Form 3160-5 (June 1990)			
	DEPARTMENT	ED STATES OF THE INTERIOR	FORM APPROVED Budget Bureau No. 1004-0135
		ND MANAGEMENT	Expires: March 31, 1993
			5. Lease Designation and Serial No.
	SUNDRY NOTICES A	ND REPORTS ON WELLS	LC- 032096B 6. If Indian, Allottee or Tribe Name
Do not use this form for prop	posals to drill or to deepe	en or reentry to a different reservoir.	o. Il Indian, Adoctee or Fride Name
Use "APPLICATIO	N FOR PERMIT " for su	ch proposals	7. If Unit or CA, Agreement Designation
	SUBMIT IN T	RIPLICATE	
1 Type of Well X Oil Gas	SWD		
	ther		8. Well Name and No.
·			Lockhart B35 Well # 3
CONOCO INC. 3 Address and Telephone No.			9. API Well No.
10 DESTA DR. STE 100W, 4. Location of Well (Footage, Sec., T., R	MIDLAND, TX. 79705 (91	5) 686 - 5424	30-025-07034 10. Field and Pool, or Exploratory Area
			Tubb Oil & Gas
SURFACE: 1980' FNL & 66 TD: Same	0" FEL of Section 35, 1-21S,	, R-37E Unit Letter 'H'	11. County or Parish, State
			LEA, NM
		TE NATURE OF NOTICE, REPORT, (
TYPE OF SUBMIS	51UN		N
Notice of Intent		Abandonment	Change of Plans
X o have a lo		. Recompletion	New Construction
X Subsequent Report	t	Plugging Back	Non-Routine Fracturing
	• Nation	Casing Repair	Water Shut-Off
Final Abandonmen		Altering Casing	Conversion to Injection
		X Other Unplug & reset tubing depth	Dispose Water
1-20-96 MIRU. Bled well	down. Picked up 40 rods ar	details, and give pertinent dates, including estimated date e vertical depths for all markers and zones pertinent to the nd paraffin knife and RIH. Could not get past 1	Completion or Recompletion Report and Log form.) e of starting any proposed work. If well is is work.)*
1-20-96 MIRU. Bled well 1-22-96 Hooked up kill tr 1-23-96 RIH with remain and casing scra 1-24-96 RIH w/ 245 rods	I down. Picked up 40 rods ar ruck. Killed well. NDWH, NU ing tubing. Picked up 18 jts. aper. RIH w/ tubing testing g and pump. Spaced well out	details, and give pertinent dates, including estimated date e vertical depths for all markers and zones pertinent to the nd paraffin knife and RIH. Could not get past 1 BOP, POOH w/ tubing (5590'). Picked up casi Tagged bottom at 6269'. Rigged up hot oil tru	Completion or Recompletion Report and Log form.) e of starting any proposed work. If well is is work.)* 1100' . SION. ing scraper and RIH w/ tubing and scraper. ick, hot watered tubing. POOH w/ tubing
1-20-96 MIRU. Bled well 1-22-96 Hooked up kill tr 1-23-96 RIH with remain and casing scra 1-24-96 RIH w/ 245 rods Blinebry perfs:	I down. Picked up 40 rods ar ruck. Killed well. NDWH, NU ing tubing. Picked up 18 jts. aper. RIH w/ tubing testing g and pump. Spaced well out 5502' - 5908'	details, and give pertinent dates, including estimated date e vertical depths for all markers and zones pertinent to the nd paraffin knife and RIH. Could not get past 1 BOP. POOH w/ tubing (5590'). Picked up casi Tagged bottom at 6269'. Rigged up hot oil tru oing in (6239').	Completion or Recompletion Report and Log form.) e of starting any proposed work. If well is is work.)* 1100' . SION. ing scraper and RIH w/ tubing and scraper. ick, hot watered tubing. POOH w/ tubing
1-20-96 MIRU. Bled well 1-22-96 Hooked up kill tr 1-23-96 RIH with remain and casing scra 1-24-96 RIH w/ 245 rods Blinebry perfs: Tubb perfs: 606	I down. Picked up 40 rods ar ruck. Killed well. NDWH, NU ing tubing. Picked up 18 jts. aper. RIH w/ tubing testing g and pump. Spaced well out 5502' - 5908'	details, and give pertinent dates, including estimated date e vertical depths for all markers and zones pertinent to the nd paraffin knife and RIH. Could not get past 1 BOP. POOH w/ tubing (5590'). Picked up casi Tagged bottom at 6269'. Rigged up hot oil tru oing in (6239').	Completion or Recompletion Report and Log form.) e of starting any proposed work. If well is is work.)* 1100' . SION. ing scraper and RIH w/ tubing and scraper. ick, hot watered tubing. POOH w/ tubing
1-20-96 MIRU. Bled well 1-22-96 Hooked up kill tr 1-23-96 RIH with remain and casing scra 1-24-96 RIH w/ 245 rods Blinebry perfs: Tubb perfs: 606	I down. Picked up 40 rods ar ruck. Killed well. NDWH, NU ing tubing. Picked up 18 jts. aper. RIH w/ tubing testing g and pump. Spaced well out 5502' - 5908'	details, and give pertinent dates, including estimated date e vertical depths for all markers and zones pertinent to the nd paraffin knife and RIH. Could not get past 1 BOP. POOH w/ tubing (5590'). Picked up casi Tagged bottom at 6269'. Rigged up hot oil tru oing in (6239').	Completion or Recompletion Report and Log form.) e of starting any proposed work. If well is is work.)* 1100' . SION. ing scraper and RIH w/ tubing and scraper. ick, hot watered tubing. POOH w/ tubing
1-20-96 MIRU. Bled well 1-22-96 Hooked up kill tr 1-23-96 RIH with remain and casing scra 1-24-96 RIH w/ 245 rods Blinebry perfs: Tubb perfs: 606	I down. Picked up 40 rods ar ruck. Killed well. NDWH, NU ing tubing. Picked up 18 jts. aper. RIH w/ tubing testing g and pump. Spaced well out 5502' - 5908'	details, and give pertinent dates, including estimated date e vertical depths for all markers and zones pertinent to the nd paraffin knife and RIH. Could not get past 1 BOP. POOH w/ tubing (5590'). Picked up casi Tagged bottom at 6269'. Rigged up hot oil tru oing in (6239').	Completion or Recompletion Report and Log form.) e of starting any proposed work. If well is is work.)* 1100' . SION. ing scraper and RIH w/ tubing and scraper. ick, hot watered tubing. POOH w/ tubing
1-20-96 MIRU. Bled well 1-22-96 Hooked up kill tr 1-23-96 RIH with remain and casing scra 1-24-96 RIH w/ 245 rods Blinebry perfs: Tubb perfs: 606	I down. Picked up 40 rods ar ruck. Killed well. NDWH, NU ing tubing. Picked up 18 jts. aper. RIH w/ tubing testing g and pump. Spaced well out 5502' - 5908'	details, and give pertinent dates, including estimated date e vertical depths for all markers and zones pertinent to the nd paraffin knife and RIH. Could not get past 1 BOP. POOH w/ tubing (5590'). Picked up casi Tagged bottom at 6269'. Rigged up hot oil tru oing in (6239').	Completion or Recompletion Report and Log form.) e of starting any proposed work. If well is is work.)* 1100' . SION. ing scraper and RIH w/ tubing and scraper. ick, hot watered tubing. POOH w/ tubing ged down.
1-20-96 MIRU. Bled well 1-22-96 Hooked up kill tr 1-23-96 RIH with remain and casing scra 1-24-96 RIH w/ 245 rods Blinebry perfs: Tubb perfs: 606	I down. Picked up 40 rods ar ruck. Killed well. NDWH, NU ing tubing. Picked up 18 jts. aper. RIH w/ tubing testing g and pump. Spaced well out 5502' - 5908'	details, and give pertinent dates, including estimated date e vertical depths for all markers and zones pertinent to the nd paraffin knife and RIH. Could not get past 1 BOP. POOH w/ tubing (5590'). Picked up casi Tagged bottom at 6269'. Rigged up hot oil tru oing in (6239').	Completion or Recompletion Report and Log form.) e of starting any proposed work. If well is is work.)* 1100' . SION. ing scraper and RIH w/ tubing and scraper. ick, hot watered tubing. POOH w/ tubing ged down.
1-20-96 MIRU. Bled well 1-22-96 Hooked up kill tr 1-23-96 RIH with remain and casing scra 1-24-96 RIH w/ 245 rods Blinebry perfs: Tubb perfs: 606 CIBP @ 6400' v	I down. Picked up 40 rods ar ruck. Killed well. NDWH, NU ing tubing. Picked up 18 jts. aper. RIH w/ tubing testing g and pump. Spaced well out 5502' - 5908'	details, and give pertinent dates, including estimated date e vertical depths for all markers and zones pertinent to the nd paraffin knife and RIH. Could not get past 1 BOP. POOH w/ tubing (5590'). Picked up casi Tagged bottom at 6269'. Rigged up hot oil tru oing in (6239').	Completion or Recompletion Report and Log form.) e of starting any proposed work. If well is is work.)* 1100' . SION. ing scraper and RIH w/ tubing and scraper. ick, hot watered tubing. POOH w/ tubing ged down.
 4. Thereby certify that the telegoing for the solution of the sol	idown. Picked up 40 rods ar ruck. Killed well. NDWH, NU ing tubing. Picked up 18 jts. aper. RIH w/ tubing testing g and pump. Spaced well out 5502' - 5908' i5' - 6225' w/ sand @ 6279'	details, and give pertinent dates, including estimated date e vertical depths for all markers and zones pertinent to the nd paraffin knife and RIH. Could not get past 1 BOP. POOH w/ tubing (5590'). Picked up casi Tagged bottom at 6269'. Rigged up hot oil tru oing in (6239').	Completion or Recompletion Report and Log form.) e of starting any proposed work. If well is is work.)* 1100' . SION. ing scraper and RIH w/ tubing and scraper. ick, hot watered tubing. POOH w/ tubing ged down.
 4. Thereby certify that the telegoing is the television of televi	idown. Picked up 40 rods ar ruck. Killed well. NDWH, NU ing tubing. Picked up 18 jts. aper. RIH w/ tubing testing g and pump. Spaced well out 5502' - 5908' i5' - 6225' w/ sand @ 6279'	details, and give pertinent dates, including estimated date e vertical depths for all markers and zones pertinent to the nd paraffin knife and RIH. Could not get past 1 BOP. POOH w/ tubing (5590'). Picked up casi Tagged bottom at 6269'. Rigged up hot oil tru oing in (6239'). t, loaded tubing tested pump. Tested OK. Rigg	Completion or Recompletion Report and Log form.) a of starting any proposed work. If well is is work.)* 1100' . SION. ing scraper and RIH w/ tubing and scraper. ick, hot watered tubing. POOH w/ tubing ged down.
 4. Thereby certify that the telegoing for the solution of the solutio	idown. Picked up 40 rods ar ruck. Killed well. NDWH, NU ing tubing. Picked up 18 jts. aper. RIH w/ tubing testing g and pump. Spaced well out 5502' - 5908' i5' - 6225' w/ sand @ 6279'	details, and give pertinent dates, including estimated date e vertical depths for all markers and zones pertinent to the nd paraffin knife and RIH. Could not get past 1 BOP. POOH w/ tubing (5590'). Picked up casi Tagged bottom at 6269'. Rigged up hot oil tru oing in (6239'). t, loaded tubing tested pump. Tested OK. Rigg	Completion or Recompletion Report and Log form.) a of starting any proposed work. If well is is work.)* 1100' . SION. ing scraper and RIH w/ tubing and scraper. ick, hot watered tubing. POOH w/ tubing ged down.
 1-20-96 MIRU. Bled well 1-22-96 Hooked up kill tr 1-23-96 RIH with remain and casing scra 1-24-96 RIH w/ 245 rods Blinebry perfs: Tubb perfs: 606 CIBP @ 6400' v CIBP @ 6400' v Signed Multi the telesting of the space for Federal or State office Approved by Conditions of approval, if any. 	I down. Picked up 40 rods ar ruck. Killed well. NDWH, NU ing tubing. Picked up 18 jts. aper. RIH w/ tubing testing g and pump. Spaced well out 5502' - 5908' 55' - 6225' w/ sand @ 6279'	details, and give pertinent dates, including estimated date e vertical depths for all markers and zones pertinent to the nd paraffin knife and RIH. Could not get past 1 BOP. POOH w/ tubing (5590'). Picked up casi Tagged bottom at 6269'. Rigged up hot oil tru oing in (6239'). t, loaded tubing tested pump. Tested OK. Rigg	Completion or Recompletion Report and Log form.) a) of starting any proposed work. If well is swork.)* 1100' . SION. ing scraper and RIH w/ tubing and scraper. ick, hot watered tubing. POOH w/ tubing ged down.

-

•



.
