

OF COPIES RECEIVED		
DISTRIBUTION		
FAFE		
E		
S.G.S.		
AND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

3-NMOCC
1-File

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State XX	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator GETTY OIL COMPANY	8. Farm or Lease Name STATE "Q"
3. Address of Operator P.O. BOX 249, HOBBS, NEW MEXICO 88240	9. Well No. 1
4. Location of Well UNIT LETTER N , 660 FEET FROM THE SOUTH LINE AND 1980 FEET FROM THE WEST LINE, SECTION 36 TOWNSHIP 21 RANGE 37 NMPM.	10. Field and Pool, or Wildcat TUBB & BLINEBRY DUAL
15. Elevation (Show whether DF, RT, GR, etc.) 3376 D.F.	12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The well is presently completed as a Blinebry Gas and Tubb Gas dual. The Blinebry is presently completed at 5520-60 and the Tubb Gas at 6140-75.

PROPOSED WORK: Drill out Model "D" packer @ 6010'.

Additionally perforate Tubb from 6015 to 6296 (18 Perforations)

Acidize and frac same interval.

Run Model "D" Packer and set @ 5950'.

Additionally perforate Blinebry from 5618 to 5879' (23 Perforations)

Acidize and frac same interval.

Rerun completion equipment and complete as a dual in the Blinebry and Tubb.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed By

SIGNED **C. L. Wade:** **C. L. WADE** TITLE **AREA SUPERINTENDENT** DATE **11-21-74**

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

MRR/bh

RECEIVED

MAY 22 1974

CALIFORNIA CONSERVATION COMM.
RIVERS, R. M.