Form 3160-5	NU 1	ED STATES	FORM APPRO	VED
(.' ine 1990)	DEPARTMENT	OF THE INTERIOR	Budget Bureau No 10	004-0135
	BUREAU OF LA	ND MANAGEMENT	Expires. March 31 5 Lease Designation an	
	SUNDRY NOTICES AN	ID REPORTS ON WELLS	6. If Indian, Allottee or T	·· · · · · · · · · · · · · · · · · ·
Do not use this form for prop	osals to drill or to deepe	n or reentry to a different reservoir.		
Use "APPLICATION	FOR PERMIT " for suc	ch proposals	7. If Unit of CA. Agreem	ent Designation
	SUBMIT IN TH	RIPLICATE	State Chine Ching Bellin	
1 Type of Well				
Oil Gas X IN Weil Well Oth Name of Operator	NJECTION er		8. Well Name and No SEMU PERMIAN	
CONOCO INC.			WELL # 76	N
Address and Telephone No	··· ·····		9. API Well No.	
10 DESTA DR. STE 100W,	MIDLAND, TX. 79705 (91)	5) 686 - 5424	30-025 10. Field and Pool, or Ex	
4 Location of Well (Footage, Sec. T., R., M. or Survey Description)			SKAGGS GRAY	
SURFACE: 660' FSL & 660' FWL, SEC. 18, T 20S, R 38E, UNIT LTR 'M' TD: Same		BE, UNITLTR 'M'	11. County or Parish, St	
			LEA, N	м
		TE NATURE OF NOTICE, REPORT, OF	R OTHER DATA	·-··
TYPE OF SUBMISS	ION	TYPE OF ACTION		
Notice of Intent	· · · · · · · · · · · · · · · · · · ·	Abandonment	Change of Plans	
		Recompletion	New Construction	
X Subsequent Report		Plugging Back	Non-Routine Fractur	ring
		Casing Repair	Water Shut-Off	
Final Abandonment I	Notice	Attering Casing	Conversion to Inject	ion
		X Other	Dispose Water	
			aller E	
uirectionally drilled, give subsurfac	rod. tubing. Lay down tubin	CI. out, add perfs, acidize details, and give pertinent dates, including estimated date of e vertical depths for all markers and zones pertinent to this w g due to corrosion.	vork.)*	vri and Log form ) well is
11-1-95 MIRU. POOH w/ p 11-2-95 GIH w/w/s Cleane Set packer at 365 11-3-95 Rig up BJ and acio	rod. tubing. Lay down tubin rod. tubing. Lay down tubin rd out to 3929'. POOH w/w/ 3'. dize Grayburg w/5500 gals.	CI. out, add perfs, acidize defails, and give pertinent dates. including estimated date of a vertical depths for all markers and zones pertinent to this w og due to corrosion. s. D.C.'s and bit. RU WL and reperforate Graybu 15% NEFE HCL, 5100# Rock Salt. Shut down f	Completion or Recompletion Repo Starting any proposed work of work.)* urg from 3704'-3735' 4 sp	well is
11-1-95 MIRU. POOH w/ p 11-2-95 GIH w/w/s Cleane Set packer at 365 11-3-95 Rig up BJ and acid	rod. tubing. Lay down tubin rod. tubing. Lay down tubin rd out to 3929'. POOH w/w/ 3'. dize Grayburg w/5500 gals.	CI. out, add perfs, acidize defails, and give pertinent dates, including estimated date of a vertical depths for all markers and zones pertinent to this w og due to corrosion. s, D.C.'s and bit. RU WL and reperforate Graybu	Completion or Recompletion Repo Starting any proposed work of work.)* urg from 3704'-3735' 4 sp	well is
11-1-95 MIRU. POOH w/ p 11-2-95 GIH w/w/s Cleane Set packer at 365 11-3-95 Rig up BJ and acid	rod. tubing. Lay down tubin rod. tubing. Lay down tubin rd out to 3929'. POOH w/w/ 3'. dize Grayburg w/5500 gals.	CI. out, add perfs, acidize defails, and give pertinent dates. including estimated date of a vertical depths for all markers and zones pertinent to this w og due to corrosion. s. D.C.'s and bit. RU WL and reperforate Graybu 15% NEFE HCL, 5100# Rock Salt. Shut down f	Completion or Recompletion Repo Starting any proposed work of work.)* urg from 3704'-3735' 4 sp	well is
11-1-95 MIRU. POOH w/ p 11-2-95 GIH w/w/s Cleane Set packer at 365 11-3-95 Rig up BJ and acid	rod. tubing. Lay down tubin rod. tubing. Lay down tubin rd out to 3929'. POOH w/w/ 3'. dize Grayburg w/5500 gals.	CI. out, add perfs, acidize defails, and give pertinent dates. including estimated date of a vertical depths for all markers and zones pertinent to this w og due to corrosion. s. D.C.'s and bit. RU WL and reperforate Graybu 15% NEFE HCL, 5100# Rock Salt. Shut down f	Completion or Recompletion Repo Starting any proposed work of work.)* urg from 3704'-3735' 4 sp	well is
11-1-95 MIRU. POOH w/ p 11-2-95 GIH w/w/s Cleane Set packer at 365 11-3-95 Rig up BJ and acid	rod. tubing. Lay down tubin rod. tubing. Lay down tubin rd out to 3929'. POOH w/w/ 3'. dize Grayburg w/5500 gals.	CI. out, add perfs, acidize defails, and give pertinent dates. including estimated date of a vertical depths for all markers and zones pertinent to this w og due to corrosion. s. D.C.'s and bit. RU WL and reperforate Graybu 15% NEFE HCL, 5100# Rock Salt. Shut down f	Completion or Recompletion Repo Starting any proposed work of work.)* urg from 3704'-3735' 4 sp	well is
11-1-95 MIRU. POOH w/ p 11-2-95 GIH w/w/s Cleane Set packer at 365 11-3-95 Rig up BJ and acid	rod. tubing. Lay down tubin rod. tubing. Lay down tubin rd out to 3929'. POOH w/w/ 3'. dize Grayburg w/5500 gals.	CI. out, add perfs, acidize defails, and give pertinent dates. including estimated date of a vertical depths for all markers and zones pertinent to this w og due to corrosion. s. D.C.'s and bit. RU WL and reperforate Graybu 15% NEFE HCL, 5100# Rock Salt. Shut down f	Completion or Recompletion Repo Starting any proposed work of work.)* urg from 3704'-3735' 4 sp	well is
11-1-95 MIRU. POOH w/ p 11-2-95 GIH w/w/s Cleane Set packer at 365 11-3-95 Rig up BJ and acid	rod. tubing. Lay down tubin rod. tubing. Lay down tubin rd out to 3929'. POOH w/w/ 3'. dize Grayburg w/5500 gals.	CI. out, add perfs, acidize defails, and give pertinent dates. including estimated date of a vertical depths for all markers and zones pertinent to this w og due to corrosion. s. D.C.'s and bit. RU WL and reperforate Graybu 15% NEFE HCL, 5100# Rock Salt. Shut down f	Completion or Recompletion Repo Starting any proposed work of work.)* urg from 3704'-3735' 4 sp	well is
11-1-95 MIRU. POOH w/ p 11-2-95 GIH w/w/s Cleane Set packer at 365 11-3-95 Rig up BJ and acid	rod. tubing. Lay down tubin rod. tubing. Lay down tubin rd out to 3929'. POOH w/w/ 3'. dize Grayburg w/5500 gals.	CI. out, add perfs, acidize defails, and give pertinent dates. including estimated date of a vertical depths for all markers and zones pertinent to this w og due to corrosion. s. D.C.'s and bit. RU WL and reperforate Graybu 15% NEFE HCL, 5100# Rock Salt. Shut down f	Completion or Recompletion Repo Starting any proposed work of work.)* urg from 3704'-3735' 4 sp	of and Log form ) well is
11-1-95 MIRU. POOH w/ p 11-2-95 GIH w/w/s Cleane Set packer at 365 11-3-95 Rig up BJ and acid	rod. tubing. Lay down tubin rod. tubing. Lay down tubin rd out to 3929'. POOH w/w/ 3'. dize Grayburg w/5500 gals.	CI. out, add perfs, acidize defails, and give pertinent dates. including estimated date of a vertical depths for all markers and zones pertinent to this w og due to corrosion. s. D.C.'s and bit. RU WL and reperforate Graybu 15% NEFE HCL, 5100# Rock Salt. Shut down f	Completion or Recompletion Repo Starting any proposed work of work.)* urg from 3704'-3735' 4 sp	of and Log form ) well is
11-1-95 MIRU. POOH w/ p 11-2-95 GIH w/w/s Cleane Set packer at 365 11-3-95 Rig up BJ and acid	rod. tubing. Lay down tubin rod. tubing. Lay down tubin rd out to 3929'. POOH w/w/ 3'. dize Grayburg w/5500 gals.	CI. out, add perfs, acidize defails, and give pertinent dates. including estimated date of a vertical depths for all markers and zones pertinent to this w og due to corrosion. s. D.C.'s and bit. RU WL and reperforate Graybu 15% NEFE HCL, 5100# Rock Salt. Shut down f	Completion or Recompletion Repo Starting any proposed work of work.)* urg from 3704'-3735' 4 sp	of and Log form ) well is
11-1-95 MIRU. POOH w/ p 11-2-95 GIH w/w/s Cleane Set packer at 365 11-3-95 Rig up BJ and acid	rod. tubing. Lay down tubin rod. tubing. Lay down tubin rd out to 3929'. POOH w/w/ 3'. dize Grayburg w/5500 gals.	CI. out, add perfs, acidize defails, and give pertinent dates. including estimated date of a vertical depths for all markers and zones pertinent to this w og due to corrosion. s. D.C.'s and bit. RU WL and reperforate Graybu 15% NEFE HCL, 5100# Rock Salt. Shut down f	Completion or Recompletion Repo Starting any proposed work of work.)* urg from 3704'-3735' 4 sp	of and Log form ) well is
11-1-95 MIRU. POOH w/ p 11-2-95 GIH w/w/s Cleane Set packer at 365 11-3-95 Rig up BJ and acid	rod. tubing. Lay down tubin rod. tubing. Lay down tubin rd out to 3929'. POOH w/w/ 3'. dize Grayburg w/5500 gals.	Cl. out, add perfs, acidize details, and give pertinent dates. Including estimated date of a vertical depths for all markers and zones pertinent to this w or g due to corrosion. s, D.C.'s and bit. RU WL and reperforate Graybu 15% NEFE HCL, 5100# Rock Salt. Shut down f rculate packer fluid, set packer and run MIT.	Completion or Recompletion Repo Starting any proposed work of work.)* urg from 3704'-3735' 4 sp	of and Log form ) well is
11-1-95 MIRU. POOH w/ p 11-2-95 GIH w/w/s Cleane Set packer at 365 11-3-95 Rig up BJ and acid	rod. tubing. Lay down tubin rod. tubing. Lay down tubin rd out to 3929'. POOH w/w/ 3'. dize Grayburg w/5500 gals.	Cl. out, add perfs, acidize details, and give pertinent dates. Including estimated date of a vertical depths for all markers and zones pertinent to this w or g due to corrosion. s, D.C.'s and bit. RU WL and reperforate Graybu 15% NEFE HCL, 5100# Rock Salt. Shut down f rculate packer fluid, set packer and run MIT.	Completion of Recompletion Repo Fsharting any proposed work. If vork.)* urg from 3704'-3735' 4 sp for 1.5 hours. POOH w/w	of and Log form ) well is
11-1-95 MIRU. POOH w/ p 11-2-95 GIH w/w/s Cleane Set packer at 365 11-3-95 Rig up BJ and acio 11-6-95 RIH w/ prod. equip	e locations and measured and true rod. tubing. Lay down tubin ed out to 3929'. POOH w/w/ 3'. Jize Grayburg w/5500 gals. 9. Landed AD-1 at 3652'. Cit	Cl. out, add perfs, acidize details, and give pertinent dates. Including estimated date of a vertical depths for all markers and zones pertinent to this w or g due to corrosion. s, D.C.'s and bit. RU WL and reperforate Graybu 15% NEFE HCL, 5100# Rock Salt. Shut down f rculate packer fluid, set packer and run MIT.	Completion or Recompletion Repo Fstärting aniy proposed work. If vork.)* urg from 3704'-3735' 4 sp for 1.5 hours. POOH w/w	of and Log form ) well is
11-1-95 MIRU. POOH w/ p 11-2-95 GIH w/w/s Cleane Set packer at 365 11-3-95 Rig up BJ and acio 11-6-95 RIH w/ prod. equip	e locations and measured and true rod. tubing. Lay down tubin ed out to 3929'. POOH w/w/ 3'. Jize Grayburg w/5500 gals. b. Landed AD-1 at 3652'. Cit and a AD-1 at 3652'. Cit e and conject	Cl. out, add perfs, acidize defails, and give pertinent dates. Including estimated date of a vertical depths for all markers and zones pertinent to this w g due to corrosion. s, D.C.'s and bit. RU WL and reperforate Graybu 15% NEFE HCL, 5100# Rock Salt. Shut down f rculate packer fluid, set packer and run MIT.	Completion or Recompletion Repo Fstärting aniy proposed work. If vork.)* urg from 3704'-3735' 4 sp for 1.5 hours. POOH w/w	of and Log form ) well is
Thereby certify that the foregoing is true	e locations and measured and true rod. tubing. Lay down tubin ed out to 3929'. POOH w/w/ 3'. dize Grayburg w/5500 gals. b. Landed AD-1 at 3652'. Cil and a AD-1 at 3652'. Cil	Cl. out, add perfs, acidize defails, and give pertinent dates. Including estimated date of a vertical depths for all markers and zones pertinent to this w g due to corrosion. s. D.C.'s and bit. RU WL and reperforate Graybu 15% NEFE HCL, 5100# Rock Satt. Shut down f rculate packer fluid, set packer and run MIT.	Completion or Recompletion Repo Fsharting any proposed work. If urg from 3704'-3735' 4 sp for 1.5 hours. POOH w/w SJS	of. RIH w/pkr. and w/s. /s.
11-1-95 MIRU. POOH w/ p 11-2-95 GIH w/w/s Cleane Set packer at 365 11-3-95 Rig up BJ and acio 11-6-95 RIH w/ prod. equip	e locations and measured and true rod. tubing. Lay down tubin ed out to 3929'. POOH w/w/ 3'. dize Grayburg w/5500 gals. b. Landed AD-1 at 3652'. Cit Landed AD-1 at 3652'. Cit and conject	Cl. out, add perfs, acidize defails, and give pertinent dates. Including estimated date of a vertical depths for all markers and zones pertinent to this w g due to corrosion. s, D.C.'s and bit. RU WL and reperforate Graybu 15% NEFE HCL, 5100# Rock Salt. Shut down f rculate packer fluid, set packer and run MIT.	Completion of Recompletion Report Fsharting any proposed work. If urg from 3704'-3735' 4 sp for 1.5 hours. POOH w/w SJS	of and Log form ) well is
11-1-95 MIRU. POOH w/ p 11-2-95 GIH w/w/s Cleane Set packer at 365 11-3-95 Rig up BJ and acid 11-6-95 RIH w/ prod. equip 11-6-95 RIH w/ prod. equip Signed Mit Mitter foregoing is true Signed Mit Mitter office u	e locations and measured and true rod. tubing. Lay down tubin ed out to 3929'. POOH w/w/ 3'. dize Grayburg w/5500 gals. b. Landed AD-1 at 3652'. Cit Landed AD-1 at 3652'. Cit and conject	Cl. out, add perfs, acidize details, and give pertinent dates. Including estimated date of a vertical depths for all markers and zones pertinent to this w g due to corrosion. s. D.C.'s and bit. RU WL and reperforate Graybu 15% NEFE HCL, 5100# Rock Salt. Shut down f rculate packer fluid, set packer and run MIT. where the set of the s	Completion of Recompletion Report Fsharting any proposed work. If urg from 3704'-3735' 4 sp for 1.5 hours. POOH w/w SJS	of. RIH w/pkr. and w/s. /s.
Thereby certify that the foregoing is true Signed	e locations and measured and true rod. tubing. Lay down tubin ed out to 3929'. POOH w/w/ 3'. dize Grayburg w/5500 gals. b. Landed AD-1 at 3652'. Cit Landed AD-1 at 3652'. Cit and conject	Cl. out, add perfs, acidize details, and give pertinent dates. Including estimated date of a vertical depths for all markers and zones pertinent to this w g due to corrosion. s. D.C.'s and bit. RU WL and reperforate Graybu 15% NEFE HCL, 5100# Rock Salt. Shut down f rculate packer fluid, set packer and run MIT. where the set of the s	Completion of Recompletion Report Fsharting any proposed work. If urg from 3704'-3735' 4 sp for 1.5 hours. POOH w/w SJS	of. RIH w/pkr. and w/s. /s.
Thereby certify that the foregoing is true Signed Market for Federal or State office u	e locations and measured and true rod. tubing. Lay down tubin ed out to 3929'. POOH w/w/ 3'. dize Grayburg w/5500 gals. b. Landed AD-1 at 3652'. Cit Landed AD-1 at 3652'. Cit and conject	Cl. out, add perfs, acidize details, and give pertinent dates. Including estimated date of a vertical depths for all markers and zones pertinent to this w g due to corrosion. s. D.C.'s and bit. RU WL and reperforate Graybu 15% NEFE HCL, 5100# Rock Salt. Shut down f rculate packer fluid, set packer and run MIT. where the set of the s	Completion or Recompletion Repo Fsharting any proposed work. If urg from 3704'-3735' 4 sp for 1.5 hours. POOH w/w SJS Date	of. RIH w/pkr. and w/s. /s.
Thereby certify that the foregoing is investigation of approval, if any conditions of approval, if any certify that a crime conditions of approval, if any certify that the foregoing is investigated to the conditions of approval.	e locations and measured and true rod. tubing. Lay down tubin ed out to 3929'. POOH w/w/ 3'. Jize Grayburg w/5500 gals. b. Landed AD-1 at 3652'. Cit Landed AD-1 at 3652'. Cit and conject Tritle F se) Tritle	Cl. out, add perfs, acidize details, and give pertinent dates. Including estimated date of a vertical depths for all markers and zones pertinent to this w g due to corrosion. s. D.C.'s and bit. RU WL and reperforate Graybu 15% NEFE HCL, 5100# Rock Salt. Shut down f rculate packer fluid, set packer and run MIT. where the set of the s	Completion of Recompletion Report Fsharting any proposed work. If urg from 3704'-3735' 4 sp for 1.5 hours. POOH w/w SJS Date Date	of. RIH w/pkr. and w/s. /s.
11-1-95 MIRU. POOH w/ p 11-2-95 GIH w/w/s Cleane Set packer at 365 11-3-95 Rig up BJ and acid 11-6-95 RIH w/ prod. equip 11-6-95 RIH w/ prod. equip Signed Mit And State office u	e locations and measured and true rod. tubing. Lay down tubin ed out to 3929'. POOH w/w/ 3'. dize Grayburg w/5500 gals. b. Landed AD-1 at 3652'. Cit Landed AD-1 at 3652'. Cit and the test of the test of the test of the test of the test of the test of the test of	Cl. out, add perfs, acidize details, and give pertinent dates. Including estimated date of a vertical depths for all markers and zones pertinent to this w g due to corrosion. s, D.C.'s and bit. RU WL and reperforate Graybu 15% NEFE HCL, 5100# Rock Salt. Shut down f rculate packer fluid, set packer and run MIT. on E. Ritchie REGULATORY AGENT	Completion of Recompletion Report Fsharting any proposed work. If urg from 3704'-3735' 4 sp for 1.5 hours. POOH w/w SJS Date Date	of. RIH w/pkr. and w/s. /s.

-



-

Sem # 76 Permin TBg O PKR. 3653. Topperf, 3705in e Zicopm & C Zisopm. Inoco. Hand Milleton