lune 1950)	DEPARTMEN	TED STATES T OF THE INTERIOR	ORM APPROVED Budget Bureau No. 1004-0135
	BUREAU OF I	AND MANAGEMENT	Expires: March 31, 1993
			5. Lease Designation and Serial No.
	SUNDRY NOTICES	AND REPORTS ON WELLS	LC 03I695A 6. If Indian, Allottee or Tribe Name
Do not use this form for p		en or reentry to a different reservoir.	
		TRIPLICATE	7. It Unit or CA, Agreement Designation
Type of Well X Oil Gas	INJECTION		······
Well Well Name of Operator	Other		8 VIName of lease & wen
CONOCO, INC.			SEMU Well#10
Address and Telephone No.			9. 7 ap i weil #
10 Desta Dr., Suite IOOW, Location of Well (Footage, Sec., 1	Midland, Texas 79705-4500,9 T., R., M., or Survey Description)	I5 686-5424 915 684-6381	30 025 07849 10. Field and Pool, or Exploratory Area
Surface: 1980' FNL & I		T2:0S, R38E, Unit Ltr F	Warren McKee Simpsion
TD: same as at		T2.00, NOOL, UNIT LU F	1 County or Parish, State
			Lea, NM
TYPE OF SUBM		ATE NATURE OF NOTICE, REPO	······································
Notice of Intent			
	· .	Abandonment Recompletion	Change of Plans
X Subsequent Re	eport	Plugging Back	New Construction
		Casing Repair	Water Shut-Off
Final Abandonn	ment Notice	Altering Casing	Conversion to Injection
		X Repair tubing	
Describe Proposed or Completed directionally drilled, give subs	d Operations (Clearly state all pertine surface locations and measured and t	nt cletails, and give pertinent dates, including estima rue vertical depths for all markers and zones pertine	Orspose Water Avore: Report results of multiple completion on Wet Completion or Recompletion Report and Log form.) Ited date of starting any proposed work. If well its ent to this work.)*
I-il-99: Moved in & r ND wellhea I-l2-99: Rack & tally	rigged up, opened up we ad, NU BOP, tagged @ 3 / tubing, RiH w/notched d	ell, worked pump free, POOH w/ro 1934', RU tuboscope, Iaid down all 2014 SN @ 3786', ND BOP, NU w	evon: Report results of multiple completion on Weil Completion or Recompletion Report and Log form.) Ited date of starting any proposed work. If well its ent to this work.)* ds & pump, faid (down rods, I tubing, SION. yellhead, RiH w/rump & rods.
I-:I-99: Moved in & r ND wellhea I-I2-99: Rack & tally load & test,	rigged up, opened up we ad, NU BOP, tagged @ 3 / tubing, RiH w/notched d	nt cletails, and give pertinent dates, including estima rue vertical depths for all markers and zones pertine etl, worked pump free, POOH w/ro	evon: Report results of multiple completion on Weel Completion or Recompletion Report and Log form.) Ited date of starting any proposed work. If well its ent to this work.)* ds & pump, faid down rods, I tubing, SION. yellhead, RiH w/rump & rods
I-:I-99: Moved in & r ND wellhea I-I2-99: Rack & tally load & test,	rigged up, opened up we ad, NU BOP, tagged @ 3 / tubing, RiH w/notched o . check pump action: pul	ell, worked pump free, POOH w/ro 1934', RU tuboscope, Iaid down all 2014 SN @ 3786', ND BOP, NU w	evon: Report results of multiple completion on Weel Completion or Recompletion Report and Log form.) Ited date of starting any proposed work. If well its ent to this work.)* ds & pump, faid down rods, I tubing, SION. yellhead, RiH w/rump & rods
I-:I-99: Moved in & r ND wellhea I-I2-99: Rack & tally Ioad & test,	rigged up, opened up we ad, NU BOP, tagged @ 3 / tubing, RiH w/notched o . check pump action: pul	ell, worked pump free, POOH w/ro 1934', RU tuboscope, Iaid down all 2014 SN @ 3786', ND BOP, NU w	evon: Report results of multiple completion on Weel Completion or Recompletion Report and Log form.) Ited date of starting any proposed work. If well its ent to this work.)* ds & pump, faid down rods, I tubing, SION. yellhead, RiH w/rump & rods
I-:I-99: Moved in & r ND wellhea I-I2-99: Rack & tally load & test,	rigged up, opened up we ad, NU BOP, tagged @ 3 / tubing, RiH w/notched o . check pump action: pul	ell, worked pump free, POOH w/ro 1934', RU tuboscope, Iaid down all 2014 SN @ 3786', ND BOP, NU w	two: Report results of multiple completion on Weel Completion or Recompletion Report and Lug form.) Ited date of starting any proposed work. If well its ent to this work.)* ds & pump, faid down rods, I tubing. SION. vellhead, RiH w/pump & rods, 2 3/8" tubing.
I-:I-99: Moved in & r ND wellhea I-I2-99: Rack & tally load & test,	rigged up, opened up we ad, NU BOP, tagged @ 3 / tubing, RiH w/notched o . check pump action: pul	ell, worked pump free, POOH w/ro 1934', RU tuboscope, laid down all collar SN @ 3786', ND BOP, NU w led 3766' 2 3/8" replaced w/3777'	two: Report results of multiple completion on Weel Completion or Recompletion Report and Lug form.) Ited date of starting any proposed work. If well its ent to this work.)* ds & pump, faid down rods, I tubing. SION. vellhead, RiH w/pump & rods, 2 3/8" tubing.
I-:I-99: Moved in & r ND wellhea I-I2-99: Rack & tally load & test,	rigged up, opened up we ad, NU BOP, tagged @ 3 / tubing, RiH w/notched o . check pump action: pul	ell, worked pump free, POOH w/ro 1934', RU tuboscope, laid down all collar SN @ 3786', ND BOP, NU w led 3766' 2 3/8" replaced w/3777'	two: Report results of multiple completion on Weel Completion or Recompletion Report and Lug form.) Ited date of starting any proposed work. If well its ent to this work.)* ds & pump, faid down rods, I tubing. SION. vellhead, RiH w/pump & rods, 2 3/8" tubing.
I-:I-99: Moved in & r ND wellhea I-I2-99: Rack & tally Ioad & test,	rigged up, opened up we ad, NU BOP, tagged @ 3 / tubing, RiH w/notched o . check pump action: pul	ell, worked pump free, POOH w/ro 1934', RU tuboscope, laid down all collar SN @ 3786', ND BOP, NU w led 3766' 2 3/8" replaced w/3777'	two: Report results of multiple completion on Weel Completion or Recompletion Report and Lug form.) Ited date of starting any proposed work. If well its ent to this work.)* ds & pump, faid down rods, I tubing. SION. vellhead, RiH w/pump & rods, 2 3/8" tubing.
I-:I-99: Moved in & r ND wellhea I-I2-99: Rack & tally load & test,	rigged up, opened up we ad, NU BOP, tagged @ 3 / tubing, RiH w/notched o . check pump action: pul	ell, worked pump free, POOH w/ro 1934', RU tuboscope, laid down all collar SN @ 3786', ND BOP, NU w led 3766' 2 3/8" replaced w/3777'	two: Report results of multiple completion on Weel Completion or Recompletion Report and Lug form.) Ited date of starting any proposed work. If well its ent to this work.)* ds & pump, faid down rods, I tubing. SION. vellhead, RiH w/pump & rods, 2 3/8" tubing.
I-:I-99: Moved in & r ND wellhea I-I2-99: Rack & tally load & test, Well put ba	rigged up, opened up we ad, NU BOP, tagged @ 3 / tubing, RiH w/notched o , check pump action: pul ack on production.	ell, worked pump free, POOH w/ro 1934', RU tuboscope, laid down all collar SN @ 3786', ND BOP, NU w led 3766' 2 3/8" replaced w/3777'	two: Report results of multiple completion on Weel Completion or Recompletion Report and Lug form.) Ited date of starting any proposed work. If well its ent to this work.)* ds & pump, faid down rods, I tubing. SION. vellhead, RiH w/pump & rods, 2 3/8" tubing.
I-:I-99: Moved in & r ND wellhea I-I2-99: Rack & tally Ioad & test, Well put ba	rigged up, opened up we ad, NU BOP, tagged @ 3 / tubing, RiH w/notched o , check pump action: pul ack on production.	ell, worked pump free, POOH w/ro 1934', RU tuboscope, laid down all collar SN @ 3786', ND BOP, NU w led 3766' 2 3/8" replaced w/3777'	#vor. Report results of multiple completion on Weel Completion or Recompletion Report and Lug form.) ited date of starting any proposed work. If well its ent to this work.)* ods & pump, laid down rods, I tubing. SION. vellhead, RiH w/pump & rods, 2 3/8" tubing. Page 1 1033 Page 1 1033 Page 1 1033
I-:I-99: Moved in & r ND wellhea I-I2-99: Rack & tally Ioad & test, Well put ba	rigged up, opened up we ad, NU BOP, tagged @ 3 / tubing, RiH w/notched o , check pump action: pul ack on production.	Ann E. Ritchie	two: Report results of multiple completion on Weel Completion or Recompletion Report and Lug form.) Ited date of starting any proposed work. If well its ent to this work.)* ds & pump, faid down rods, I tubing. SION. vellhead, RiH w/pump & rods, 2 3/8" tubing.
I-:I-99: Moved in & r ND wellhea I-I2-99: Rack & tally Ioad & test, Well put ba	rigged up, opened up we ad, NU BOP, tagged @ 3 / tubing, RiH w/notched o , check pump action: pul ack on production.	Ann E. Ritchie	#vor. Report results of multiple completion on Weel Completion or Recompletion Report and Lug form.) ited date of starting any proposed work. If well its ent to this work.)* ods & pump, laid down rods, I tubing. SION. vellhead, RiH w/pump & rods, 2 3/8" tubing. Page 1 1033 Page 1 1033 Page 1 1033
I-:I-99: Moved in & r ND wellhea I-I2-99: Rack & tally Ioad & test, Well put ba	rigged up, opened up we ad, NU BOP, tagged @ 3 y tubing, RiH w/notched o check pump action: pul ack on production.	Ann E. Ritchie	#00: Report results of multiple completion on Weel Completion or Recompletion Report and Lug form.) itted date of starting any proposed work. If well its ent to this work.)* adds & pump, faid down rods, I tubing. SION. vellhead, RiH w/pump & rods, 2 3/8" tubing. Date 3-25-99 CR Date <u>All A 6 1009</u>