

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)</small>		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		5. State Oil & Gas Lease No.
2. Name of Operator Tenneco Oil Company		7. Unit Agreement Name
3. Address of Operator 900 Wilco Midland Texas 79701		8. Farm or Lease Name Amerada State
4. Location of Well UNIT LETTER L , 660 FEET FROM THE N LINE AND 1980 FEET FROM THE E LINE, SECTION 1 TOWNSHIP 22-S RANGE 35-E NMPM.		9. Well No. 1
10. Field and Pool, or Wildcat Jalmat		11. County Lea
15. Elevation (Show whether DF, RT, GR, etc.)		12. County

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Present conditions of Well:

TD 3858'

8 5/8" casing set at 309' w/270 sacks

5 1/2" casing set at 3858 w/200 sacks

Perforations at 3768' to 3794'

We Propose to plug and abandon as follows:

Spot 25 sacks at 3750' to 3550'

Cut and pull 5 1/2" casing

Spot 25 sacks at stub of 5 1/2"

Spot 25 sacks at top of salt

Spot 25 sacks at 320'

Spot 10 sacks at tops of surface

Install dry hole marker

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNED F. C. Stickney		TITLE President	
DATE 12/5/70		DATE DEC 9 1970	
APPROVED BY [Signature]		TITLE SECRETARY	
CONDITIONS OF APPROVAL, IF ANY:			

RECEIVED

APR 1 1970

CONSERVATION COM.
HARRIS, R. L.