NO. OF COPIES RECEIVED			Form C-103
DISTRIBUTION			Supersedes Old
SANTAFE	NEW MEXICO OIL CONS	SERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE			
U.S.G.S.			5a. Indicate Type of Lease
LAND OFFICE			State Fee
OPERATOR			5. State Oil & Gas Lease No.
SIINDPY	/ NOTICES AND DEPORTS ON	WELLS	B-1534
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO GEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)			
Name of Operator	OTHER- temp. Shut-Ir		7. Unit Agreement Name
CONOCO IN	8. Form or Lease Name		
P. O. Box 460, Hobbs, N.M. 88240			9. Well No.
Location of Well			0
UNIT LETTER F , 1980 FEET FROM THE NORTH LINE AND 2310 FEET FROM			Arrowhead Grayhura
11) 00 6			
LINE, SECTION	TOWNSHIP dd	5 RANGE 36F NMPM	
	15. Elevation (Show whether	DF RT CR etc.)	
		or, Kr, OK, etc.)	12. County
Check Appropriate Box To Indicate Names of No.			Lea MIIII
Check Appropriate Box To Indicate Nature of Notice, Report or Oth NOTICE OF INTENTION TO: SUBSEQUENT			her Data T REPORT OF:
ERFORM REMEDIAL WORK	PLUG AND ABANDON	_	
EMPORARILY ABANDON	PEDG AND ABANDON	REMEDIAL WORK	ALTERING CASING
JLL OR ALTER CASING	CHANGE PLANS	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
		OTHER	
OTHER			
. Describe Proposed or Completed Oper	gtions (Clearly state all pertinent desa	<i>ii i</i>	estimated date of starting any proposed
1) An Allamat	vas made to Pi	A //	
1) All Hitempt U	PAS MADE TO FE	A this well in	May of 1986 but
was unsuccessfu	l ,		/ 1001
D MIRU . +ag fill	@ 700: Sout 10.		
Pull the up to	300' and wast Co	~ KI =	rom 700'-600'.
D MIRU, tag fill @ 700'. Spot 10 sxs Cal Seal plug from 700'-600'. Pull the up to 300' and wait for 1/2 hr			
Tag plug @ 600'. Pump 60 sxs class "c" cmt w/270 (alls down they Top off 5½ csg w/cmt, D Cut off csg @ base of cellar. weld 44" metal cover over wellbore and instalt abandonment, marker. A sundry notice of to cover all previous and future subsequent work when the job is completed. The NMOCD will be notified prior to the job in order to witness.			
TOP OT 5/2 CS9 WI CMT,			
) Lut off csg @ base of cellar. Weld 14" metal conor aver well.			
and install abo	andonment, marko.	<i>(</i>	Well bore
DA Sundry notice	e will be submitted	Oracle = 100	· .
work when to	TA TO COVER ALL	previous and f	uture Subsequen
out when T	ne lop 15 comple-	ted. The NMOCI	I will be notified
prior to the	106 in order to	witness	100 11011110
	J		
I hereby certify that the information abo	we is true and complete to the best of	my knowledge and belief.	
11//	V		
ED MELINING	TITLE	Administrative Supervisor	DATE 7-3-86
OSICINAL CIO			8
ORIGINAL SIGNED BY JERN	ly sexton		JUL 7 1986
DISTRICT I SUPERVI	TITLE		DATE

NDITIONS OF APPROVAL, IF ANY:

1141 - 111 11