Submit 3 Copies to Appropriate

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revisied 1-1-89

District Office

## **OIL CONSERVATION DIVISION**

P.O. Box 2088	
DISTRICT   Santa Fe, New Mexico 87504-2088	
P.O. Box 1980, Hobbs, NM 88240	
DISTRICT II	API NO. (assigned by OCD on New Wells)
P.O. Drawer Dd, Artesia, NM 88210	30-025-08766
DISTRICT III 1000 Rio Brazos Rd., Aztec, Nm 87410	5. Indicate Type of Lease STATE X FEE
	STATE A FEE
	6. State Oil & Gas Lease No.
CUNDOV NOTICES AND DEPOSIT	B-1732
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG B  DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"	7. Lesse Name or Unit Agreement Name HARRY LEONARD (NCT-D)
(FORM C-101) FOR SUCH PROPOSALS.)	HARRY LEONARD (NC1-D)
1. Type of Well:	
OIL GAS	
WELL X WELL OTHER	
2. Name of Operator	8. Well No.
CHEVRON U.S.A. INC.	15
3. Address of Operator  P.O. POY 1150 MIDLAND, TV 70702 ATTN, D.D. MATTHONG	9. Pool name or Wildcat
P.O. BOX 1150 MIDLAND, TX 79702 ATTN: P.R. MATTHEWS	EUNICE SOUTH A CONTROL
Unit Letter P : 660 Feet From Th SOUTH Line and	660 Feet From The EAST Line
Section 3 Township 22S Range	36E NMPM LEA County
10. Elevation(Show whether DF, RKB, RT, GR, et	c.}
3567' GL	
11 Check Appropriate Box to Indecate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT	REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK	ALTER CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS.	PLUG AND ABAN.
PULL OR ALTER CASING CMT JOB CASING TEST AND CMT JOB	
OTHER: OTHER:	
12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including	
esticated date of starting any proposed work) SEE RULE 1103.  IT IS PROPOSED TO: PLUG AND ABANDON WELL	
· · · · · · · · · · · · · · · · · · ·	
TIH AND SET CIBP AT 3710', LOAD AND TEST ANN., CAP BP W/35' CEMENT. COVERS QUEEN PAY.	
SET BALANCED PLUG F/3470-3120. (35 SX.)COVERS YATES & 7-RIVERS PAYS.	
SHOOT HOLES AT 1715' AND BREAK CIRC BETWEEN 5.5" & 8 5/8" CSG. SET CICR AT 1520'.	
SQUEEZE WITH 75 SXS. CMT AND LEAVE 35' ON TOP OF BP. COVERS RUSTLER AND SALT.	
PERF AT 450' BREAK CIRC BETWEEN 5.5" & 8 5/8" CSG PUMP 115 SXS. CMT. LEAVING 5.5" FULL.	
CUT OFF WELLHEAD AND INSTALL P & A MARKER.	
10# P & A MUD WILL BE PLACED BETWEEN ALL CMT. PLUGS.	
CHANGE WELL STATUS TO P & A.	
I hereby certify that the information shows is true and complete to the best of my knowledge and belief.	
SIGNITURE PROMISE TITLE TECH. ASSISTANT	DATE: 5/20/92
TYPE OR PRINT NAME P.R. MATTHEWS	TELEPHONE NO (915)687-7812
APPROVED BY TITLE	DATE MAY 9 9 100