

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator Gulf Oil Corporation		5. State Oil & Gas Lease No.
3. Address of Operator P. O. Box 670, Hobbs, NM 88240		7. Unit Agreement Name
4. Location of Well UNIT LETTER <u>K</u> , <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>4</u> TOWNSHIP <u>22S</u> RANGE <u>36E</u> NMPM.		8. Farm or Lease Name J. F. Janda (NCT-F)
		9. Well No. 7
		10. Field and Pool, or Wildcat Jalmat Gas South Eunice
15. Elevation (Show whether DF, RT, GR, etc.) 3589' GL		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER <u>Test for DHC</u> <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

POH with rods and pump. Cut paraffin. Close in S. Eunice 24 hours. Obtain SIBP and 250' gradient pressure. Set plug at 3740', test 500#. Open valve at 3706'. Close in Jalmat 24 hours. Obtain SIBP and 250' gradient pressure. Close valve at 3706'. Test tubing 500#. P/U plug. GIH with pump and rods, hang on. Test pump. Complete after obtaining bottom hole pressure for CDH 12-27-81.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Rd Pite TITLE Area Engineer DATE 1-11-82
APPROVED BY _____ TITLE _____ DATE JAN 1 1982
CONDITIONS OF APPROVAL, IF ANY: