Form C-102

NEW MEXICO OIL CONSERVATION COMMISSION

Santa, Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in triplicate to the Oil Conservation Commission or its proper agent before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Regulations of the Commission. Indicate nature of notice by checking below: NOTICE OF INTENTION TO TEST CASING NOTICE OF INTENTION TO SHOOT OR CHEMICALLY TREAT WELL SHUT-OFF NOTICE OF INTENTION TO PULL OR NOTICE OF INTENTION TO CHANGE PLANS OTHERWISE ALTER CASING NOTICE OF INTENTION TO REPAIR WELL NOTICE OF INTENTION TO PLUG WELL NOTICE OF INTENTION TO DEEPEN WELL Hobbs, New Mexico May 28, 1943. OIL CONSERVATION COMMISSION, Santa Fe, New Mexico. Gentlemen: Following is a notice of intention to do certain work as described below at the Gulf Oil Corpn - Gypsy Prod Divn - J. F. Janda #F* Well No. 1 in C.SW SW 4-225-361 Company or Operator of Sec. 4, T. 225, R. 361, N. M. P. M., Pontes Field,County. FULL DETAILS OF PROPOSED PLAN OF WORK FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS OF THE COMMISSION Started Drilling May 26, 1943. The 9 5/8" OD 3 gauge Armoo Spiral weld slip joint casing (NEW), set 290' 8", cemented with 250 sacks common coment and 100# Calcium Chloride, plug at 285', comented by the Halliburton Comenting Process, Coment circulated in cellar. Job completed at 600 AM May 27th, 1945. Will drill plug and test at 600 PM May 28th, 1945. JUN 3 - 1945 Gulf Oil Corpn = Gypsy Prod Diva.

Company or Operator 19____ Approved ... except as follows: District Supt. Send communications regarding well to Name Lester LeFavour OIL CONSERVATION COMMISSION, Address P. O. Box 1667 - Hobbs Now Moziso. AS INSPECTO

 $(\mathbf{x}_{i},\mathbf{x}_{i}) = (\mathbf{x}_{i},\mathbf{x}_{i}) \cdot (\mathbf{x}_{i},\mathbf{x}_{i}) \cdot (\mathbf{x}_{i},\mathbf{x}_{i}) \cdot (\mathbf{x}_{i},\mathbf{x}_{i}) \cdot (\mathbf{x}_{i},\mathbf{x}_{i},\mathbf{x}_{i})$

· Control of the

a a si substitution a