DISTRIBUTION ANTA FE		Supersedes Old
ANTAFE	HUR DE LOCATION ALLA ALL.	C-102 and C-103
	NEW MEXICO OTE CONSERVATION COMMISSION	Effective 1-1-65
FILE	FED 1 THE CO.	5a. Indicate Type of Lease
J.S.G.S.	FEB ! 4 01 PM '66	State Fee.
AND OFFICE	-	5. State Oil & Gas Lease No.
OPERATOR		·
SUNE	DRY NOTICES AND REPORTS ON WELLS PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVA	DIR.
OIL GAS	OTHER-	7. Unit Agreement Name
Name of Operator Qulf Oil Corporation		8. Farm or Lease Name J. H. Day #
. Address of Operator		9. Well No.
Box 670, Hobbs, New	Mexico	4
. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER	1980 FEET FROM THE North LINE AND 660	FEET FROM
UNIT LETTER,		
THE West LINE, SEC	6 TOWNSHIP 22-8 RANGE 36-1	NMPM.
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	15. Elevation (Show whether DT, NT, OR, etc.)	Lea
	k Appropriate Box To Indicate Nature of Notice, Reprint Intention to:	BSEQUENT REPORT OF:
	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK	COMMENCE DRILLING OPNS	. PLUG AND ABANDONMENT
TEMPORARILY ABANDON	r	
	CHANGE PLANS CASING TEST AND CEMENT	JOB
PULL OR ALTER CASING	OTHER	108
other Plug and aba	OTHER	JÓB
OTHER Plug and aba	OTHER	
Plug and aba 17. Describe Proposed or Completed work) SEE RULE 1103. Pull tubing. Pun Completed Pu	ndon	750'. Circulate hole with 110 twith 500%. Spot 10 sack
Plug and aba 17. Describe Proposed or Completed work) SEE RULE 1703. Pull tubing. Pun Completed barrels of mud. Speciment plug from 50	OTHER de Operations (Clearly state all pertinent details, and give pertinent data approximately 3 to 10 sack cement plug on top of BP. Test to surface. Install dry hole marker and attended to the best of my knowledge and believed to the best of my knowledge and believed to the best of my knowledge and believed to the best of my knowledge and believed.	750°. Circulate hole with 110 twith 500%. Spot 10 sack delean location.
Plug and aba 17. Describe Proposed or Completed work) SEE RULE 1703. Pull tubing. Pun Completed barrels of mud. Speciment plug from 50	Indon H Operations (Clearly state all pertinent details, and give pertinent data approximately 3) to 10 sack cement plug on top of BP. Team to surface. Install dry hole marker and	750°. Circulate hole with 110 twith 500%. Spot 10 sack delean location.
Plug and aba 17. Describe Proposed or Completed work) SEE RULE 1703. Pull tubing. Pun Completed barrels of mud. Speciment plug from 50	OTHER de Operations (Clearly state all pertinent details, and give pertinent data approximately 3 to 10 sack cement plug on top of BP. Test to surface. Install dry hole marker and attended to the best of my knowledge and believed to the best of my knowledge and believed to the best of my knowledge and believed to the best of my knowledge and believed.	750°. Circulate hole with 110 twith 500%. Spot 10 sack delean location.

CONDITIONS OF APPROVAL, IF ANY: