

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-08842
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name State A AC 2
8. Well No. 55
9. Pool name or Wildcat Eunice SR-Queen-South

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator Clayton W. Williams, Jr., Inc.
3. Address of Operator Six Desta Drive, Suite 3000 Midland, Texas 79705

4. Well Location Unit Letter <u>P</u> : <u>660</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>8</u> Township <u>22S</u> Range <u>36E</u> NMPM Lea County
--

10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL - 3581'
--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. WORK WILL COMMENCE UPON OCD APPROVAL

- 1) Spot 35' cement plug on CIBP that was set 12/07/90 @ 3710'
- 2) Circulate hole w/10 PPG Gelled Brine
- 3) Spot 20 sx balanced cement plug from 2400 - 2600'.
- 4) Spot 20 sx balanced cement plug from 400 - 600'.
- 5) Perforate @ 300'
- 6) Circulate cement down 5-1/2, 8-5/8" annulus to surface (±75 sx cement)
- 7) Cut 5-1/2" and 8-5/8" casing 3' below GL. Set P & A marker. Cut Deadmen. Clear location of all junk. Plug and abandon wellbore.

SEE ATTACHED WELLBORE DIAGRAM

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David Grafe TITLE Petroleum Engineer DATE 02/18/93
TYPE OR PRINT NAME David Grafe TELEPHONE NO. 682-6324

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

FEB 22 1993