

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240
DISTRICT II
P.O. Drawer DD, Artesia, NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-08856
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name State A AC 2
8. Well No. 31
9. Pool name or Wildcat Eunice 7 Rvrs Queen South

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Clayton Williams Energy, Inc.
3. Address of Operator Six Desta Drive, Suite 3000 Midland, Texas 79705	4. Well Location Unit Letter F : 1980 Feet From The North Line and 1980 Feet From The West Line

Section 9	Township 22S	Range 36E	NMPM	Lea	County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3573' DF					

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Work will begin upon OCD approval

- 09/23/93. Set CIBP @ 3570' w/35' cement on CIBP.
- Load hole w/10 ppg gelled brine from CIBP to surface
- Perforate the 5-1/2" casing @ \pm 310'.
- Circulate cement down 5-1/2" casing and up the 5-1/2 - 7-5/8" annulus to surface.
(60 sx Class "C" cement)
- Cut all casing 3' below G.L. Install P & A marker. Cut and remove all deadmen.
Clear location of all junk.

Plug and Abandon Wellbore

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David G. Grafe TITLE Senior Operations Engineer DATE 12/05/94
TYPE OR PRINT NAME David G. Grafe TELEPHONE NO. 682-6324

(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON

DISTRICT SUPERVISOR

APPROVED BY _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

DEC 13 1994