

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name Skaggs Grayburg Unit
2. Name of Operator Tanner, Inc.	8. Former Lease Name Skaggs Grayburg Unit
3. Address of Operator P. O. Box 72, Little, New Mexico 87610	9. Well No. 11
4. Location of Well UNIT LETTER D, 600 FEET FROM THE North LINE AND 500 FEET FROM THE West LINE, SECTION 13, TOWNSHIP 20-S, RANGE 27-E, NMPM.	10. Field and Pool, or Wildcat Skaggs Grayburg San Andres
15. Elevation (Show whether DF, RT, GR, etc.) 3565' (DF)	12. County Lee

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☒ Addl. Perfs & Treat	CASING TEST AND CEMENT JOBS ☐	
OTHER ☐			

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up. Install ROP. Pull rods, pump & tubing.
2. Perforate 2 7/8" Csg w/1-JSPF @ 3894', 3914', 18', 20', 22', 32', 34', 40', 42', 44', 46', 61', 66', 81', 83', 85', 87', 89', & 3992'.
3. Set pkr @ 3750'. Acidize 3806'-3992' w/3000 gals 20% NEFF Acid using rock salt between stages. Flush w/75 Bbls. 2% Kcl water.
4. Frac perfs. 3806'-3992' w/28,000 gal. x-linked gelled water & 42,000# 20/40 sand. Flush w/fresh water.
5. Perforate 2 7/8" Csg w/1-JSPF @ 3724', 26', 28', 38', 40', 50', 53', 54', 56', 66', & 3768'.
6. Set ROP @ 3787' & pkr @ 3690'. Acidize perfs. 3724'-3768' w/1500 gals. 20% NEFF Acid in 3 stages using rock salt between stages. Flush w/75 Bbls. 2% Kcl water.
7. Frac perfs. 3724'-3768' w/15,000 gals. x-linked gelled water & 29,000# 20/40 sand. Flush w/produced water. Pull RBP & pkr. Clean out.
8. Install production equipment. Test & return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Asst. Dist. Supt. DATE 1/9/81

APPROVED BY Dist. & Supt. TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: