

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
N. M. OIL CONS. COMMISSION

SUBMIT IN TRI
(Other instructions
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR CONOCO INC.	8. FARM OR LEASE NAME SEMU Tubb
3. ADDRESS OF OPERATOR P. O. Box 460, Hobbs, N.M. 88240	9. WELL NO. 86
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Unit D	10. FIELD AND POOL, OR WILDCAT Monument Tubb
14. PERMIT NO. 30-025-20656	11. SEC., T., R., OR BLK. AND SURVEY OR AREA Sec. 14-205-37E
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE Lea NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other) open add'l pay & acidize

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- ① MIRU. POOH w/ rods & pump. Make scraper run to PBTD (6700±) Spot. 5 bbls 28% HCL-NE-FE from 6620'-6441'.
- ② Perf Tubb w/ 1 JSF @ 6441', 46', 58', 61', 64', 67', 70', 6473', 79', 82', 85', 6504', 10', 13', 16', 24', 46', 48', 59', 62', 65', 87', 6600', 03', 12', 20'.
- ③ Set treating pkr @ 6250'. Acidize Tubb perms w/ 80 bbls 28% HCL-NE-FE in 4 equal stages. Flush to last perf w/ 46 bbls completion fluid. Swab
- ④ Rel pkr @ 6250'. GIH w/ prod. equip, place on test. Rig down

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Administrative Supervisor

DATE

9-10-86

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

9-24-86

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

RECEIVED
SEP 29 1986
C.C.P.
HOBBS OFFICE