STATE OF NEW MEXICO

ENERGY AND MINERALS DEPARTMENT

HD. OF CONIES MELEIVED	T	
POLITICINATEID		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		1

OIL CONSERVATION DIVISION

Form C-103

DISTRIBUTION		P. O. BOX	2088		Revised 10-1-73		
SANTA FE	SAN'	TA FE, NEW	MEXICO:	87501	1611360 13 1		
FILE					Sa. Indicate Type	of Leaso	
U.S.O.S.					State	Fee [
LAND OFFICE							
OPERATOR					5. State Oil & Gas	Lease No.	
To Examine	لسسم						
SUN SUN TOR THIS FORM FOR	IDRY NOTICES AND	REPORTS ON A	NELLS CR TO A DIFFEI PROPOSALS.)	RENT RESERVOIR.			
USC AFFEC					7. Unit Agreement	Nome	
OIL X WELL GAB	OTHER-					N	
Name of Operator					8. Farm or Lease		
TEXACO Inc.			M. B. Weir B				
					9. Well No.		
Address of Operator	U. I.I.a. May May 5	aa 00240			9		
P. O. Box 728,	Hobbs, New Mexi	0 30240			10. Field and Poc	L or Wildcat	
Location of Well	-	200		. 0100	See Below	•	
0	660 FEET PROM	South	LINE AND	ZIBU FEET FROM	266 pe low	, , , , , , , , , , , , , , , , , , , 	
	12 TO						
THELINE, SE	CTIONT	WNSHIP			VIIIIII		
	15. Elevat	ion (Show whether l	DF, RT, GR, e DF)	etc.)	12. County Lea		
5. Cl	ck Appropriate Box	To Indicate N	ature of No	otice Report of Ot	her Data		
		to materie N	ature or its	cuperough	T REPORT OF:		
NOTICE OF	F INTENTION TO:			SUBSEQUEN	I REPORT OF.		
PERFORM REMEDIAL WORK	PLUG	AND ABANDON		i Fi		ING CASING	
TEMPORARILY ABANDON	•			RILLING OPHS.	PEUG A	NO XBXHDVIII	
PULL OR ALTER CASING	CHAN	GE PLANS		AND CEMENT JOB		L-	
OTHER Repair	Casing Leak	⊠	OTHER				
	•	,	L		- antimuted does of	etarting any propose	
17. Describe Proposed or Complete	ed Operations (Clearly state	te all pertinent deta	ills, and give	pertinent dates, includin	g estimated date of	starting any proposi	
work) SEE RULE 1103.		•					
	•						

10. FIELD AND POOL: SKAGGS GLORIETA, SKAGGS DRINKARD, WEIR BLINEBRY

- 1. RIG UP. KILL DRINKARD STRING. INSTALL BOP. PULL TUBING.
- SET CIBP IN DRINKARD STRING @ 5600'. 2.
- SQUEEZE BLINEBRY CASING LEAK 5240' -5369' W/100 SX CLASS 3. H CEMENT. WOC. DOC. TEST.
- 4. DRILL OUT CIBP IN BLINEBRY STRING @ 5600' AND CLEAN OUT TO 6020'.
- 5. DRILL OUT CIBP IN DRINKARD STRING @ 5600' AND CLEAN OUT TO TD.
- 6. INSTALL PRODUCTION EQUIPMENT. TEST AND RETURN BLINEBRY

AND DRINKARD STRIN		
· · · · · · · · · · · · · · · · · · ·	THE COMMISSION MEDICAL INC. 24 Hours Prior to commence	UTED NG WORK
15. I hereby certify that the information above is true and com	plete to the best of my knowledge and belief.	•
ALL Choth	Asst Dist Mgr	DATE 4-10-84
ORIGINAL SIGNED BY JEARY SEXTON DISTRICT I SUPERVISOR	TITLE	APR 1 3 1984