Second Comparison   Sundry Notices and Reports on Wells   Society   Societ	DISTRIBUTION		Form C+103 Supersedes Old C+102 and C+103
SUNDRY NOTICES AND REPORTS ON WELLS  100 NOT USE THIS FORL FOR MORPOLASE TO SMILL ON TO SECRETAR PLANS AND REPORTS ON WELLS  100 NOT USE THIS FORL FOR MORPOLASE TO SMILL ON TO SECRETAR PLANS AND REPORTS ON WELLS  11. OIL WELL AND OFFICE OF MARKET AND REPORTS ON WELLS  22. Name of Operator  TEXACO Inc.  3. Address of Operator  TEXACO Inc.  3. Address of Operator  P. O. BOX 728 - Hobbs, New Mexico 88240  4. Location of Well  OMIT LETTER N 660  FET FROM THE SOUTH CHEER AND 1980  THE West LINE, SECTION 20 TOWNSHIP 20-5 RANGE 37-E NAME  NOTICE OF INTENTION TO:  PLUG AND ABANDON  TEMPORABILLY ABANDON  PULL OR ALTER CASING  OTHER  17. Until Agreement Nome  Eunice Monument Unit  8. Form or Losse Name  Eunice Monument Unit  18. Flower Long Remedial Work  Eunice  Full AND ABANDON  TEMPORABILLY ABANDON  PULL OR ALTER CASING  OTHER  17. Until Agreement Nome  Eunice Monument Unit  8. Form or Losse Name  Eunice Monument Unit  18. Form or Losse Name  Eunice Monument Unit  1980  TEMPORATION THE SUBSEQUENT REPORT OF:  REMEDIAL WORK  TEMPORABILLY ABANDON  PULL OR ALTER CASING  OTHER  17. Until Agreement Nome  Eunice Monument Unit  8. Form or Losse Name  Eunice Monument Unit  18. Form or Losse Name  Eunice Monument Unit  1980  TEMPORATION THE SUBSEQUENT REPORT OF:  REMEDIAL WORK  TEMPORABILLY ABANDON  TEMPORABILLY ABANDON  PULL OR ALTER CASING  OTHER  17. Until Agreement Nome  Eunice Monument Unit  8. Form or Losse Name  Eunice Monument Unit  1980  TEMPORATION THE SUBSEQUENT REPORT OF:  REMEDIAL WORK  TEMPORATION THE SUBSEQUENT REPORT OF:  REMEDIAL WORK  TEMPORATION THE SUBSEQUENT REPORT OF:  REMEDIAL WORK  TEMPORATION THE SUBSEQUENT REPORT OF:  REMEDIAL OF THE SUBSEQUENT REPORT OF:  REMEDIAL WORK  TEMPORATION THE SUBSEQUENT REPORT OF:  REMEDIAL OF THE SUBSEQUEN	SANTA FE FILE	NEW MEXICO OIL CONSERVATION COMMISSION	
SUNDRY NOTICES AND REPORTS ON WELLS    COMMON USE THIS COMMON SERVICE   COMMON COLOR   COLO	U.S.G.S.		5a. Indicate Type of Lease
SUNDRY NOTICES AND REPORTS ON WELLS  (100 NOT USE THIS COMM FOR MEDICAL TO SHELL ON TO DEED BY AND REDUCED AND PRUSE BACK 12.4 DIFFERENT RESERVOIR.  2. Name of Ciperator  TEXACO Inc.  3. Address of Operator  P.O. Box 728 - Hobbs, New Mexico 88240  4. Location of Well  UNIT LETTER N	LAND OFFICE		State X Fee.
SUNDRY NOTICES AND REPORTS ON WELLS  1. (IO NOT USE THIS FORM FOR WORDANDS TO CENTUM FOR PERMIT — "I FORM C. 1011 FOR SUCE PROPOSALS.")  1. (INC.	OPERATOR		
TEXACO Inc.  3. Address of Operator TEXACO Inc.  3. Address of Operator P.O. Box 728 - Hobbs, New Mexico 88240  4. Location of Well Unit LETTER N 660 FEET FROM THE South INE AND 1980  10. Field and Pool, or Wildcar Eurice Fine West Line, Section 20 TOWNSHIP 20-S RANGE 37-E NAPPM.  15. Elevation (Show whether DF, RT, GR, etc.)  16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF:  PERFORM REMEDIAL WORK TEMPORALILY ABANDON CHANGE PLANS  TEMPORALILY ABANDON CHANGE PLANS  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose unok) see RULE (103.  1. Pull Tubing. 2. Drill out hydromite & CIBP (8' Hydromite above CIBP at 3780').  3. Run cement retainer and set at 3830'. Squeeze lower perforations W/75 sx. Class 'C' cement containing 1/4 lb./sx. Flocele. Resqueeze if necessary.  4. Perforate W/1 JSPF from 3741-3745', 3750-3754', 1 JSPI at 3759', 3760', 1 JSPF from 3764-3772', 1 JSPI at 3779', 3798', 3802', 3804' and 3806'.  5. Run tubing W/treating packer set at 3730'.  6. Acidize W/4000 gals 15% chemically retarded NEA in 10 equal stages.			B-160-1
OTHER  OTHER  OTHER  OTHER  OTHER  DITICE Monument Unit  S. Farm or Lease Home Eunice Monument  In Field Monument S. Farm or Lease Home Eunice Monument S. Farm or Lease Home S. Farm or Lease Home Eunice Monument S. Eunice S. Farm or Lease Home Eunice Monument S. Eunice Eunice Monument S. Farm or Lease	(DO NOT USE THIS FORM FOR PUSE "APPLIC	DRY NOTICES AND REPORTS ON WELLS PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. ATION FOR PERMIT - (FORM C-101) FOR SUCH PROPOSALS.)	
TEXACO Inc.  3. Address of Operator P.O. Box 728 - Hobbs, New Mexico 88240  4. Location of Well UNIT LETTER N 660 PEET FROM THE SOUTH LINE AND 1980  10. Field and Pool, or Wildcot Eunice  West LINE, SECTION 20 TOWNSHIP 20-S RANGE 37-E NAME  15. Elevation (Show whether DF, RT, GR, etc.)  16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK X TEMPORARILY ABANDON PULL OR ALTER CASING OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose other commence Office of Starting and Pull And AbandonMent Temporation of the Data NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK X TEMPORARILY ABANDON PULL OR ALTER CASING OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose other commence of the Data OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose other commence of the Data OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose other commence of the Data OTHER  18. Elevation (Show whether DF, RT, GR, etc.)  19. Describe Proposed or Completed OTHER  19. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose other commence of the Data OTHER  19. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose other Commence of Notice, Report or Other Data SUBSEQUENT  12. County Lea  12. Describe Proposed or Completed Operations (Clearly state all pertinent details, an	OIL GAS WELL	OTHER-	
P.O. Box 728 - Hobbs, New Mexico 88240  4. Location of Well  UNIT LETTER N 660  FEET FROM THE South  IS. Elevation (Show whether DF, RT, GR, etc.)  3522' DF  Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK  TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 1103.  18. Pull Tubing. 2. Drill out hydromite & CIBP (8' Hydromite above CIEP at 3780'). 3. Run cement retainer and set at 3830'. Squeeze lower perforations w/75 sx. Class 'C' cement containing 1/4 lb./sx. Flocele. Resqueeze if necessary. 4. Perforate w/1 JSPF from 3741-3745', 3750-3754', 1 JSPI at 3759', 3760', 1 JSPF from 3764-3772', 1 JSPI at 3778', 3780', 1 JSPF from 3786-3792', 1 JSPI at 3797', 3798', 3802', 3804' and 3806'. 5. Run tubing w/treating packer set at 3730'. 6. Actidize w/4000 gals 15% chemically retarded NEA in 10 equal stages.	1		
4. Location of Well  UNIT LETTER N 660  THE West  LINE, SECTION 20  TOWNSHIP  15. Elevation (Show whether DF, RT, GR, etc.)  3522' DF  Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) see ROLLE 1703.  Pull Tubing.  2. Drill out hydromite & CIBP (8' Hydromite above CIBP at 3780').  3. Run cement retainer and set at 3830'. Squeeze lower perforations w/75 sx. Class 'C' cement containing 1/4 lb./sx. Flocele. Resqueeze if necessary.  4. Perforate w/1 JSPF from 3741-3745', 3750-3754', 1 JSPI at 3759', 3760', 1 JSPF from 3764-3772', 1 JSPI at 3778', 3780', 1 JSPF from 3786-3792', 1 JSPI at 3797', 3798', 3802', 3804' and 3806'.  5. Run tubing w/treating packer set at 3730'.  6. Acidize w/4000 gais 15% chemically retarded NEA in 10 equal stages.	1 · · · · · · · · · · · · · · · · · · ·	s, New Mexico 88240	9, Well No.
UNIT LETTER N . 660  FEET FROM THE SOuth LINE AND 1980  FEET FROM THE West LINE, SECTION 20  TOWNSHIP 20-S RANGE 37-E HMPM.  15. Elevation (Show whether DF, RT, GR, etc.)  16.  Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  PERFORM REMEDIAL WORK X PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPRS.  COMMENCE DRILLING OPRS.  CASING TEST AND CEMENT JQB OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 1703.  1. Pull Tubing.  2. Drill out hydromite & CIBP (8' Hydromite above CIBP at 3780').  3. Run cement retainer and set at 3830'. Squeeze lower perforations w/75 sx. Class 'C' cement containing 1/4 lb./sx. Flocele. Resqueeze if necessary.  4. Perforate w/1 JSPF from 3741-3745', 3750-3754', 1 JSPI at 3759', 3760', 1 JSPF from 3764-3772', 1 JSPI at 3778', 3780', 1 JSPF from 3786-3792', 1 JSPI at 3797', 3798', 3802', 3804' and 3806'.  5. Run tubing w/treating packer set at 3730'.  6. Acidize w/4000 gals 15% chemically retarded NEA in 10 equal stages.			
15. Elevation (Show whether DF, RT, GR, etc.)  3522' DF  Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 1703.  1. Pull Tubing. 2. Drill out hydromite & CIBP (8' Hydromite above CIBP at 3780').  3. Run cement retainer and set at 3830'. Squeeze lower perforations w/75 sx. Class 'C' cement containing 1/4 lb./sx. Flocele. Resqueeze if necessary.  4. Perforate w/1 JSPF from 3741-3745', 3750-3754', 1 JSPI at 3759', 3760', 1 JSPF from 3764-3772', 1 JSPI at 3778', 3780', 1 JSPF from 3786-3792', 1 JSPI at 3797', 3798', 3802', 3804' and 3806'.  5. Run tubing w/treating packer set at 3730'.  6. Acidize w/4000 gals 15% chemically retarded NEA in 10 equal stages.	UNIT LETTER N	660 FEET FROM THE South LINE AND 1980 FEE	
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK  TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 1703.  1. Pull Tubing. 2. Drill out hydromite & CIBP (8' Hydromite above CIBP at 3780'). 3. Run cement retainer and set at 3830'. Squeeze lower perforations w/75 sx. Class 'C' cement containing 1/4 lb./sx. Flocele. Resqueeze if necessary. 4. Perforate w/1 JSPF from 3741-3745', 3750-3754', 1 JSPI at 3759', 3760', 1 JSPF from 3764-3772', 1 JSPI at 3778', 3780', 1 JSPF from 3786-3792', 1 JSPI at 3797', 3798', 3802', 3804' and 3806'. 5. Run tubing w/treating packer set at 3730'. 6. Acidize w/4000 gals 15% chemically retarded NEA in 10 equal stages.	THE West LINE, SEC	TION 20 TOWNSHIP 20-S RANGE 37-E	, MAPM,
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK  TEMPORARILY ABANDON PULL OR ALTER CASING  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 1703.  1. Pull Tubing. 2. Drill out hydromite & CIBP (8' Hydromite above CIBP at 3780'). 3. Run cement retainer and set at 3830'. Squeeze lower perforations w/75 sx. Class 'C' cement containing 1/4 lb./sx. Flocele. Resqueeze if necessary. 4. Perforate w/1 JSPF from 3741-3745', 3750-3754', 1 JSPI at 3759', 3760', 1 JSPF from 3764-3772', 1 JSPI at 3778', 3780', 1 JSPF from 3786-3792', 1 JSPI at 3797', 3798', 3802', 3804' and 3806'. 5. Run tubing w/treating packer set at 3730'. 6. Acidize w/4000 gals 15% chemically retarded NEA in 10 equal stages.	mannana da	15. Elevation (Show whether DF, RT, GR, etc.)	12 County Allian
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK  TEMPORARILY ADAINON PULL OR ALTER CASING  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) see Rule 1 fos.  1. Pull Tubing.  2. Drill out hydromite & CIBP (8' Hydromite above CIBP at 3780').  3. Run cement retainer and set at 3830'. Squeeze lower perforations w/75 sx. Class 'C' cement containing 1/4 lb./sx. Flocele. Resqueeze if necessary.  4. Perforate w/1 JSPF from 3741-3745', 3750-3754', 1 JSPI at 3759', 3760', 1 JSPF from 3764-3772', 1 JSPI at 3778', 3780', 1 JSPF from 3786-3792', 1 JSPI at 3797', 3798', 3802', 3804' and 3806'.  5. Run tubing w/treating packer set at 3730'.  6. Acidize w/4000 gals 15% chemically retarded NEA in 10 equal stages.			
PERFORM REMEDIAL WORK X PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 1703.  1. Pull Tubing. 2. Drill out hydromite & CIBP (8' Hydromite above CIBP at 3780'). 3. Run cement retainer and set at 3830'. Squeeze lower perforations w/75 sx. Class 'C' cement containing 1/4 lb./sx. Flocele. Resqueeze if necessary. 4. Perforate w/1 JSPF from 3741-3745', 3750-3754', 1 JSPI at 3759', 3760', 1 JSPF from 3764-3772', 1 JSPI at 3778', 3780', 1 JSPF from 3786-3792', 1 JSPI at 3797', 3798', 3802', 3804' and 3806'. 5. Run tubing w/treating packer set at 3730'. 6. Acidize w/4000 gals 15% chemically retarded NEA in 10 equal stages.	16. Check		
TEMPORARILLY ABANDON  PULL OR ALTER CASING  CHANGE PLANS  CHANGE PLANS  CHANGE PLANS  COMMENCE DRILLING OPNS.  CASING TEST AND CEMENT JQB  OTHER  OTHER  17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 1103.  1. Pull Tubing.  2. Drill out hydromite & CIBP (8' Hydromite above CIBP at 3780').  3. Run cement retainer and set at 3830'. Squeeze lower perforations w/75 sx. Class 'C' cement containing 1/4 lb./sx. Flocele. Resqueeze if necessary.  4. Perforate w/l JSPF from 3741-3745', 3750-3754', 1 JSPI at 3759', 3760', 1 JSPF from 3764-3772', 1 JSPI at 3778', 3780', 1 JSPF from 3786-3792', 1 JSPI at 3797', 3798', 3802', 3804' and 3806'.  5. Run tubing w/treating packer set at 3730'.  6. Acidize w/4000 gals 15% chemically retarded NEA in 10 equal stages.		· · · · · · · · · · · · · · · · · · ·	
TEMPORARILY ABANDON PULL OR ALTER CASING  CHANGE PLANS  CH	PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 1 fos.  1. Pull Tubing. 2. Drill out hydromite & CIBP (8' Hydromite above CIBP at 3780'). 3. Run cement retainer and set at 3830'. Squeeze lower perforations w/75 sx. Class 'C' cement containing 1/4 lb./sx. Flocele. Resqueeze if necessary. 4. Perforate w/1 JSPF from 3741-3745', 3750-3754', 1 JSPI at 3759', 3760', 1 JSPF from 3764-3772', 1 JSPI at 3778', 3780', 1 JSPF from 3786-3792', 1 JSPI at 3797', 3798', 3802', 3804' and 3806'. 5. Run tubing w/treating packer set at 3730'. 6. Acidize w/4000 gals 15% chemically retarded NEA in 10 equal stages.	TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 1103.  1. Pull Tubing. 2. Drill out hydromite & CIBP (8' Hydromite above CIEP at 3780'). 3. Run cement retainer and set at 3830'. Squeeze lower perforations w/75 sx. Class 'C' cement containing 1/4 lb./sx. Flocele. Resqueeze if necessary. 4. Perforate w/l JSPF from 3741-3745', 3750-3754', 1 JSPI at 3759', 3760', 1 JSPF from 3764-3772', 1 JSPI at 3778', 3780', 1 JSPF from 3786-3792', 1 JSPI at 3797', 3798', 3802', 3804' and 3806'. 5. Run tubing w/treating packer set at 3730'. 6. Acidize w/4000 gals 15% chemically retarded NEA in 10 equal stages.	PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JQB	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any propose work) SEE RULE 1703.  1. Pull Tubing. 2. Drill out hydromite & CIBP (8' Hydromite above CIBP at 3780'). 3. Run cement retainer and set at 3830'. Squeeze lower perforations w/75 sx. Class 'C' cement containing 1/4 lb./sx. Flocele. Resqueeze if necessary. 4. Perforate w/l JSPF from 3741-3745', 3750-3754', 1 JSPI at 3759', 3760', 1 JSPF from 3764-3772', 1 JSPI at 3778', 3780', 1 JSPF from 3786-3792', 1 JSPI at 3797', 3798', 3802', 3804' and 3806'. 5. Run tubing w/treating packer set at 3730'. 6. Acidize w/4000 gals 15% chemically retarded NEA in 10 equal stages.		OTHER	
<ol> <li>Pull Tubing.</li> <li>Drill out hydromite &amp; CIBP (8' Hydromite above CIEP at 3780').</li> <li>Run cement retainer and set at 3830'. Squeeze lower perforations w/75 sx. Class 'C' cement containing 1/4 lb./sx. Flocele. Resqueeze if necessary.</li> <li>Perforate w/l JSPF from 3741-3745', 3750-3754', 1 JSPI at 3759', 3760', 1 JSPF from 3764-3772', 1 JSPI at 3778', 3780', 1 JSPF from 3786-3792', 1 JSPI at 3797', 3798', 3802', 3804' and 3806'.</li> <li>Run tubing w/treating packer set at 3730'.</li> <li>Acidize w/4000 gals 15% chemically retarded NEA in 10 equal stages.</li> </ol>	OTHER		
<ol> <li>Drill out hydromite &amp; CIBP (8' Hydromite above CIEP at 3780').</li> <li>Run cement retainer and set at 3830'. Squeeze lower perforations w/75 sx. Class 'C' cement containing 1/4 lb./sx. Flocele. Resqueeze if necessary.</li> <li>Perforate w/l JSPF from 3741-3745', 3750-3754', 1 JSPI at 3759', 3760', 1 JSPF from 3764-3772', 1 JSPI at 3778', 3780', 1 JSPF from 3786-3792', 1 JSPI at 3797', 3798', 3802', 3804' and 3806'.</li> <li>Run tubing w/treating packer set at 3730'.</li> <li>Acidize w/4000 gals 15% chemically retarded NEA in 10 equal stages.</li> </ol>	17. Describe Proposed or Completed ( work) SEE RULE 1103.	Operations (Clearly state all pertinent details, and give pertinent dates, inc	luding estimated date of starting any propose
<ol> <li>Run cement retainer and set at 3830'. Squeeze lower perforations w/75 sx. Class 'C' cement containing 1/4 lb./sx. Flocele. Resqueeze if necessary.</li> <li>Perforate w/1 JSPF from 3741-3745', 3750-3754', 1 JSPI at 3759', 3760', 1 JSPF from 3764-3772', 1 JSPI at 3778', 3780', 1 JSPF from 3786-3792', 1 JSPI at 3797', 3798', 3802', 3804' and 3806'.</li> <li>Run tubing w/treating packer set at 3730'.</li> <li>Acidize w/4000 gals 15% chemically retarded NEA in 10 equal stages.</li> </ol>			
cement containing 1/4 lb./sx. Flocele. Resqueeze if necessary.  4. Perforate w/l JSPF from 3741-3745', 3750-3754', 1 JSPI at 3759', 3760', 1 JSPF from 3764-3772', 1 JSPI at 3778', 3780', 1 JSPF from 3786-3792', 1 JSPI at 3797', 3798', 3802', 3804' and 3806'.  5. Run tubing w/treating packer set at 3730'.  6. Acidize w/4000 gals 15% chemically retarded NEA in 10 equal stages.	2. Drill out hydromi	te & CIBP (8' Hydromite above CIBP at 3780').	
<ol> <li>Perforate w/l JSPF from 3741-3745', 3750-3754', 1 JSPI at 3759', 3760', 1 JSPF from 3764-3772', 1 JSPI at 3778', 3780', 1 JSPF from 3786-3792', 1 JSPI at 3797', 3798', 3802', 3804' and 3806'.</li> <li>Run tubing w/treating packer set at 3730'.</li> <li>Acidize w/4000 gals 15% chemically retarded NEA in 10 equal stages.</li> </ol>	3. Run cement retain	er and set at 3830'. Squeeze lower perforati	ons w/75 sx. Class 'C'
3764-3772', 1 JSPI at 3778', 3780', 1 JSPF from 3786-3792', 1 JSPI at 3797', 3798', 3802', 3804' and 3806'.  5. Run tubing w/treating packer set at 3730'.  6. Acidize w/4000 gals 15% chemically retarded NEA in 10 equal stages.	cement containing		
3802', 3804' and 3806'. 5. Run tubing w/treating packer set at 3730'. 6. Acidize w/4000 gals 15% chemically retarded NEA in 10 equal stages.			
<ol> <li>Run tubing w/treating packer set at 3730'.</li> <li>Acidize w/4000 gals 15% chemically retarded NEA in 10 equal stages.</li> </ol>			JSP1 at 3/9/', 3/98',
6. Acidize w/4000 gals 15% chemically retarded NEA in 10 equal stages.			
			2200
7. Tull packer, full cubing, shab hell, cest, and place on production.			
	7. Tull packer, full	cubing, shab herr, test, and prace on product	.1011
		•	
	18. I hereby certify that the information	n above is true and complete to the best of my knowledge and belief	
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief		Assistant District	
		Suparintandant	19-17-71

DEC 20 1971

APPROVED BY \_

Orig. Signed by Joe D. Ramey Dist. I, Supv.

RECEIVED

17 17 1971

OIL CONSTRUCTION COMM.