

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

Dec 2 3 42 PM '66

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>B-2441</b>
7. Unit Agreement Name
8. Farm or Lease Name <b>H. T. Orcutt (NCT-H) Com</b>
9. Well No. <b>2</b>
10. Field and Pool, or Wildcat <b>Paddock</b>
12. County <b>Lea</b>

### SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>
2. Name of Operator <b>Gulf Oil Corporation</b>
3. Address of Operator <b>Box 670, Hobbs, New Mexico</b>
4. Location of Well UNIT LETTER <b>C</b> , <b>990</b> FEET FROM THE <b>North</b> LINE AND <b>1800</b> FEET FROM THE <b>West</b> LINE, SECTION <b>11</b> TOWNSHIP <b>20-S</b> RANGE <b>37-E</b> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) <b>3608' GL</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

#### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> <b>Plug and abandon</b>

#### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**5736' PB, 6752' TD**

Plans have been made to plug and abandon as follows: Load hole with water. Spot 25 sack cement plug from 4900' to 5000'. Spot 10 sack cement plug from 50' to surface. Install dry hole marker and clean location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

ORIGINAL SIGNATURE

**L. A. TURNER**

SIGNED

TITLE **Area Petroleum Engineer**

DATE **December 2, 1966**

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: