

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRI
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-031736(b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR PAN AMERICAN PETROLEUM CORPORATION	8. FARM OR LEASE NAME GILLULLY B Federal
3. ADDRESS OF OPERATOR BOX 68, HOBBS, N. M. 88240	9. WELL NO. 12
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FSL x 1980' FEL Sec. 22 (Unit J, NW 1/4 SE 1/4)	10. FIELD AND POOL, OR WILDCAT CASS Penn
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3529.5' R.D.B
	12. COUNTY OR PARISH LEA
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

In accordance w/ Form 9-331 dated 7-25-69, acidized perf: 7701-10 w/ 2000 gal 15%. Evaluated. Amp 0-Bo x 190 BW - 24 hours. No further workovers or re-completion possibilities. Propose to plug and abandon as follows:

Cover perf 7701-10 w/ 25 of cement plug.

Sheet & pull 7" @ free point. T OMT - 5600.

Spot 25 of plug in & out of stub.

Sheet & pull 9 5/8" @ free point. T OMT - 1400. If cut below

1210' spot 50 8x @ T ANHY. If above, spot 50 of. In & out of 9 5/8" stub.

Spot 50 5x in & out of 13 3/8" @ SA 318'.

Spot 10 5x @ surface & erect P & A marker.

Make final cleanup and restore ground to contour.

TD- 7712

7" CSA 7712'

9 5/8" CSA 3783'

13 3/8" CSA 318'.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Area Foreman

DATE AUG 19 1969

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

0+ 4- USGS- H
1- NSW
1- SUSP
1- REY

*See Instructions on Reverse Side

AUG 26 1969
RPLS
AUG 26 1969
STRICT ENGINEER