

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

(Other instructions on reverse side)

Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC-045708-B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

CUCAN'S
Ownes Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wantz ABO

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 19, T21S, R38E

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

3. NAME OF OPERATOR
American Exploration Company

4. ADDRESS OF OPERATOR

2100 NCNB Center, Houston, Texas 77002

5. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FSL & 660' FWL of Sec. 19, T21S, R38E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO

TEST WATER SHUT-OFF

FRAC TURE TREAT

SHOOTING OR ACIDIZ

CHANGING

PLUG

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRAC TURE TREATMENT

SHOOTING OR ACIDIZING

CHANGING

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATION: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-

* NOTIFY BLM AT (505)393-3612 PRIOR TO COMMENCING PLUGGING OPERATION.

MIRU WOR. Set CIBP @ $\pm 6600'$. Freepoint 7" csg. Cut & POH w/7". Set 100' cement plug (50' in 7"/50' above 7" in openhole). Set 100' cement plug across base of salt section @ $\pm 2500'$. Set 100' cment plug @ 800-900 across surface csg. shoe. Set 50' cmt. plug @ surface. Cut off csg. 4' below ground. Cap well. Set metal plate on surface.

* USE 9.0 PPG MUD BETWEEN PLUGS.

* USE CLASS 'C' CEMENT MIXED WITH
FRESH WATER WITH SLURRY WEIGHT
OF 14.8 POUNDS PER GALLON.

✓ TAG THE CASING STUB PLUG.

✓ TAG THE SURFACE CASING SHOE PLUG.

18. I hereby certify that the foregoing is true and correct

SIGNED

Marty B. McElanahan

TITLE Sr. Production Analyst

DATE 6/04/90

(This space for Federal or State office use)

APPROVED BY

Orig. Signed by [Signature]

TITLE

DIRECTOR

DATE

8-20-90

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side