

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPlicate
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
American Exploration Company

3. ADDRESS OF OPERATOR
700 Louisiana, Suite 2100, Houston, Texas 77002-2791

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
1980' FNL & 1980' FWL of Sec. 19, T21S, R38E, Lea
Co., New Mexico

14. PERMIT NO. 15. ELEVATIONS (Show whether DE, RT, GR, etc.)

5. LEASE DESIGNATION AND SERIAL NO.
LC-061650-B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Rosa Lee Federal

9. WELL NO.
1

10. FIELD AND POOL, OR WILDCAT
Drinkard *Wantz, abo*

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA
Sec. 19, T21S, R38E

12. COUNTY OR PARISH
Lea

13. STATE
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data


NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	☐	WATER SHUT-OFF	☐
FRACTURE TREAT	☐	FRACTURE TREATMENT	☐
SHOOT OR ACIDIZE	☐	SHOOTING OR ACIDIZING	☐
REPAIR WELL	☐	(Other)	☐
PULL OR ALTER CASING	☐	REPAIRING WELL	☐
MULTIPLE COMPLETE	☐	ALTERING CASING	☐
ABANDON*	☐	ABANDONMENT*	☒
CHANGE PLAN	☐		

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS: (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Set CIBP @ 6600' (50' above top perf @ 6712'). Circ. hole w/9.5#/gal. mud laden fluid. Freepoint 7" csg. *Cut & POH w/same. Spot 50' cmt. plug in & 50' cmt. plug out of 7" csg. stub. Spot 100' cmt. plug across the base of salt @ 2500'. 50' cmt. plug in and 50' cmt. plug out of 10-3/4" surf. shoe @ 850'. 50' cmt. plug at surf. Cut off csg. and place 4' below ground. Cap well. Set metal plate on surface. FINAL REPORT.

CUT 7" CSG @ 900'.



RECEIVED
DEC 18 12 57 PM '90
BUREAU OF LAND MANAGEMENT

18. I hereby certify that the foregoing is true and correct

SIGNED

Marty B. McClanahan

TITLE

Sr. Prod. Analyst

DATE

12/11/90

APPROVED BY

TITLE

DATE

1-14-91

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side