

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

(Other instructions on reverse side)

Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

CC-061650-B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Rosa Lee Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Drinkard

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 19, T21S, R38E

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. WELL ☒ NEW WELL ☐ OTHER

2. NAME OF OPERATOR

American Exploration Company

3. ADDRESS OF OPERATOR

2100 NCNB Center, Houston, Texas 77002

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

1980' FNL & 1980' FWL of Sec. 19, T21S, R38E, Lea Co. New Mexico

14. PERMIT NO.

15. ELEVATION (Show whether RT or etc.)

Check Appropriate box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO

RESEQUENT REPORT OF:

1. STOPPING OR ABANDONING

2. STOPPING OR ABANDONING

3. WATER SHUT-OFF

4. REPAIRING WELL

5. STOPPING OR ABANDONING

6. STOPPING OR ABANDONING

7. FRACTURE TREATMENT

8. ALTERING CASING

9. STOPPING OR ABANDONING

10. STOPPING OR ABANDONING

11. STOPPING OR ABANDONING

12. ABANDONMENT*

13. STOPPING OR ABANDONING

14. STOPPING OR ABANDONING

15. STOPPING OR ABANDONING

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

16. OTHER DATA (Include any other pertinent details, and give pertinent dates, including estimated date of starting any production work. If well is directionally drilled, give direction, location, and measured and true vertical depths for all markers and zones pertinent to the work.)

* NOTIFY BLM AT (505)393-3612 PRIOR TO COMMENCING PLUGGING OPERATION.
MIRU WOR. Set CIBP @ 16600'. Freepoint 7" csg. Cut & POH w/7". Set 100' cmt. plug (50' in 7" / 50' above 7" in openhole). Set 100' cmt. plug across base of salt section @ 12500'. Set 100' cmt. plug @ 800-900' across surface csg. shoe. Set 50' cmt. plug @ surface. Cut off csg. 4' below ground. Cap well. Set metal plate on surface.

* USE A 9.0 PPG MVD BETWEEN PLUGS.

* USE CLASS "C" CEMENT MIXED WITH FRESH WATER WITH A SLURRY WEIGHT OF 14.8 POUNDS PER GALLON.

✓ TAG THE CASING 5' FROM SURFACE.

✓ TAG THE SURFACE CASING 5' TO 6' CENTRAL PLUG IS.

18. I hereby certify that the foregoing is true and correct.

SIGNED

Marty B. McClanahan

Sr. Production Analyst

DATE 6/04/90

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

FILED

DATE

8 24 90

*See Instructions on Reverse Side

I hereby certify that the foregoing is true and correct, and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.