NO. OF CORES RECEIVED			~			
CISTRIBUTION	NEW MEXICO OIL CON		6rm C-101			
SANTA FE				tevined 1-1-55		
FILE				5A. Indicate Ty		
U.S.G.S.				STATE .	FFF X	
LAND OFFICE				5, State OIL & G	in Leane No.	
OPERATOR						
			, i i i i i i i i i i i i i i i i i i i	<u>uuuuu</u>		
APPLICATION F	OR PERMIT TO DRILL, DEEPE	N. OR PLUG BACK				
a. Type of Work				7. Unit Agreeme	nt Nume	
DRILL DRILL	DEEPEN X	PLUG BACK		8. Farm or Lease Marie		
OIL GAS WELL	OTHER	SINGLE MU		H. T. Mat	tern (NCT-B)	
2. Name of Operator		1		9. Well No.		
Gulf 011 Corporation	n			19		
3. Address of Operator					10. Field and Pool, or Willicat	
Box 670, Hobbs, New	Mexico 88240			Blinebry.	-	
	0 LOCATED 510	South		Prenever 1		
UNIT LETTER		FEET FROM THE DOULT	LLINE			
NO 2310 FEET FROM THE	Fact 20	21 0 27			///////////////////////////////////////	
	East LINE OF SEC. 30	TWP. 21-S RGE.37-		12. County	Hilling and the second s	
				-		
<i>+++++++++++++++++++</i> +++++++++++++++++	********	**********	HHHHH	Leann	HHHHHAA	
********	*******	19. Proposed Depth	19A. Formation	20.	Rotory or C.T.	
		6800'	Drinkar	d I	Reverse Unit	
21. Elevations (Show whether DF, RT,	etc.) 21A. Kind & Status Plug. Bond	21B. Drilling Contractor			te Work will start	
3497' GL	Blanket			March 1	1976	
23.		AND CEMENT PROGRAM				

SIZE OF HOLE	SIZE OF CASING	WEIGHT PER FOOT	SETTING DEPTH	SACKS OF CEMENT	EST. TOP
11"	8-5/8"	24#	1207'	400 sacks (Ci	rculated)
7-7/8"	5-1/2"	14#	5761'	645 sacks (TO	C at 2266')
4-3/4"	4"	11.60#	6800'	100 sacks	

Plans have been made to squeeze Blinebry perforations, drill deeper and complete in Drinkard as follows: Pull producing equipment. Squeeze Blinebry perforations 5527' to 5670' with approximately 50 sacks of cement. WOC 18 hours. Test squeezed perforations with  $500^4$ , 30 minutes. Clean out to total depth at 5761' and drill 4-3/4" hole to approximately 6800'. Run 4" OD 11.60# J-55 liner and set on bottom with top at approximately 5690'. WOC 24 hours. Test liner with 1,000#, 30 minutes. Perforate Drinkard zone in 4" liner with 4, 1/2" JHPF in the approximate interval 6480' to 6730'. Run treating equipment and treat new perforations with 2,000 gallons of 15% NE acid. Swab and clean up. Frac new perforations with 16,000 gallons of gel brine and 40,000 gallons containing 1 to 2# SPG. Flush with brine water. Pull treating equipment. Run 4" packer on 2-3/8" tubing and set packer at approximately 5720'. Swab and clean up and place well on production.

hereby certify that the information above is true and complete to the best of my knowledge and belief.				
igned	D. F. Berlin	Area Engineer	Date February 27, 1976	
	(This space for State Use)			

CONDITIONS OF APPROVAL, IF ANY: