
Submit 3 Copies To Appropriate District Office		f New M			Form C-10
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	Energy, Mineral	ls and Na	tural Resources	WELLADI	Revised March 25, 19
<u>District II</u> 1301 W. Grand Avenue, Artesia, NM 88210	OIL CONSER	VATIO	N DIVISION	WELL API 30.025.2	NO. 4418
District III			ancis Dr.	5. Indicate 7	Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV		Fe, NM 8		STAT	
1220 S. St. Francis Dr., Santa Fe, NM 87505				6. State Oil	& Gas Lease No.
SUNDRY NOTIC (DO NOT USE THIS FORM FOR PROPOSA DIFFERENT RESERVOIR. USE "APPLICA	ES AND REPORTS (LS TO DRILL OR TO DE	EDEM OD DI	LIC DACK TO A		ne or Unit Agreement Nar
PROPOSALS.) 1. Type of Well: Oil Well Gas Well	Other	Idvi C-101) I	OK SUCH	W. C. ROA	ACH
2 Name of Operator				8. Well No.	
B.P. AMERICA PRODUCTION CO.			5. Well No.		
3. Address of Operator P. O. 1089 EUNICE N.M. 88231 4. Well Location				9. Pool nam EUNICE N	ie or Wildcat MONUMENT GRBG SA
					-
Unit Letter F : 16	feet from the	NORTH	line and 16	50feet	from the WEST line
Section 21	Township 20	Os Ra	ange 37e	NMPM	County lea
	10. Elevation (Show		R, RKB, RT, GR, etc	c.)	County ICA
11 Check An	3512 gr	dicata M		2	
NOTICE OF INTE	propriate Box to In	dicate in	ature of Notice, I	Report or Other	er Data
	PLUG AND ABANDON	V	REMEDIAL WORK		REPORT OF: ALTERING CASING
TELEPOP					T VELETIMO OVOIMA
LEMPORARILY ARANDON FTT (THANCE DI AMO		001414=110=		
••	CHANGE PLANS		COMMENCE DRIL	LING OPNS.	PLUG AND
PULL OR ALTER CASING N	CHANGE PLANS MULTIPLE COMPLETION		COMMENCE DRILL CASING TEST AN CEMENT JOB	<u> </u>	PLUG AND ABANDONMENT
PULL OR ALTER CASING OTHER:	MULTIPLE COMPLETION		CASING TEST AN CEMENT JOB	D [ABANDONMENT L
OTHER: 12. Describe proposed or completed of starting any proposed work). S	MULTIPLE COMPLETION d operations. (Clearly	state all p	CASING TEST AN CEMENT JOB OTHER:	D _	ABANDONMENT lates, including estimated dom of proposed completion
OTHER: 12. Describe proposed or completed of starting any proposed work). Sor recompilation.	MULTIPLE COMPLETION I operations. (Clearly EE RULE 1103. For I	state all p	CASING TEST AN CEMENT JOB OTHER:	D _	ABANDONMENT lates, including estimated day m of proposed completion
OTHER: 12. Describe proposed or completed of starting any proposed work). Sor recompilation. TD: 3808 PBD:3798 PERF	MULTIPLE COMPLETION I operations. (Clearly EE RULE 1103. For 1 S: 3266-3593	Mulupie C	CASING TEST AN CEMENT JOB OTHER:	D _	ABANDONMENT lates, including estimated day m of proposed completion
PULL OR ALTER CASING OTHER: 12. Describe proposed or completed of starting any proposed work). Sor recompilation. TD: 3808 PBD:3798 PERF	MULTIPLE COMPLETION doperations. (Clearly EE RULE 1103. For 1 S: 3266-3593 DH W/ PRODUCTION	Mulupie C	CASING TEST AN CEMENT JOB OTHER:	D _	ABANDONMENT lates, including estimated dom of proposed completion
PULL OR ALTER CASING OTHER: 12. Describe proposed or completed of starting any proposed work). Sor recompilation. TD: 3808 PBD:3798 PERF MIRUPU. NDWH, NUBOP PORIH W/ WIRELINE SET CIBP SPOT 35' CMT PLUG ON TO	MULTIPLE COMPLETION doperations. (Clearly EE RULE 1103. For I S: 3266-3593 DH W/ PRODUCTION 9 3216' P OF CIBP	Mulupie C	CASING TEST AN CEMENT JOB OTHER:	D _	ABANDONMENT lates, including estimated dim of proposed completion
PULL OR ALTER CASING OTHER: 12. Describe proposed or completes of starting any proposed work). S or recompilation. TD: 3808 PBD:3798 PERF MIRUPU. NDWH, NUBOP PORIH W/ WIRELINE SET CIBP SPOT 35' CMT PLUG ON TO DISPLACE HOLE W/ 9.5 LB N	MULTIPLE COMPLETION d operations. (Clearly EE RULE 1103. For I S: 3266-3593 DH W/ PRODUCTION @ 3216' P OF CIBP MUD	Multiple C	CASING TEST AN CEMENT JOB OTHER: pertinent details, and ompletions: Attach	D _	ABANDONMENT lates, including estimated dim of proposed completion
PULL OR ALTER CASING OTHER: 12. Describe proposed or completed of starting any proposed work). Sor recompilation. TD: 3808 PBD:3798 PERF MIRUPU. NDWH, NUBOP PORIH W/ WIRELINE SET CIBP SPOT 35' CMT PLUG ON TODISPLACE HOLE W/ 9.5 LB IPU AND SPOT 25 SX CMT P	MULTIPLE COMPLETION d operations. (Clearly EE RULE 1103. For 1 S: 3266-3593 DH W/ PRODUCTION @ 3216' P OF CIBP MUD LUG @ 1250' - 1356	N TBG.	CASING TEST AN CEMENT JOB OTHER: ertinent details, and ompletions: Attach	give pertinent d	ABANDONMENT lates, including estimated dim of proposed completion
PULL OR ALTER CASING OTHER: 12. Describe proposed or completed of starting any proposed work). Sor recompilation. TD: 3808 PBD:3798 PERF MIRUPU. NDWH, NUBOP PORIH W/ WIRELINE SET CIBP SPOT 35' CMT PLUG ON TODISPLACE HOLE W/ 9.5 LB PU AND SPOT 25 SX CMT PPOH PERF @ 50' BELOW TO	MULTIPLE COMPLETION doperations. (Clearly EE RULE 1103. For 1 S: 3266-3593 OH W/ PRODUCTION @ 3216' P OF CIBP MUD LUG @ 1250' - 1350 OP OF SHOE @ 425	N TBG.	CASING TEST AN CEMENT JOB OTHER: ertinent details, and ompletions: Attach	give pertinent d	ABANDONMENT ABANDONMENT Lates, including estimated d
OTHER: 12. Describe proposed or completed of starting any proposed work). Sor recompilation. TD: 3808 PBD:3798 PERF MIRUPU. NDWH, NUBOP PORIH W/ WIRELINE SET CIBP SPOT 35' CMT PLUG ON TODISPLACE HOLE W/ 9.5 LB IPU AND SPOT 25 SX CMT PPOH PERF @ 50' BELOW TORIH W/ TBG PUMP CMT 50' CPOH W/ TBG NDWH SPOT 1	MULTIPLE COMPLETION I operations. (Clearly EE RULE 1103. For I S: 3266-3593 OH W/ PRODUCTION @ 3216' P OF CIBP MUD LUG @ 1250' - 1350 OP OF SHOE @ 425 OUT AND 50' IN (50) 0 SX CMT. OR 60' T	N TBG. O' (TOP O' SX) TO SUE.	CASING TEST AN CEMENT JOB OTHER: Pertinent details, and completions: Attach	give pertinent d wellbore diagra	ABANDONMENT Lates, including estimated dom of proposed completion
OTHER: 12. Describe proposed or completed of starting any proposed work). Sor recompilation. TD: 3808 PBD:3798 PERF MIRUPU. NDWH, NUBOP PC RIH W/ WIRELINE SET CIBP SPOT 35' CMT PLUG ON TO DISPLACE HOLE W/ 9.5 LB IP PU AND SPOT 25 SX CMT PP POH PERF @ 50' BELOW TO RIH W/ TBG PUMP CMT 50' CPOH W/ TBG NDWH SPOT 1 CUT OFF WELLHEAD AND II	MULTIPLE COMPLETION I operations. (Clearly EE RULE 1103. For I S: 3266-3593 OH W/ PRODUCTION @ 3216' P OF CIBP MUD LUG @ 1250' - 1350 OP OF SHOE @ 425 OUT AND 50' IN (50) 0 SX CMT. OR 60' T	N TBG. O' (TOP O' SX) TO SUE.	CASING TEST AN CEMENT JOB OTHER: Pertinent details, and completions: Attach F SALT) TAG	give pertinent divellbore diagram	ABANDONMENT Lates, including estimated d m of proposed completion 10117273787878
PULL OR ALTER CASING OTHER: 12. Describe proposed or completed of starting any proposed work). Sor recompilation. TD: 3808 PBD:3798 PERF MIRUPU. NDWH, NUBOP PORITH W/ WIRELINE SET CIBP SPOT 35' CMT PLUG ON TODISPLACE HOLE W/ 9.5 LB IPU AND SPOT 25 SX CMT PPOH PERF @ 50' BELOW TORITH W/ TBG PUMP CMT 50' CMT POMP CMT 50' CMT PUMP CMT 50' CMT POMP CMT POMP CMT 50' CMT POMP C	MULTIPLE COMPLETION I operations. (Clearly EE RULE 1103. For I S: 3266-3593 OH W/ PRODUCTION @ 3216' P OF CIBP MUD LUG @ 1250' - 1350 OP OF SHOE @ 425 OUT AND 50' IN (50) 0 SX CMT. OR 60' T	N TBG. O' (TOP O' SX) TO SUE.	CASING TEST AN CEMENT JOB OTHER: Pertinent details, and ompletions: Attach F SALT) TAG ATHE COMMISSION HOURS PRIOR	give pertinent d wellbore diagra	ABANDONMENT Lates, including estimated d m of proposed completion 10111213223
OTHER: 12. Describe proposed or completed of starting any proposed work). Sor recompilation. TD: 3808 PBD:3798 PERF MIRUPU. NDWH, NUBOP PC RIH W/ WIRELINE SET CIBP SPOT 35' CMT PLUG ON TO DISPLACE HOLE W/ 9.5 LB IP PU AND SPOT 25 SX CMT PP POH PERF @ 50' BELOW TO RIH W/ TBG PUMP CMT 50' CPOH W/ TBG NDWH SPOT 1 CUT OFF WELLHEAD AND II	MULTIPLE COMPLETION I operations. (Clearly EE RULE 1103. For I S: 3266-3593 OH W/ PRODUCTION @ 3216' P OF CIBP MUD LUG @ 1250' - 1350 OP OF SHOE @ 425 OUT AND 50' IN (50) 0 SX CMT. OR 60' T	N TBG. O' (TOP O' SX) TO SUE.	CASING TEST AN CEMENT JOB OTHER: Pertinent details, and ompletions: Attach F SALT) TAG ATHE COMMISSION HOURS PRIOR PLUGGING OFF	give pertinent divellbore diagrament of the Begin RATIONS FOR	ABANDONMENT Lates, including estimated dim of proposed completion 1011727372737
OTHER: 12. Describe proposed or completed of starting any proposed work). Sor recompilation. TD: 3808 PBD:3798 PERF MIRUPU. NDWH, NUBOP PORITH W/ WIRELINE SET CIBP SPOT 35' CMT PLUG ON TODISPLACE HOLE W/ 9.5 LB IPU AND SPOT 25 SX CMT PPOH PERF @ 50' BELOW TORITH W/ TBG PUMP CMT 50' CPOH W/ TBG NDWH SPOT 10 CUT OFF WELLHEAD AND IRRDPU. P&A WELL BORE	MULTIPLE COMPLETION doperations. (Clearly EE RULE 1103. For 1 S: 3266-3593 OH W/ PRODUCTION @ 3216' P OF CIBP MUD LUG @ 1250' - 1350 OP OF SHOE @ 425 OUT AND 50' IN (50 0 SX CMT, OR 60' T NSTALL DRY HOLE	N TBG. O' (TOP O SX) O SUF. MARKER	CASING TEST AN CEMENT JOB OTHER: Pertinent details, and ompletions: Attach TAG ATHE COMMISSION HOURS PRIOR PLUGGING OPE TO BE APPROVE	give pertinent divellbore diagrammellos BEGIRATIONS FOR D.	ABANDONMENT Lates, including estimated day of proposed completion 10117273787878787878787878787878787878787878
OTHER: 12. Describe proposed or completed of starting any proposed work). Sor recompilation. TD: 3808 PBD:3798 PERF MIRUPU. NDWH, NUBOP PC RIH W/ WIRELINE SET CIBP SPOT 35' CMT PLUG ON TO DISPLACE HOLE W/ 9.5 LB IP PU AND SPOT 25 SX CMT P POH PERF @ 50' BELOW TO RIH W/ TBG PUMP CMT 50' CPOH W/ TBG NDWH SPOT 1 CUT OFF WELLHEAD AND IF RDPU. P&A WELL BORE	MULTIPLE COMPLETION doperations. (Clearly EE RULE 1103. For 1 S: 3266-3593 OH W/ PRODUCTION @ 3216' P OF CIBP MUD LUG @ 1250' - 1350 OP OF SHOE @ 425 OUT AND 50' IN (50 0 SX CMT, OR 60' T NSTALL DRY HOLE	N TBG. O' (TOP O SX) O SUF. MARKER	CASING TEST AN CEMENT JOB OTHER: Pertinent details, and ompletions: Attach TAG ATHE COMMISSION HOURS PRIOR PLUGGING OPE TO BE APPROVE	give pertinent divellbore diagrammellos BEGIRATIONS FOR D.	ABANDONMENT Lates, including estimated day m of proposed completion 10117273787878787878787878787878787878787878
OTHER: 12. Describe proposed or completed of starting any proposed work). Sor recompilation. TD: 3808 PBD:3798 PERF MIRUPU. NDWH, NUBOP PORITH W/ WIRELINE SET CIBP SPOT 35' CMT PLUG ON TODISPLACE HOLE W/ 9.5 LB IPU AND SPOT 25 SX CMT PPOH PERF @ 50' BELOW TORITH W/ TBG PUMP CMT 50' CPOH W/ TBG NDWH SPOT 10 CUT OFF WELLHEAD AND IRRDPU. P&A WELL BORE	MULTIPLE COMPLETION doperations. (Clearly EE RULE 1103. For I S: 3266-3593 OH W/ PRODUCTION @ 3216' P OF CIBP MUD LUG @ 1250' - 1350 OP OF SHOE @ 425 OUT AND 50' IN (50 0 SX CMT, OR 60' T NSTALL DRY HOLE ove is true and complete	N TBG. O' (TOP O' SX) O SUF. MARKER	CASING TEST AN CEMENT JOB OTHER: Pertinent details, and ompletions: Attach TAG ATHE COMMISSION HOURS PRIOR PLUGGING OPE TO BE APPROVE	give pertinent divellbore diagrament of the BEGI RATIONS FOR D.	ABANDONMENT Lates, including estimated day m of proposed completion 10117273787878787878787878787878787878787878
OTHER: 12. Describe proposed or completed of starting any proposed work). Sor recompilation. TD: 3808 PBD:3798 PERF MIRUPU. NDWH, NUBOP PORIH W/ WIRELINE SET CIBP SPOT 35' CMT PLUG ON TODISPLACE HOLE W/ 9.5 LB MPU AND SPOT 25 SX CMT PPOH PERF @ 50' BELOW TORIH W/ TBG PUMP CMT 50' CPOH W/ TBG NDWH SPOT 10 CUT OFF WELLHEAD AND MRDPU. P&A WELL BORE	MULTIPLE COMPLETION doperations. (Clearly EE RULE 1103. For I S: 3266-3593 OH W/ PRODUCTION @ 3216' P OF CIBP MUD LUG @ 1250' - 1350 OP OF SHOE @ 425 OUT AND 50' IN (50 0 SX CMT, OR 60' T NSTALL DRY HOLE ove is true and complete	N TBG. O' (TOP O' SX) O SUF. MARKER	CASING TEST AN CEMENT JOB OTHER: Pertinent details, and ompletions: Attach F SALT) TAG ATHE COMMISS CHOURS PRIOR PLUGGING OFF TO BE APPROVE st of my knowledge	SHOE SOLUTIONS FOR D.	ABANDONMENT Lates, including estimated day m of proposed completion 9 101172 73 78 78 78 78 78 78 78 78 78 78 78 78 78
OTHER: 12. Describe proposed or completed of starting any proposed work). Sor recompilation. TD: 3808 PBD:3798 PERF MIRUPU. NDWH, NUBOP PORIH W/ WIRELINE SET CIBP SPOT 35' CMT PLUG ON TODISPLACE HOLE W/ 9.5 LB NPU AND SPOT 25 SX CMT PPOH PERF @ 50' BELOW TORIH W/ TBG PUMP CMT 50' CPOH W/ TBG NDWH SPOT 11 CUT OFF WELLHEAD AND IN RDPU. P&A WELL BORE	MULTIPLE COMPLETION d operations. (Clearly EE RULE 1103. For I S: 3266-3593 OH W/ PRODUCTION @ 3216' P OF CIBP MUD LUG @ 1250' - 1350 OP OF SHOE @ 425 OUT AND 50' IN (50 0 SX CMT, OR 60' T NSTALL DRY HOLE eve is true and complet	N TBG. O' (TOP O') SX) TO SUF. MARKER	CASING TEST AN CEMENT JOB OTHER: Pertinent details, and completions: Attach F SALT) TAG ATHE COMMISS OF PLUGGING OFF TO BE APPROVE st of my knowledge perations supervi	give pertinent de wellbore diagrament de wellbore diagrament de la company de la compa	ABANDONMENT Lates, including estimated day of proposed completion 9 1011727378786 EVERTED 24 NAME OF THE C-103 DATE 11/4/02 Sphone No. (505) 677-3642
OTHER: 12. Describe proposed or completed of starting any proposed work). Sor recompilation. TD: 3808 PBD:3798 PERF MIRUPU. NDWH, NUBOP PORIH W/ WIRELINE SET CIBP SPOT 35' CMT PLUG ON TODISPLACE HOLE W/ 9.5 LB MPU AND SPOT 25 SX CMT PPOH PERF @ 50' BELOW TORIH W/ TBG PUMP CMT 50' CPOH W/ TBG NDWH SPOT 10 CUT OFF WELLHEAD AND MRDPU. P&A WELL BORE I hereby certify that the information about the second s	MULTIPLE COMPLETION d operations. (Clearly EE RULE 1103. For I S: 3266-3593 OH W/ PRODUCTION @ 3216' P OF CIBP MUD LUG @ 1250' - 1350 OP OF SHOE @ 425 OUT AND 50' IN (50 0 SX CMT, OR 60' T NSTALL DRY HOLE eve is true and complet	N TBG. O' (TOP O') SX) TO SUF. MARKER	CASING TEST AN CEMENT JOB OTHER: Pertinent details, and ompletions: Attach F SALT) TAG ATHE COMMISS CHOURS PRIOR PLUGGING OFF TO BE APPROVE st of my knowledge	give pertinent de wellbore diagrament de wellbore diagrament de la company de la compa	ABANDONMENT Lates, including estimated dom of proposed completion 10117273747676 THE C-103 DATE 11/4/02 The phone No. (505) 677-3642

WELLBORE SCHEMATIC

10 SX CMT 60' TO SURF.



W. C. ROACH #5

1650' FNL &1650' FWL Sec 21, T-20S, R37E, lea County, nm 3512 gr

8-5/8" casing @ 425' Cmt Circulated to surface

PERF 50' BELOW SHOE 50' OUT AND 50' IN (50 SX)

25 SX CMT AT TOP OF SALT 1250' TO 1350'

TOC @ 1510' by TS

35' CMT PLUG

CIBP @ 3216'

Perfs @ 3266' to 3593'

4-1/2" csg @ 3808'

TD @ 3808".

PBD @ 3798"